

1 BLOOD HURST & O'REARDON, LLP  
TIMOTHY G. BLOOD (149343)  
2 PAULA R. BROWN (254142)  
JENNIFER L. MACPHERSON (202021)  
3 CRAIG W. STRAUB (249032)  
501 West Broadway, Suite 1490  
4 San Diego, CA 92101  
Tel: 619/338-1100  
5 619/338-1101 (fax)  
tblood@bholaw.com  
6 pbrown@bholaw.com  
cstraub@bholaw.com  
7 jmacpherson@bholaw.com

MONTELEONE & McCRORY LLP  
JEFFREY S. HURST (138664)  
725 S. Figueroa Street, #3200  
Los Angeles, CA 90017-5446  
Tel: 213/612-9900  
212/612-9930 (fax)  
hurst@mmlawyers.com

8 BEASLEY, ALLEN, CROW,  
METHVIN, PORTIS & MILES, P.C.  
9 W. DANIEL "DEE" MILES, III\*  
H. CLAY BARNETT, III\*  
10 J. MITCH WILLIAMS\*  
272 Commerce Street  
11 Montgomery, AL 36104  
Tel: 334/269-2343  
12 334/954-7555 (fax)  
Dee.Miles@Beasleyallen.com  
13 Clay.Barnett@BeasleyAllen.com  
Mitch.Williams@Beasleyallen.com

14 Attorneys for Plaintiffs

15 **UNITED STATES DISTRICT COURT**  
16 **CENTRAL DISTRICT OF CALIFORNIA**

17 TOWNSEND VANCE and  
18 ZACHARY HAINES, individually  
and on behalf of all others similarly  
19 situated,

20 Plaintiffs,

21 v.

22 MAZDA MOTOR OF AMERICA,  
INC. D/B/A MAZDA NORTH  
23 AMERICAN OPERATIONS,  
MAZDA MOTOR CORPORATION,  
24 FCA US LLC. DENSO  
CORPORATION, and DENSO  
25 INTERNATIONAL AMERICA,  
INC,

26 Defendants.  
27  
28

Case No. 8:21-cv-01890-CJC-KES

**CLASS ACTION**

**PLAINTIFFS' FIRST AMENDED  
CLASS ACTION COMPLAINT**

District Judge Cormac J. Carney  
Courtroom 9B, Santa Ana  
Magistrate Judge Karen E. Scott  
Courtroom 6D, Santa Ana

Complaint Filed: November 16, 2021  
Trial Date: Not Set

**JURY TRIAL DEMANDED**

1 Plaintiffs Townsend Vance and Zachary Haines (collectively, “Plaintiffs”)  
2 file this Consolidated Amended Class Action Complaint, on behalf of themselves  
3 and all others similarly situated against defendants Mazda Motor of America, Inc.  
4 and Mazda Motor Corporation (collectively, “Mazda”), FCA US LLC (“FCA”),  
5 Denso Corporation and Denso International America, Inc. (collectively,  
6 “Denso”).<sup>1</sup> Based on personal knowledge as to matters relating to themselves, and  
7 on information and belief based on the investigation of counsel, including  
8 counsels’ review of consumer complaints available on the database of the National  
9 Highway Traffic Safety Administration (“NHTSA”) and other publicly available  
10 information, as to all other matters, Plaintiffs allege as follows:

11 **I. NATURE OF THE ACTION**

12 1. This class action lawsuit seeks redress for the misconduct of Denso,  
13 a \$47.6 billion global company that claims to be a leading supplier of advanced  
14 automotive technology, systems and components, and Mazda, an international  
15 manufacturer of automobiles that claims to manufacture and sell high-quality, safe  
16 vehicles, that knowingly exposed the purchasers and lessees of at least hundreds  
17 of thousands of Mazda vehicles, such as Plaintiffs and members of the proposed  
18 classes (“Class Members”), to a dangerous defect lurking in their vehicles’ fuel  
19 pump. This defect causes Mazda vehicles to stall, their engines to shut down or  
20 fail to start, and creates a substantial risk of injury and death for any person  
21 operating or riding in a vehicle equipped with the defective fuel pump. Despite  
22 being aware of this problem for years, Mazda and Denso failed to disclose it to  
23 Plaintiffs until November 12, 2021, when Mazda announced a recall (Denso issued  
24 a general recall of its fuel pumps in April 2020).

25 2. Denso is one of the largest suppliers of original equipment fuel pumps  
26 to vehicle manufacturers, including to Mazda. According to Denso, its fuel “pumps  
27

28 <sup>1</sup> Mazda, FCA, and Denso are collectively referenced as “Defendants.”

1 are chosen as standard equipment by the world’s most demanding OEMs,  
2 especially for their premium vehicles.”

3 3. On April 27, 2020, Denso issued a recall for defective low-pressure  
4 fuel pumps it manufactured between September 1, 2017 and October 6, 2018. The  
5 number of potentially affected vehicles across manufacturers is 2,020,000.

6 4. The fuel pump in an automobile is critically important to the overall  
7 operation of a vehicle because it lifts gasoline from the fuel tank and delivers it to  
8 the engine where it is ignited in the combustion chamber and generates vehicle  
9 propulsion. A fuel pump is expected to last for the life of an automobile or a  
10 minimum of 200,000 miles.

11 5. In its Part 573 Safety Recall Report (“Denso’s April 27, 2020 Recall  
12 Report”)<sup>2</sup> filed with NHTSA, Denso admitted its low-pressure fuel pumps contain  
13 a defective impeller that poses a risk to consumer safety:

14 An impeller in some low pressure fuel pumps may become deformed  
15 under certain conditions which could render the fuel pump  
16 inoperable.... If an impeller deforms to a point that creates sufficient  
17 interference with the fuel pump body, the fuel pump becomes  
18 inoperative. According to vehicle manufacturer’s system evaluation,  
19 an inoperative fuel pump may result in the illumination of the check  
20 engine light and/or master warning indicators, rough engine running,  
21 engine no start and/or vehicle stall while driving at low speed and, in  
22 rare instances, a vehicle stall could occur while driving at higher  
23 speeds, increasing the risk of a crash.

24 6. Specifically, Denso stated its low-pressure fuel pumps could become  
25 inoperable if “an impeller is manufactured with a lower density, and contains a  
26 lower surface strength or is exposed to production solvent drying for a longer  
27 period of time, higher levels of surface cracking may occur which, when excessive  
28 fuel absorption occurs, may result in impeller deformation.”<sup>3</sup> (“Fuel Pump  
Defect”).

<sup>2</sup> Denso’s April 27, 2020 Recall Report is attached hereto as Exhibit A.

<sup>3</sup> *Id.*

1           7.     On June 11, 2020, Denso expanded its recall by submitting a second  
2 Part 573 Safety Recall Report to NHTSA (“Denso’s June 11, 2020 Recall  
3 Report”),<sup>4</sup> increasing the number of affected fuel pumps from 2,020,000 to  
4 2,156,057.<sup>5</sup>

5           8.     The Denso Recall Reports listed various manufactures that  
6 “purchased this defective/noncompliant equipment,” one of which is Mazda.<sup>6</sup>

7           9.     Despite admitting responsibility for the Fuel Pump Defect, and that  
8 the Defect poses a risk to consumer safety, Denso failed to take any corrective  
9 action itself and said “[t]he remedy program, if any, will be determined by vehicle  
10 manufacturers.”<sup>7</sup>

11          10.    On November 17, 2020, nearly seven months after Denso’s initial  
12 recall, Denso again expanded its recall, nearly doubling the months of production  
13 and, with that, the number of admittedly defective low–pressure fuel pumps with  
14 the Fuel Pump Defect. In this expansion, fuel pumps manufactured as early as June  
15 26, 2017, and as late as June 28, 2019, were now included in the recall, and  
16 1,517,721 additional pumps were admitted to be defective.<sup>8</sup>

17          11.    In its November 17, 2020 Recall Report, Denso also set forth the  
18 results of additional analysis it conducted concerning the Fuel Pump Defect,  
19 concluding that the density of the resin in the impeller material “was found to more  
20 closely correlate with the occurrence of field cases” and that “a lower minimum  
21 surface strength [of impellers] than previously estimated could be possible”:

22               Additional analysis was conducted regarding the density of impellers  
23 manufactured during various periods. Because the impeller material  
24 contains three elements (resin, glass fiber, and calcium carbonate),

25           <sup>4</sup> Denso’s June 11, 2020 Recall Report is attached hereto as Exhibit B.

26           <sup>5</sup> Denso’s April 27, 2020 Recall Report and June 11, 2020 Recall Report are  
collectively referenced as the “Denso Recalls.”

27           <sup>6</sup> See Exhibit A at 3.

28           <sup>7</sup> *Id.* at 2.

<sup>8</sup> Denso’s November 17, 2020 Recall Report is attached hereto as Exhibit C.

1 but only one element (resin) is susceptible to swelling, only resin  
2 density was examined for this analysis. Resin density was found to  
3 more closely correlate with the occurrence of field cases than overall  
4 impeller density. The resin density findings indicated additional  
5 material lots which could contribute to the occurrence of the  
6 condition in combination with other factors. In addition, the surface  
7 strength of impellers manufactured during various periods was  
8 examined with additional variables considered. This analysis  
9 demonstrated that a lower minimum surface strength than previously  
10 estimated could be possible. The new resin density and surface  
11 strength information can be correlated by vehicle manufacturers with  
12 warranty data, production timing data, vehicle specific variables, and  
13 other information to determine which vehicles, if any, may be  
14 susceptible to the condition.<sup>9</sup>

11 12. On July 17, 2020, Mazda filed a Part 579.12 Foreign Recall  
12 Campaign Report with NHTSA, alerting NHTSA of recalls in China, Japan,  
13 Thailand, Malaysia, Vietnam, and Mexico for vehicles equipped with Denso's  
14 Fuel Pumps that suffer from the Fuel Pump Defect ("Mazda's Foreign Recall").<sup>10</sup>

15 13. Mazda's Foreign Recall states that "fuel pump impellers located  
16 inside the fuel delivery module (FDM) may experience surface cracks due to low  
17 part density during the manufacturing process and/or length of time between pump  
18 production and vehicle installation. As a result, the impeller may deform, causing  
19 interference with surrounding pump components."<sup>11</sup>

20 14. Mazda's Foreign Recall also identified "Substantially Similar  
21 Vehicles in the U.S.": 2018-2020 Mazda CX-3, CX-5, CX-9, Mazda2, Mazda3,  
22 Mazda6, MX-5, and Toyota Yaris vehicles.<sup>12</sup>

---

26 <sup>9</sup> *Id.*

27 <sup>10</sup> *See* Exhibit D.

28 <sup>11</sup> *Id.*

<sup>12</sup> *Id.*

1           15. Despite using the same Fuel Pump, Mazda failed to recall the Class  
2 Vehicles “due to differences in U.S. logistic conditions, typical customer usage  
3 and other factors.”<sup>13</sup>

4           16. On November 12, 2021, over one year after the initial Denso Recall  
5 and Mazda’s Foreign Recall, Mazda finally issued its own U.S. recall of its  
6 vehicles equipped with the defective low-pressure Denso fuel pumps. Mazda filed  
7 its own Part 573 Safety Recall Report (“Mazda’s Recall Report”)<sup>14</sup> with NHTSA  
8 confirming that at least 121,038 of its vehicles are equipped with the defective  
9 Denso fuel pumps. Mazda’s Recall covers Mazda’s 2019 CX-3, 2018-2019 CX-5,  
10 2018-2019 CX-9, 2019-2020 Mazda2, 2018 Mazda3, 2018 Mazda6, and 2018-  
11 2019 MX-5 vehicles manufactured at various times between April 2018 and  
12 January 2020 (“Mazda’s 2020 Recalled Vehicles”).

13           17. Mazda’s Recall Report confirms the existence and seriousness of the  
14 Fuel Pump Defect: “The impeller in some low pressure fuel pumps may become  
15 deformed under certain conditions, which could cause fuel pump failure. . . . Fuel  
16 pump failure may result in engine no start and/or vehicle stall while driving at low  
17 speed and, in rare instances, a vehicle stall could occur while driving at higher  
18 speeds, increasing the risk of a crash.”<sup>15</sup>

19           18. Mazda claims to have accurately identified the total population of  
20 vehicles equipped with the defective fuel pumps.

21           19. Mazda and FCA are engaged in a joint venture for the production of  
22 the Fiat 124 Spider. Mazda and FCA jointly designed and manufactured the Fiat  
23 124 Spider vehicles using the Mazda MX-5 platform.

24  
25  
26

---

27           <sup>13</sup> *Id.*  
28           <sup>14</sup> Mazda’s November 12, 2021 Recall Report is attached hereto as Exhibit E.  
              <sup>15</sup> *Id.*

1           20. On November 12, 2021, FCA issued a recall for the 2019 Fiat 124  
2 Spider vehicles because they are equipped with Denso’s defective low-pressure  
3 fuel pumps (“FCA’s Recall”).<sup>16</sup>

4           21. FCA’s Recall acknowledged the seriousness of the Fuel Pump Defect:

5           A FDM with a deformed impeller may interfere with other fuel pump  
6 components which can inhibit the operation of the fuel pump  
7 potentially causing fuel starvation. . . . Fuel starvation may result in  
8 an unexpected loss of motive power, which can cause vehicle crash  
without prior warning.

9           22. Mazda’s Recall fails to include other 2013-2020 Mazda  
10 manufactured vehicles equipped with the same defective Denso made low-  
11 pressure fuel pump with a part number suffix 13350 as those in the Mazda Recall,  
12 and FCA’s Recall fails to include other FCA/Mazda vehicles equipped with the  
13 same defective low-pressure fuel pump with a part number 68313125AA as those  
14 in the FCA Recall (“Class Vehicles”).

15           23. While Mazda’s and FCA’s Recalls include only certain model year  
16 2018-2020 vehicles that suffer from the Fuel Pump Defect, a recall by another  
17 manufacturer over the same Fuel Pump Defect covers model year 2013-2019  
18 vehicles equipped with Denso’s same defective fuel pumps. Moreover, Mazda  
19 customers have been submitting Fuel Pump Defect complaints to NHTSA since  
20 2013.

21           24. Mazda (and therefore, FCA) admits it knew about the Fuel Pump  
22 Defect as early as March 2019.<sup>17</sup> Nevertheless, Mazda, and FCA failed to make  
23 public the existence of the Fuel Pump Defect until November 12, 2021, over two  
24 years later. Moreover, Mazda and FCA failed to notify consumers directly or  
25 instruct them to stop driving their dangerous vehicles until they are repaired. Nor  
26 did Mazda or FCA offer a timely remedy.

27 \_\_\_\_\_  
28 <sup>16</sup> Exhibit G.

<sup>17</sup> Exhibit F.

1           25. Despite admitting in its recall that the Fuel Pump Defect could occur  
2 while driving, “increasing the risk of a crash,” egregiously, Mazda and FCA did  
3 not direct the owners and lessees of the Recalled Vehicles to immediately cease  
4 driving their cars. Mazda and FCA also did not offer owners and lessees loaner  
5 cars they could drive until an adequate remedy could be implemented.

6           26. Moreover, though Mazda and FCA have not made public their repair  
7 instructions to dealerships, Mazda’s and FCA’s Recalls are identical to those of  
8 three other manufacturers (Toyota, Honda, and Subaru) and each have  
9 implemented the same repair provided by Denso. But Mazda’s and FCA’s Recall  
10 repairs are inadequate on multiple levels.

11           27. Rather than following the industry standard and replacing the entire  
12 fuel pump module, Mazda’s and FCA’s Recalls direct technicians to replace only  
13 the fuel pump *motor*, which is part of the module. This is an extremely delicate  
14 and difficult procedure with a high risk of damaging the entire fuel pump module,  
15 which can result in gas leaking out of the fuel tank, creating hazardous conditions  
16 and exacerbating the Fuel Pump Defect instead of correcting it. As set forth below  
17 in Section IV, there are numerous reports from individuals who received the same  
18 repair from Toyota, Honda, and Subaru that detail the dangerous consequences of  
19 the recall repair.

20           28. Thus, Mazda’s and FCA’s Recalls failed to adequately repair the Fuel  
21 Pump Defect, and often cause additional damage to the fuel pump module and the  
22 Vehicle.

23           29. As a result, at least hundreds of thousands of Mazda’s and FCA’s  
24 customers in the United States are driving vehicles that pose a serious safety risk.

25           30. The Fuel Pump Defect in the Class Vehicles exposes occupants and  
26 others to extreme danger, even death. A vehicle that stalls or suffers engine  
27 shutdown is at heightened risk for collision. A vehicle that stalls or suffers engine  
28 shutdown causes drivers to react to remove themselves from danger, typically by



1 exiting the road. Drivers stranded on the side of the road experience a heightened  
2 risk of danger, whether it is from other vehicles, remoteness or weather elements.

3 31. Fuel pump failure can also prevent the driver from accelerating at the  
4 necessary and anticipated pace. Diminished acceleration ability creates  
5 unexpected hazards, startling drivers of the Class Vehicles and other drivers in  
6 their proximity. Finally, once a Class Vehicle fuel pump fails, the vehicle becomes  
7 totally inoperable and will not start.

8 32. Despite Mazda's and FCA's indisputable knowledge of the danger  
9 posed by defective fuel pumps in its vehicles, Mazda's and FCA's Recalls are  
10 woefully inadequate because they: (1) failed to identify and include the full scope  
11 of Mazda and FCA manufactured vehicles equipped with defective fuel pumps;  
12 (2) failed to offer a timely or effective repair; (3) failed to warn consumers about  
13 the serious safety hazards posed by the Fuel Pump Defect and recommend  
14 customers stop driving their vehicles until they are repaired; and (4) failed to offer  
15 free loaner vehicles until Plaintiffs' and Class Members' vehicles are repaired.

16 33. As in Section IV, throughout the relevant period, Mazda's and FCA's  
17 marketing of the Class Vehicles was and is replete with assurances about their  
18 safety and dependability. A vehicle that can suddenly stall and lose power during  
19 normal operating conditions is inherently unsafe and not dependable, and renders  
20 Mazda's and FCA's marketing of the Class Vehicles untrue and materially  
21 misleading. Plaintiffs and other Class Members have been damaged as a result.

22 34. Despite marketing and selling the Class Vehicles as safe and  
23 dependable, as alleged above, Mazda and FCA have long known of the Fuel Pump  
24 Defect. Mazda and FCA amassed years of research, data gathering, and  
25 hundreds—if not thousands—of Fuel Pump Defect warranty claims. Moreover,  
26 under the TREAD Act, 49 U.S.C. § 30118, Mazda and FCA are duty-bound to,  
27 and does, monitor complaints from consumers that are posted on NHTSA's  
28 website. As set forth in Section IV below, there were consumer complaints on

1 NHTSA’s website about the Fuel Pump Defect in Mazda’s and FCA’s vehicles  
2 that predate Mazda’s and FCA’s 2021 Recalls by over eight years (submitted in  
3 2013).

4 35. Denso is equally culpable because it designed, engineered, tested,  
5 validated, manufactured, and placed into the stream of commerce defective fuel  
6 pumps, which it knew would be installed the Class Vehicles. As described in  
7 Section IV below, Denso indisputably had exclusive knowledge of the Fuel Pump  
8 Defect well before October 2016, when Denso filed a patent application seeking  
9 to improve the durability and absorption qualities of the defective fuel pump  
10 impeller. However, at no time did Denso disclose to others what it knew about the  
11 Fuel Pump Defect nor was that information reasonably available to Plaintiffs and  
12 the public. Denso’s knowing and intentional failure to disclose the Fuel Pump  
13 Defect was a direct and proximate cause of harm to Plaintiffs and Class Members.

14 36. With or without a viable remedy for the Fuel Pump Defect, Mazda’s  
15 Recalls have decreased the intrinsic and resale value of the Class Vehicles.  
16 Plaintiffs and other Class Members have been damaged as a result. Additionally,  
17 Class Members must still honor their lease and loan payments (without proration),  
18 even while their vehicles are inoperable and devalued.

19 37. Plaintiffs bring this lawsuit on behalf of themselves and all others  
20 similarly situated who own or lease a Class Vehicle equipped with a defective  
21 Denso fuel pump, and assert claims for breach of express warranty, breach of  
22 implied warranty, strict liability, negligent undertaking, and fraudulent omission.

23 **II. JURISDICTION AND VENUE**

24 38. Subject matter jurisdiction is proper in this Court pursuant to the  
25 Class Action Fairness Act, 28 U.S.C. § 1332(a) and (d), because Plaintiffs and  
26 Class Members are citizens of a state different than Defendants’ home states, and  
27 the aggregate amount in controversy exceeds \$5,000,000, exclusive of interest and  
28 costs.

1           39. Subject matter jurisdiction is also proper in this Court pursuant to 28  
2 U.S.C. § 1331 because Plaintiffs’ Magnuson-Moss Warranty Act claim arises  
3 under federal law, and this Court has supplemental subject matter jurisdiction over  
4 Plaintiffs’ state law claims under 28 U.S.C. § 1367.

5           40. Venue is proper in this Court pursuant to 28 U.S.C. § 1391 because a  
6 substantial portion of actions giving rise to these claims occurred in this District,  
7 Mazda and Denso have caused harm to Plaintiffs in this District, and Mazda and  
8 Denso are residents of this District under 28 U.S.C. § 1391(c)(2) because they are  
9 subject to personal jurisdiction in this District. Venue is also proper in this District  
10 pursuant to 18 U.S.C. § 1965.

11 **III. THE PARTIES**

12 *Plaintiffs*

13           41. Plaintiff Townsend Vance is a citizen of Texas and resides in  
14 Houston, Texas.

15           42. Plaintiff Vance owns a 2018 Mazda CX-5 which she purchased new  
16 from Med Center Mazda in Pelham, Alabama on August 31, 2018.

17           43. Prior to purchasing her Mazda, Plaintiff Vance reviewed Mazda’s  
18 promotional materials touting its safety and reliability, such as, Mazda’s television  
19 advertisements, the Monroney sticker, and sales brochures, and interacted with at  
20 least one sales representative without Mazda disclosing the Fuel Pump Defect.

21           44. Through her exposure and interaction with Mazda, Plaintiff Vance  
22 was aware of Mazda’s uniform and pervasive marketing message that its vehicles  
23 are safe and dependable, which was material to her decision to purchase her Class  
24 Vehicle. When she purchased the vehicle, she believed, based on Mazda’s  
25 marketing message, that she would be in a safe and dependable vehicle, one that  
26 is safer than a vehicle that is not marketed as safe and dependable. At no point  
27 before Plaintiff Vance purchased her vehicle did Mazda disclose to her that her  
28

1 vehicle was not safe or dependable, or that it was equipped with a defective Denso  
2 fuel pump.

3 45. Plaintiff Vance’s Mazda suffers from the Fuel Pump Defect because  
4 the impeller in her vehicle started absorbing fuel and deforming the moment it was  
5 exposed to gasoline.

6 46. Plaintiff Vance’s Mazda suffers from the Fuel Pump Defect and  
7 during at least six different usages experienced hesitated and interrupted  
8 acceleration and near engine stall out.

9 47. The Fuel Pump Defect creates a dangerous condition that gives rise  
10 to a clear, substantial, and unreasonable danger of death or personal injury to  
11 Plaintiff Vance, other occupants in her Class Vehicle, and others on the road. At  
12 no time did Mazda inform Plaintiff Vance of the seriousness of the Fuel Pump  
13 Defect or recommend that she discontinue use of her vehicle until there is a repair  
14 or a replacement fuel pump.

15 48. Plaintiff Vance purchased her Class Vehicle with the Fuel Pump  
16 Defect as part of a transaction in which Mazda did not disclose material facts  
17 related to the automobile’s essential purpose—safe and dependable transportation.  
18 Plaintiff Vance did not receive the benefit of her bargain. She purchased a vehicle  
19 that is of a lesser standard, grade, and quality than represented, and she did not  
20 receive a vehicle that met ordinary and reasonable consumer expectations  
21 regarding safe and reliable operation. The Fuel Pump Defect has significantly  
22 diminished the value of Plaintiff Vance’s Class Vehicle.

23 49. Had Mazda disclosed the Fuel Pump Defect, Plaintiff Vance would  
24 not have purchased her Class Vehicle, or would have paid less to do so.

25 50. Plaintiff Vance would purchase a Mazda from Mazda in the future if  
26 Defendants’ representations about the vehicle, including its safety and durability,  
27 were accurate.

28

1           51. Plaintiff Zachary Haines is a citizen of California and resides in Los  
2 Angeles, California.

3           52. Plaintiff Haines owns a 2018 Mazda 3 Touring which he purchased  
4 used from Russell Westbrook Hyundai of Garden Grove, California on June 15,  
5 2019.

6           53. Prior to purchasing his Mazda, Plaintiff Haines reviewed Mazda’s  
7 promotional materials touting its safety and reliability, such as, Mazda’s television  
8 advertisements, the Monroney sticker, and sales brochures without Mazda  
9 disclosing the Fuel Pump Defect.

10           54. Through his exposure and interaction with Mazda, Plaintiff Haines  
11 was aware of Mazda’s uniform and pervasive marketing message that its vehicles  
12 are safe and dependable, which was material to his decision to purchase his Class  
13 Vehicle. When he purchased the vehicle, he believed, based on Mazda’s marketing  
14 message, that he would be in a safe and dependable vehicle, one that is safer than  
15 a vehicle that is not marketed as safe and dependable. At no point before Plaintiff  
16 Haines purchased his vehicle did Mazda disclose to him that his vehicle was not  
17 safe or dependable, or that it was equipped with a defective Denso fuel pump.

18           55. Plaintiff Haines’ Mazda suffers from the Fuel Pump Defect because  
19 the impeller in his vehicle started absorbing fuel and deforming the moment it was  
20 exposed to gasoline.

21           56. Plaintiff Haines’ Mazda suffers from the Fuel Pump Defect and on  
22 numerous occasions has experienced hesitated acceleration and difficulty with  
23 starting the vehicle.

24           57. The Fuel Pump Defect creates a dangerous condition that gives rise  
25 to a clear, substantial, and unreasonable danger of death or personal injury to  
26 Plaintiff Haines, other occupants in his Class Vehicle, and others on the road. At  
27 no time did Mazda inform Plaintiff Haines of the seriousness of the Fuel Pump  
28

1 Defect or recommend that he discontinue use of his vehicle until there is a repair  
2 or a replacement fuel pump.

3 58. Plaintiff Haines purchased his Class Vehicle with the Fuel Pump  
4 Defect as part of a transaction in which Mazda did not disclose material facts  
5 related to the automobile’s essential purpose—safe and dependable transportation.  
6 Plaintiff Haines did not receive the benefit of his bargain. He purchased a vehicle  
7 that is of a lesser standard, grade, and quality than represented, and he did not  
8 receive a vehicle that met ordinary and reasonable consumer expectations  
9 regarding safe and reliable operation. The Fuel Pump Defect has significantly  
10 diminished the value of Plaintiff Haines’ Class Vehicle.

11 59. Had Mazda disclosed the Fuel Pump Defect, Plaintiff Haines would  
12 not have purchased his Class Vehicle, or would have paid less to do so.

13 60. Plaintiff Haines would purchase a Mazda in the future if Defendants’  
14 representations about the vehicle, including its safety and durability, were  
15 accurate.

16 ***Defendants***

17 61. Defendant Mazda Motor Corporation (“MMC”) is a Japanese  
18 corporation with its principal place of business in Fuchu, Aki District, Hiroshima  
19 Prefecture, Japan, and the parent company of Mazda Motor of America, Inc.  
20 (“MMA”). MMC has substantial control over MMA, and MMA acts for the benefit  
21 of MMC.

22 62. At all relevant times, MMC acted in the United States by itself and  
23 through MMA and its various entities including in this District. MMC, itself and  
24 through MMA and its various entities, is in the business of designing, engineering,  
25 testing, validating, manufacturing, marketing, and selling Mazda branded vehicles  
26 throughout the United States, including within this District.

27 63. Defendant MMA is incorporated in California with its principal place  
28 of business in Irvine, California.

1           64. MMA is a holding company of sales, manufacturing, engineering,  
2 and research and development strategies of MMC in the United States and is  
3 wholly owned by MMC. MMA is in the business of designing, engineering,  
4 testing, validating, manufacturing, distributing, marketing, selling, and servicing  
5 Mazda branded vehicles in the United States, including within this District.

6           65. MMA, through its various entities, designs, manufactures, markets,  
7 distributes and sells Mazda automobiles through its hundreds of dealerships in the  
8 United States, including within this District.

9           66. FCA US LLC (“FCA”) is a Michigan limited liability company with  
10 its principal place of business in Auburn Hills, Michigan. FCA designs, tests,  
11 manufacturers, distributes, warrants, sells, and leases various vehicles under  
12 several prominent brands, such as Chrysler, Dodge, Jeep, Ram, and Fiat  
13 throughout the United States, including in this District.

14           67. Defendant Denso Corporation (“DC”) is a Japanese corporation  
15 located at 1-1, Showa-cho, Karlya, Alchi 448-9661, Japan. DC is the parent  
16 company of Denso International America, Inc. (“DIAM”).

17           68. DIAM is a wholly owned subsidiary of DC. DIAM acts for the benefit  
18 and at the discretion of DC.

19           69. DC, itself, and through DIAM and its various subsidiaries and agents,  
20 designed, engineered, tested, and validated the low-pressure fuel pump that is  
21 equipped in Mazda vehicles sold/leased in the United States, including in  
22 Plaintiffs’ states.

23           70. DIAM is incorporated in Delaware and has its principal place of  
24 business at 2477 Denso Drive Southfield, Michigan 48033. DIAM is a holding  
25 company of sales, manufacturing, engineering, and research and development  
26 subsidiaries of Denso Corporation located in the United States. DIAM is in the  
27 business of designing, engineering, testing, validating, manufacturing, selling,  
28

1 among other things, fuel pumps throughout the United States, including within this  
2 District.

3 71. DIAM is “Denso’s North American regional headquarters and parent  
4 company for its North American operations, including design and production  
5 engineering, technical support, sales and finance.”

6 72. DIAM, through its various entities and on behalf of DC, designed,  
7 engineered, tested, and validated the low-pressure fuel pump that is equipped in  
8 Mazda and Acura Vehicles across the United States, including in Plaintiffs’ states.

9 **IV. FACTUAL ALLEGATIONS**

10 73. Mazda and FCA manufacture, market, and sell vehicles all over the  
11 United States, including California.

12 74. Mazda and FCA have branded themselves as the makers of safe and  
13 dependable vehicles and has spent millions of dollars on extensive marketing and  
14 advertising campaigns to cement the association of safety and reliability with their  
15 Mazda and Fiat brands, including the Class Vehicles. Through their investment  
16 and marketing, Mazda and FCA sought to portray themselves as the safest vehicle  
17 brands on the market.

18 75. Denso is the world’s second largest Tier1 Original Equipment  
19 Manufacturer (“OEM”), producing parts and products for Mazda and other  
20 manufacturers. According to its website, Denso records nearly \$10.9 billion in  
21 annual sales in the United States, including in California.

22 76. According to Denso itself, when designing, engineering, testing, and  
23 manufacturing its products, Denso aims to “[c]ontribute to future mobility that is  
24 safer, more comfortable and convenient for everyone.” The defective fuel pumps  
25 fails to meet Denso’s published standard.

26 77. Defendants collectively designed, engineered, tested, validated,  
27 manufactured and placed in the stream of commerce Class Vehicles equipped with  
28 defective fuel pumps, thereby subjecting Plaintiffs and Class Members to an



1 unreasonable risk of death or injury, and damaging Plaintiffs and Class Members  
2 as further detailed below. Nonetheless, Mazda and FCA marketed and sold the  
3 Class Vehicles, and has, at all times, uniformly branded the Class Vehicles as safe  
4 and dependable.

5 **A. The Operation of Class Vehicles’ Low-Pressure Fuel Pump**

6 78. The Class Vehicles are equipped with Denso made low-pressure fuel  
7 pumps (the “Fuel Pump”).

8 79. All Class Vehicles are equipped with the same or substantially similar  
9 defective Fuel Pumps.


10 80. Fuel Pumps serve a critical role in the function of combustion  
11 engines. In simple terms, the fuel pump lifts gasoline out of the fuel tank and sends  
12 it to the engine where it is injected into the combustion chamber and ignited,  
13 driving the pistons and creating propulsion. Denso explains the role of the electric  
14 fuel pump as “deliver[ing] fuel from the tank to the engine, under high pressure,  
15 depending on the vehicle application’s specific requirements. The fuel is  
16 transported to fuel injectors, which spray the fuel into the engine cylinders.”<sup>18</sup>

17 81. The Fuel Pump assembly is mounted inside of the fuel tank. The Fuel  
18 Pump assembly consists of a fuel intake strainer at one end and a fuel output line  
19 at the other. At the heart of the Fuel Pump assembly is an electric motor with a  
20 plastic impeller attached to a rotating shaft. The impeller is a plastic disk that  
21 rotates and draws in fuel and pushes it up through the pump.<sup>19</sup> The impeller is  
22 equipped with vanes—or blades—that, when spun, creates negative pressure  
23 which lifts the gasoline out of the fuel tank and sends it to the engine. Protruding  
24 from the side of the Fuel Pump assembly is a fuel level float and a fuel level sender.


25  
26 \_\_\_\_\_  
27 <sup>18</sup> [https://www.denso-am.eu/media/1462778/2020\\_dems\\_web.pdf](https://www.denso-am.eu/media/1462778/2020_dems_web.pdf) (last  
visited November 16, 2021)

28 <sup>19</sup> <https://www.denso-am.co.uk/products/automotive-aftermarket/ems-lambda-sensor/fuel-pumps/how-they-work/> (last visited November 16, 2021).

1 Figure One illustrates the parts of the Fuel Pump assembly. Figure Two illustrates  
2 the internal components of the Denso Fuel Pump's electric motor.



3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13 **Figure 1 Fuel Pump Assembly Diagram<sup>20</sup>**




14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24 **Figure 2 Electric Motor Internal Components<sup>21</sup>**

25  
26 <sup>20</sup> [http://www.agcoauto.com/content/news/p2\\_articleid/195](http://www.agcoauto.com/content/news/p2_articleid/195) (last visited  
27 November 16, 2021).

28 <sup>21</sup> [https://aftermarket.denso.com.sg/product\\_info/?cat\\_id=194](https://aftermarket.denso.com.sg/product_info/?cat_id=194) (last visited  
November 16, 2021)

1 82. As the electric motor rotates, the impeller spins generating negative  
2 pressure. The negative pressure pulls fuel into the pump housing where it passes  
3 through the electric motor assembly and exits through the output, into the fuel line  
4 and forward to the fuel filter. After exiting the fuel filter, the fuel flow is  
5 accelerated via a high-pressure pump which delivers pressurized fuel to injectors  
6 mounted in the engine. Denso describes the operation of its in-tank fuel pump as  
7 “[w]hen the impeller of an in-tank [f]uel [p]ump rotates, the blade moves around  
8 the impeller, creating a swirling motion inside the pump to deliver fuel. The fuel  
9 then passes around the motor, forcing the check valve upwards to supply fuel to  
10 the fuel pipe.”<sup>22</sup> Figures Three and Four, below, illustrates this sequence.




11  
12  
13  
14  
15  
16  
17  
18  
19 **Figure 3 Fuel Pump Sequence**<sup>23</sup>


20  
21  
22  
23  
24  
25  
26 <sup>22</sup> <https://www.denso-am.eu/media/966284/dems180001mm-lr.pdf> (last  
27 visited November 16, 2021).

28 <sup>23</sup> <https://www.autoplusdubai.net/blog/fuel-pumps-common-causes-and-how-to-identify-it/> (last visited November 16, 2021).

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28



**Figure 4 Impeller Rotation Operation<sup>24</sup>**



**Figure 5**

<sup>24</sup> [https://aftermarket.denso.com.sg/product\\_info/?cat\\_id=194](https://aftermarket.denso.com.sg/product_info/?cat_id=194) (last visited November 16, 2021)

1 83. At all times, by design, the Fuel Pump assembly and all its  
2 components are exposed to gasoline within the tank. Fuel pumps are designed to  
3 survive the harsh environment for at least 200,000 miles.<sup>25</sup> Denso claims its fuel  
4 pumps “offer more than triple the lifetime ...”<sup>26</sup>

5 **B. The Class Vehicles Suffer From a Fundamentally Defective Fuel**  
6 **Pump**

7 84. As described herein, the Class Vehicles’ Fuel Pumps suffer from a  
8 fundamental defect causing them to prematurely fail. Engines operate within a  
9 narrow and precisely calibrated air fuel mixture range, which means they are very  
10 sensitive to fuel pressure and delivery requirements. Partial, intermittent, or  
11 complete fuel pump failure disturbs the calculated precision and results in engine  
12 stalling or hesitancy.

13 85. Based on Mazda’s, FCA’s, and Denso’s own admissions, and the  
14 findings of Plaintiffs’ Expert to date, the failure results from a defectively designed  
15 plastic impeller in the Fuel Pump.

16 86. A manufacturer’s goal in designing and manufacturing a fuel pump  
17 must be to design and create one that operates safely and dependably for the life  
18 of the vehicle. According to the analysis of Plaintiffs’ Expert to date, and by  
19 Mazda’s, FCA’s, and Denso’s admissions, the Fuel Pump assembly in the Class  
20 Vehicles was poorly designed and/or manufactured.

21 87. As Defendants admit, the subject Fuel Pumps contain an impeller that  
22 could deform due to excessive fuel absorption.<sup>27</sup> The Denso Fuel Pump impeller’s  
23 material is unsuitable for its environment due to its excessive fuel absorption  
24

25 \_\_\_\_\_  
26 <sup>25</sup> <https://www.autoblog.com/2015/11/24/how-long-does-a-fuel-pump-usually-last/> (last visited November 16, 2021).

27 <sup>26</sup> <https://densoautoparts.com/fuel-pumps.aspx> (last visited November 16,  
28 2021).

<sup>27</sup> Compare Exhibits A-B with Exhibits C-G.

1 propensity, which causes swelling and premature and unexpected Fuel Pump  
2 failure.<sup>28</sup>

3 88. Plaintiffs’ Expert’s research to date indicates that the Denso impeller  
4 uses an unsuitable material for its intended use. The impeller’s material has an  
5 inferior long-term dimensional instability (it deforms, swells and changes shape),  
6 resulting in premature and unexpected failure due to component distortion and the  
7 resultant swelling induced friction.

8 89. The Denso impeller’s material has inadequate heat resistance,  
9 potentially resulting in dimensional distortion and loss of structural integrity when  
10 exposed to high temperatures or repeated temperature cycling (i.e., the intended  
11 and repeated temperature changes of operation).

12 90. The impeller’s material is also highly porous, which may lead not  
13 only to absorption of gasoline, but also fuel contaminants may become lodged in  
14 the impeller’s pores, leading to Fuel Pump failure.

15 91. Plastics absorb liquids, typically. However, the degree of absorption  
16 varies depending on the type of plastic and its environmental conditions. When  
17 plastics absorb liquid, such as gasoline, the plastic pieces’ intended dimensions  
18 change. Therefore, manufacturers like Denso, Mazda, and FCA must adequately  
19 design and validate plastic materials exposed to liquids to ensure that they remain  
20 dimensionally stable.<sup>29</sup> Here, Mazda, FCA, and Denso clearly failed to do that with  
21 respect to the Fuel Pumps in the Class Vehicles.

22 92. Moreover, according to Plaintiffs’ Expert’s research to date, Denso’s  
23 further hypothesis that lower surface strength of the impeller contributes to the  
24 Fuel Pump Defect is an obvious and expected correlation rather than a separate  
25 issue. Notably, it is typical and expected for a low-density material to exhibit lower  
26

27 <sup>28</sup> See Exhibit A at 1-2.

28 <sup>29</sup> [https://www.ensingerplastics.com/en-us/shapes/plastic-material-selection/  
dimensionally-stable](https://www.ensingerplastics.com/en-us/shapes/plastic-material-selection/dimensionally-stable) (last visited November 16, 2021).

1 surface strength when compared to a higher density material. It is also expected  
2 that low density materials would have higher porosity and absorption propensity  
3 compared to higher density materials.

4 93. Mazda, FCA, and Denso admitted the impeller was poorly designed  
5 to the point that it cannot remain dimensionally stable under its intended  
6 conditions. Specifically, the Mazda Recall admitted that “[f]uel pump failure may  
7 result in engine no start and/or vehicle stall while driving at low speed and, in rare  
8 instances, a vehicle stall could occur while driving at high speeds, increasing the  
9 risk of a crash.”<sup>30</sup> FCA’s Recall stated that “Fuel starvation may result in an  
10 unexpected loss of motive power, which can cause vehicle crash without prior  
11 warning.” Moreover, Denso admitted in the Denso Recalls that the impeller “may  
12 become deformed” and cause the Fuel Pump to fail and become inoperable.<sup>31</sup>

13 94. The Fuel Pump Defect manifests from the moment the Fuel Pump is  
14 installed in the fuel tank and submerged in gasoline. Once exposed to gasoline, the  
15 impeller begins to absorb fuel, swell, and deform.

16 95. The Fuel Pump and/or the Fuel Pump impeller was not designed  
17 and/or manufactured with the necessary robustness to operate safely under normal  
18 operating conditions.

19 96. At the time the Fuel Pumps were designed, engineered, tested,  
20 validated, manufactured, and placed in the stream of commerce by Defendants,  
21 Defendants were aware of, and had access to, reasonable alternative designs. Such  
22 designs would mitigate or eliminate the Fuel Pump Defect.

23 97. For example, Defendants could have mitigated or eliminated the Fuel  
24 Pump Defect by using different designs and/or materials where:

- 25 a. The impeller was not fuel permeable under intended and  
26 foreseeable purposes;

27 \_\_\_\_\_  
28 <sup>30</sup> Exhibit E.

<sup>31</sup> Exhibit A.

- 1           b.     The impeller would not deform when exposed to operating
- 2                 temperatures under intended and foreseeable purposes;
- 3           c.     The impeller would not prematurely age under intended and
- 4                 foreseeable purposes;
- 5           d.     The impeller would not lose its dimensional stability under
- 6                 intended and foreseeable purposes; and/or
- 7           e.     The impeller would not contact the fuel pump body under
- 8                 intended and foreseeable purposes; and/or
- 9           f.     The Fuel Pump would not overheat under intended and
- 10                foreseeable purposes.

11           98.    Nevertheless, Defendants designed, engineered, tested, validated,

12           manufactured, and placed in the stream of commerce Class Vehicles equipped with

13           the defective Fuel Pumps that cause an unreasonable risk of injury or death to the

14           Plaintiff, Class Members, and others.

15           **C.     The Fuel Pump Defect Reduces Engine Power, Causes Vehicle**

16           **Stalling, and Can Leave the Class Vehicles Completely**

17           **Inoperable Compromising Consumer Safety**

18           99.    The Fuel Pump Defect in the Class Vehicles exposes occupants and

19           others to extreme danger, even death. In fact, Mazda, FCA, and Denso tacitly

20           admitted as much in their respective recalls, stating that the Fuel Pump Defect can

21           “increas[e] the risk of a crash.”<sup>32</sup>

22           100.   The Fuel Pump is an integral component of safe vehicle operation.

23           But as described herein, the Class Vehicles suffer from a fundamental design flaw

24           that causes the Fuel Pump to prematurely fail. As Mazda admitted in its recall, the

25           deformed impeller comes in contact with the Fuel Pump body, creating excess

26           running resistance, resulting in “engine no start and/or vehicle stall” and

27           “increasing the risk for a crash.”<sup>33</sup> FCA’s Recall stated that “Fuel starvation may

28           <sup>32</sup>     Compare Exhibits A-B with Exhibit E.

<sup>33</sup>     Exhibit E.



1 result in an unexpected loss of motive power, which can cause vehicle crash  
2 without prior warning.” In the Denso Recalls, Denso admitted the deformed  
3 impeller contacts the Fuel Pump body, creating excess running resistance and  
4 causing reduced engine performance or complete engine failure:

5 If an impeller deforms to a point that creates sufficient interference  
6 with the fuel pump body, the fuel pump becomes inoperative.  
7 According to vehicle manufacturer’s system evaluation, an  
8 inoperative fuel pump may result in the illumination of the check  
9 engine light and/or master warning indicators, rough engine running,  
10 engine no start and/or vehicle stall while driving at low speed and, in  
11 rare instances, a vehicle stall could occur while driving at higher  
12 speeds, increasing the risk of a crash.<sup>34</sup>

11 101. Engines necessarily require steady gasoline supply to function  
12 properly. The Fuel Pump’s primary purpose is to transfer gasoline from the tank  
13 to the engine. But when the Fuel Pump fails, gasoline is not supplied to the engine,  
14 causing reduced engine power, stalling, and/or engine shutdown.

15 102. Compounding the problem, Fuel Pump Defect occurs spontaneously  
16 with no advance warning to the consumer, thereby creating an extremely  
17 dangerous condition for drivers, including those on the road who may be left  
18 helpless and unable to take action to get out of the way of oncoming traffic or reach  
19 safety.

20 103. Class Members’ complaints set forth below exemplify the real-world  
21 dangers caused by the Fuel Pump Defect.

22 104. Vehicle manufacturers like Mazda and FCA monitor NHTSA and  
23 other databases for consumer complaints as part of their ongoing obligation to  
24 uncover and report potential safety-related defects. Accordingly, Mazda (and  
25 therefore FCA) knew, or should have known, of the many complaints lodged with  
26  
27  
28

---

<sup>34</sup> See Exhibits A and B.

1 NHTSA and elsewhere about the specific safety hazard that is the subject of the  
2 Recalls.

3 105. By way of example, the consumer complaints set forth below  
4 demonstrate the seriousness of the Fuel Pump Defect and further show that Mazda  
5 and FCA knew or should have known of them as early as 2017, or was reckless in  
6 not knowing of them. These consumer complaints represent a small fraction of the  
7 hundreds of similar complaints submitted to NHTSA by owners and lessees of the  
8 Class Vehicles regarding the Fuel Pump Defect.

9 106. On August 21, 2017, the owner of a 2015 Mazda3 filed the following  
10 complaint with NHTSA:

11 HOT WEATHER ACCELERATION AND BLIND SPOT  
12 MONITORING SYSTEM (BSM) ISSUE: IN EXTREMELY HOT  
13 WEATHER BSM OFF LIGHT TURNS ON REPEATEDLY WHILE  
14 THE VEHICLE IS IN MOTION OR STARTING FROM  
15 COMPLETE STOP. AT THE SAME TIME THE INFOTAINMENT  
16 SYSTEM DISPLAY FLICKERS IN SYNC WITH THE BSM OFF  
17 LIGHT APPEARANCE. WHEN THIS OCCURS THERE IS A  
18 CLICKING SOUND COMING FROM THE FRONT OF THE  
19 CAR/WHERE THE ENGINE IS LOCATED. THE SOUND IS  
20 ACCOMPANIED BY TEMPORARY LOSS OF ACCELERATION  
21 WHEN IN MOTION OR STARTING TO MOVE FROM A  
22 COMPLETE STOP. WHEN THIS OCCURS WHILE STARTING  
23 FROM A COMPLETE STOP, THE ENGINE REVOLUTIONS  
24 (REV) DROPS BELOW 1K RPM DESPITE GAS PEDAL INPUT  
25 THUS THE CAR WOULD NOT MOVE/ACCELERATE FOR  
26 ABOUT 5 SECONDS. WHEN IT OCCURS WHEN THE CAR IS  
27 IN MOTION SUCH AS ON THE HIGHWAY OR MERGING  
28 ONRAMP INTO THE HIGHWAY THE CAR UNSAFELY SLOWS  
DOWN DESPITE GAS PEDAL INPUT. AGAIN THIS ISSUE IS  
OBSERVED DURING UNUSUALLY HOT DAYS EG. JULY 22,  
2017 IN ST. LOUIS, MISSOURI<sup>35</sup>

107. On January 31, 2018, the owner of a 2013 Mazda CX-7 filed the  
following complaint with NHTSA:

<sup>35</sup> NHTSA ID 11018752.

1 TL\* THE CONTACT INQUIRED ABOUT A 2013 MAZDA CX-7.  
2 THE CONTACT STATED THAT THE VEHICLE EXPERIENCED  
3 A LACK OF ACCELERATION AND REDUCED ENGINE  
4 POWER. ALSO, THE TRACTION CONTROL WARNING  
5 INDICATOR ILLUMINATED. THE DEALER WAS NOT  
6 CONTACTED. THE MANUFACTURER WAS NOT NOTIFIED.  
7 THE FAILURE MILEAGE WAS APPROXIMATELY 59,400.<sup>36</sup>

8 108. On May 13, 2018, the owner of a 2018 Mazda CX-5 filed the  
9 following complaint with NHTSA:

10 SITUATION: DRIVING UPHILL ON HWY 120 ON NEW PRIEST  
11 ROAD, BIG OAK FLAT, CA, TWO LANE MOUNTAIN ROAD.  
12 SLOW CAR IN FRONT OF ME AND A DELIVERY TRUCK  
13 TAILGATING. SLOW CAR EVENTUALLY MOVES ASIDE IN A  
14 TURNOUT AND I ACCELERATE TO OPEN UP SPACE  
15 BETWEEN MYSELF AND WHAT I THOUGHT WOULD BE THE  
16 TRUCK BUT SOMEHOW THE SLOW CAR RETURNED TO THE  
17 DRIVING LANE AHEAD OF THE TRUCK. I CONTINUE TO  
18 ACCELERATE TO ATTEMPT TO OPEN UP SPACE BETWEEN  
19 MYSELF AND THE CAR BEHIND ME WHEN I LOST POWER,  
20 THE CAR BEHIND ME MOVES TO THE OPPOSING TRAFFIC  
21 LANE TO AVOID REAR ENDING MY CAR THAT IS RUNNING  
22 IN DEGRADED MODE (ACCELERATOR HAS NO EFFECT,  
23 BASICALLY MOVING ON IDLE POWER) AND NARROWLY  
24 MISSES AN ONCOMING CAR AS I MOVE TOWARDS THE  
25 RIGHT EDGE OF THE RIGHT LANE. TRUCK BEHIND ME HAS  
26 TO BRAKE HARD TO AVOID REAR ENDING ME. THERE WAS  
27 NO SHOULDER TO PULL OVER TO AT THAT LOCATION  
28 IMMEDIATE LOCATION. I PULL OVER A FEW HUNDRED  
YARDS FURTHER AT A SAFE LOCATION. GRADE WAS  
PERHAPS 4% TO 6%. WEATHER: HOT 90 DEGREES SPEED:  
ACCELERATING FROM 35 TO 50 MPH (GUESS) DIAGNOSTIC  
LIGHTS: SMART CITY BRAKING SYSTEM FAILURE  
WARNING, PLUS A LOT OF OTHER WARNING LIGHTS LIT  
INCLUDING CHECK ENGINE LIGHT. AFTERMATH: I PULLED  
SAFELY OVER, STOPPED THE ENGINE, WAITED A WHILE  
AND RESTARTED THE ENGINE AND THE CAR RETURNED  
TO IT'S NORMAL DRIVING BEHAVIOR AND COMPLETED  
MY TRIP. OTHER INFORMATION: THIS IS THE 3RD

<sup>36</sup> NHTSA ID 11066016.

1 OCCURRENCE OF THIS BEHAVIOR. EACH TIME I HAVE HAD  
2 MAZDA LOOK AT THE PROBLEM. 1ST OCCURRENCE THEY  
3 REPLACED THE CYLINDER COIL, 2ND OCCURRENCE THEY  
4 REPLACED A SPARK PLUG FOR MISFIRE. 3RD  
OCCURRENCE, TO BE DETERMINED.<sup>37</sup>

5 109. On June 12, 2018, the owner of a 2015 Mazda3 filed the following  
6 complaint with NHTSA:

7 TL\* THE CONTACT OWNS A 2015 MAZDA 3. WHILE  
8 ACCELERATING FROM A TRAFFIC LIGHT, THE VEHICLE  
9 STALLED WITHOUT WARNING. THE CONTACT WAS  
10 UNABLE TO RESTART THE VEHICLE. THE VEHICLE WAS  
11 TOWED TO GUNTHER MAZDA (1800 S STATE RD 7, FORT  
12 LAUDERDALE, FL 33317, (954) 797-1600) WHERE IT WAS  
13 DIAGNOSED THAT THE BATTERY NEEDED TO BE  
14 REPLACED. THE VEHICLE WAS REPAIRED; HOWEVER, THE  
15 FAILURE RECURRED. THE VEHICLE WAS THEN TOWED TO  
16 LOU BACHRODT MAZDA COCONUT CREEK (5400 SR 7,  
17 COCONUT CREEK, FL 33073, (954) 247-5000) WHERE IT WAS  
DIAGNOSED THAT THE FUEL PUMP NEEDED TO BE  
REPLACED. THE VEHICLE WAS REPAIRED, BUT THE  
FAILURE RECURRED TWICE. THE MANUFACTURER WAS  
INFORMED OF THE FAILURES. THE APPROXIMATE  
FAILURE MILEAGE WAS 36,000.<sup>38</sup>

18 110. On July 15, 2018, the owner of a 2018 Mazda CX-9 filed the  
19 following complaint with NHTSA:

20 ON FRIDAY (JUNE 29TH, 2018) AROUND 9:29 PM, MY CAR  
21 BROKE DOWN WHILE MY FAMILY AND I WERE  
22 TRAVELING FROM ROCHESTER NY TO BOSTON  
23 MASSACHUSETTS. I WAS DRIVING DOWN THE  
24 MASSACHUSETTS TURNPIKE WHEN ALL OF A SUDDEN MY  
25 CHECK ENGINE LIGHT TURNED ON AND MY CAR JUST  
26 STARTED TO SLOW DOWN IN THE MIDDLE OF THE  
HIGHWAY. I WAS ABLE TO PULL OVER IN TIME AND  
CALLED MAZDA ROADSIDE ASSISTANCE BECAUSE AFTER  
THE CAR STOPPED, IT WOULDN'T TURN BACK ON. SINCE

27  
28 <sup>37</sup> NHTSA ID 11416469.

<sup>38</sup> NHTSA ID 11101309.

1 WE WERE ON A RESTRICTED HIGHWAY, MY CAR HAD TO  
 2 BE TOWED AND WE WERE TAKEN TO A SAFER LOCATION.  
 3 WHEN THE CAR WAS PUT DOWN, IT TURNED ON AND THE  
 4 CHECK ENGINE LIGHT WAS STILL ON AND THE FUEL  
 5 GAUGE SAID THAT THE CAR STILL HAD 40 MILES LEFT.  
 6 THE GUY THAT TOWED OUR CAR SAID THAT IT MIGHT  
 7 HAVE BEEN A FUEL ISSUE, SO WE WENT TO GET GAS.  
 8 ONCE WE FILLED UP OUR TANK THE CHECK ENGINE  
 9 LIGHT WAS STILL ON BUT WE WERE ABLE TO REACH OUR  
 10 DESTINATION. THE NEXT MORNING, I TOOK THE CAR TO  
 11 THE NEAREST MAZDA DEALERSHIP AND THEY  
 12 RESTARTED THE CAR AND ACCORDING TO THEIR REPORT  
 13 NOTHING WAS WRONG WITH THE CAR. THEY SAID THAT  
 14 IT WAS SAFE TO DRIVE BUT THEY HAD NO CLEAR REASON  
 15 AS TO WHY THE FUEL GAUGE WASN'T STATING THE  
 16 CORRECT INFORMATION. AFTER THE TRIP I, REPORTED  
 17 THIS ISSUE TO MAZDA AND THEY DIDN'T ANSWER ME  
 18 UNTIL TWO WEEKS LATER. THEIR RESPONSE WAS THAT  
 19 THERE WAS PROBABLY NOTHING WRONG WITH THE  
 20 VEHICLE AND THAT THIS WAS A ONE TIME ISSUE. I DID  
 21 RESEARCH ON MY OWN AND DISCOVERIES THAT  
 22 SOMEONE FROM SAUDI ARABIA HAD A SIMILAR ISSUE.  
 23 SINCE MAZDA HASN'T BEEN WILLING TO HELP RESOLVE  
 24 THE SITUATION I AM FILING THIS COMPLAINT BECAUSE I  
 25 AM NOT WILLING TO PUT MY FAMILIES LIFE IN THE SAME  
 26 RISK AGAIN.<sup>39</sup>

19 111. On January 2, 2019, the owner of a 2014 Mazda3 filed the following  
 20 complaint with NHTSA:

21 OCCASIONALLY THE ENGINE WILL HESITATE WHEN  
 22 ACCELERATING, AND THEN THE CHECK ENGINE LIGHT,  
 23 TPM, AND STABILITY CONTROL LIGHT WILL ILLUMINATE  
 24 ON THE DASH. LESS FREQUENTLY, THE ENGINE WILL  
 25 OCCASIONALLY STALL WHILE DRIVING OR WHILE  
 26 SITTING AT A STOP LIGHT. THE LIGHTS ON THE  
 27 DASHBOARD WILL REMAIN ILLUMINATED, SO I DO NOT  
 28 THINK IT'S A TOTAL LOSS OF POWER.<sup>40</sup>

---

<sup>39</sup> NHTSA ID 11111474.

<sup>40</sup> NHTSA ID 11164555.

1 112. On June 2, 2019, the owner a 2019 Mazda3 filed the following  
2 complaint with NHTSA:

3 REAR VIEW MIRROR FELL OFF WHILE ON THE FREEWAY.  
4 HOT DAYS WILL BREAK DOWN THE ADHESIVE AND  
5 CAUSE THE REAR VIEW MIRROR TO FALL OFF. - BRAKES  
6 VIBRATE HARSHLY WHEN IN SPORT MODE. FASTER THE  
7 VEHICLE GOES, THE MORE HARSH THE BRAKES WILL  
8 VIBRATE. – ACCELERATION IS JERKY ON LOW END  
9 (1ST/2ND) GEAR. IN STOP AND GO TRAFFIC, OR GOING UP-  
10 HILL ON LOAD, ACCELERATION WILL FEEL JERKY WHEN  
11 TRY TO KEEP A STEADY SPEED BETWEEN 5-15MPH. CAR  
12 FEELS NORMAL WHEN PUSHING THE ACCELERATION  
13 HARDER.<sup>41</sup>

11 113. On July 23, 2019, the owner of a 2016 Mazda CX-9 filed the  
12 following complaint with NHTSA:

13 IN 2017, MY CAR SHUT OFF TWO TIMES, WITHOUT  
14 WARNING, ONE TIME AT A STOP LIGHT AND AGAIN ON  
15 THE HIGHWAY GOING 70MPH. WE WERE ACCELERATING  
16 AT THE STOP LIGHT WHEN IT SHUT OFF AND THEN  
17 DRIVING ON THE HIGHWAY. TOOK THE CAR TO THE  
18 DEALERSHIP AND 72 CODES CAME UP. THEY SAID IT WAS  
19 THE DVD PLAYERS (THAT THEY SOLD AND INSTALLED!!!)  
20 THAT WERE CAUSING THE ISSUE. THEY SUPPOSEDLY  
21 ‘FIXED’ THE ISSUE. NOW IN JULY 2019, THE CAR SHUT OFF  
22 AN ADDITIONAL FIVE TIMES. THREE TIMES WHILE  
23 DRIVING AND TWICE IN A PARKING LOT. WE WERE ON A  
24 HIGHWAY AGAIN WHEN THE CAR JUST SHUT OFF WITH NO  
25 WARNING, LIGHTS ON THE DASH STARTED FLASHING,  
26 AND THE POWER STEERING WENT OUT ONE OF THE TIMES.  
27 MY HUSBAND HAD TO PUT IT IN NEUTRAL, COAST TO THE  
28 SHOULDER, COME TO A COMPLETE STOP AND THEN  
ATTEMPT TO START IT EACH TIME. CARS WERE DODGING  
US EVERY TIME AND LUCKILY WE WEREN’T HURT. MY  
CHILDREN WERE IN THE VEHICLE EVERY SINGLE TIME.  
WE HAD THE CAR TOWED TO THE DEALERSHIP WHERE 68  
CODES CAME UP. THIS TIME THEY’RE SAYING IT’S  
THE FUEL PUMP AND THAT THEY CAN ‘FIX’ IT, BUT CAN’T

<sup>41</sup> NHTSA ID 11217419.

1 100% GUARANTEE IT WON'T HAPPEN AGAIN. WE WERE  
2 PUT IN A LIFE THREATENING SITUATION EVERY TIME,  
3 WITHOUT WARNING, AFTER GIVING THE DEALERSHIP A  
4 CHANCE TO FIX IT. THE CAR IS UNDER THREE YEARS OLD  
AND ONLY HAS 30,400 MILES ON IT.<sup>42</sup>

5 114. On September 6, 2019, the owner of a 2018 Mazda CX-5 filed the  
6 following complaint with NHTSA:

7 TL\* THE CONTACT OWNS A 2018 MAZDA CX-5. WHILE  
8 DRIVING 20 MPH AND BELOW, THE VEHICLE FAILED TO  
9 ACCELERATE. THE CONTACT HAD TO DEPRESS THE  
10 ACCELERATOR PEDAL WITH FORCE TO INCREASE THE  
11 SPEED. THE CONTACT TOOK THE VEHICLE TO FINDLAY  
12 MAZDA (7760 EASTGATE ROAD, HENDERSON, NV 89011,  
13 (702) 955-5555) TO BE REPAIRED PER NHTSA CAMPAIGN  
14 NUMBER: 19V497000 (ENGINE, POWER TRAIN); HOWEVER,  
15 THE REPAIR DID NOT CORRECT THE FAILURE. THE  
16 CONTACT TOOK THE VEHICLE BACK TO THE DEALER, BUT  
THEY WERE UNABLE TO LOCATE ANY FAILURE CODES.  
THE MANUFACTURER WAS CONTACTED AND PROVIDED  
CASE NUMBER: 1-2318934006. THE VEHICLE WAS NOT  
REPAIRED. THE FAILURE MILEAGE WAS 24,800.<sup>43</sup>

17 115. On September 27, 2019, the owner of a 2014 Mazda6 filed the  
18 following complaint with NHTSA:

19 ENGINE WILL STALL OUT WHILE DRIVING VEHICLE LOSES  
20 ALL POWER CHECK ENGINE LIGHT COMES ON BATTERY  
21 LIGHT COMES ON TRACTION CONTROL LIGHT COMES ON.  
22 WHEN ENGINE STALLS OUT AND THEN I LOSE POWER  
23 STEERING AND BRAKE CONTROL AND WILL HAVE TO  
24 PULL OVER TO THE SIDE TO RESTART THE VEHICLE.  
ENGINE WILL SPUTTER ON START UP WHICH SOUNDS  
LIKE A FAULTY MASS AIRFLOW SENSOR THIS IS A 2014  
MAZDA MAZDA 6 WITH 57000 MILES<sup>44</sup>

27 <sup>42</sup> NHTSA ID 11234063.  
28 <sup>43</sup> NHTSA ID 11253636.  
<sup>44</sup> NHTSA ID 11258590.

1 116. On November 12, 2019, the owner of a 2018 Mazda CX-5 filed the  
2 following complaint with NHTSA:

3 MAZDA CX-5. CONSUMER WRITES IN REGARDS TO  
4 VEHICLE BEING TOTALED AS A RESULT OF LOSS OF  
ENGINE POWER. \*LD \*JS<sup>45</sup>

5 117. On February 6, 2020, the owner of a 2019 Mazda CX-5 filed the  
6 following complaint with NHTSA:

7 I WAS DRIVING ON THE FREEWAY ABOUT 65 MILES PER  
8 HOUR AND THE THE CAR STARTED TO RUN ROUGH AND  
9 THE DASH LIGHTS WENT OUT. IT FELT LIKE IT WANTED  
10 TO STALL SO I KEPT MY FOOT ON THE GAS AND BRAKE  
11 AND EXITED THE FREEWAY AND DROVE THE SIDE  
STREETS HOME. THE PROBLEM DID NOT HAPPEN AGAIN  
SO FAR.<sup>46</sup>

12 118. On May 9, 2020, the owner of a 2018 Mazda CX-5 filed the following  
13 complaint with NHTSA:

14 ON MAY 9, 2020, OUR MAZDA CX5 LOST THRUST, STALLED  
15 AND CAME TO A COMPLETE STOP WHILE DRIVING ON A  
16 HIGHWAY GOING 55 MPH ON A STRAIGHT 3 LANE ROAD.  
17 THIS OCCURRED DESPITE THE PCM PROGRAMMING WAS  
RE-CALIBRATED DUE TO A MANUFACTURER RECALL IN  
18 SEPTEMBER 2019 (NHTSA RECALL NO. 19V497000). THE  
CAR IS TOWED TO A MAZDA SERVICE CENTRE AND IS  
AWAITING DIAGNOSIS. \*TR<sup>47</sup>

19 119. On June 16, 2020, the owner of a 2019 Mazda CX-5 filed the  
20 following complaint with NHTSA:

21 IN JULY 2019 (APPROXIMATELY 2 MONTHS AFTER  
22 DELIVERY) MY 2019 MAZDA CX-5 BEGAN TO DRIVE  
23 ROUGHLY AT SLOW SPEEDS- SPECIFICALLY SPEEDS 15  
24 MPH OR BELOW. THE VEHICLE WOULD NOT COAST (EVEN  
DOWNHILL) AND WOULD SEEM TO SLIP OUT OF GEAR  
(THIS VEHICLE HAS AN AUTOMATIC TRANSMISSION).  
25 MORE SPECIFICALLY, THE VEHICLE WOULD BUCK AND  
LURCH ON IT'S OWN WITHOUT ENGAGING THE  
26

27 <sup>45</sup> NHTSA ID 11278994.  
28 <sup>46</sup> NHTSA ID 11307591.  
<sup>47</sup> NHTSA ID 11324001.



1 ACCELERATOR OR BRAKE. THIS WAS HAPPENING GOING  
 2 UPHILL, DOWNHILL AND ON FLAT GRADE. I BROUGHT  
 3 THE VEHICLE TO THE DEALER AND AT THEIR REQUEST  
 4 TOOK AN EMPLOYEE FOR A DRIVE SO THEY COULD FEEL  
 5 IT. THE EMPLOYEE DID FEEL IT, TOLD THE SERVICE  
 6 MANAGER, WHO THEN TOLD ME THAT, "THEY ARE  
 7 SUPPOSED TO DRIVE LIKE THAT." HE SAID HE DROVE  
 8 AROUND ANOTHER VEHICLE ON THE LOT THAT IS THE  
 9 SAME MODEL AND YEAR, AND THAT IT PERFORMED THE  
 10 SAME. PLEASE NOTE THAT THIS IS NOT THE SAME PERSON  
 11 WHO WAS IN THE CAR TO EXPERIENCE HOW MY CAR WAS  
 12 DRIVING. I PERSONALLY KNOW TWO OTHER PEOPLE WHO  
 13 HAVE THE SAME EXACT YEAR AND MODEL CX-5. I  
 14 SHARED MY EXPERIENCE WITH BOTH OWNERS- THEY  
 15 BOTH TOLD ME THAT THEIR CARS DO NOT PERFORM IN  
 16 THAT WAY. ADDITIONALLY, I DROVE ONE OF THOSE  
 17 VEHICLE AND THAT ONE DID NOT PERFORM IN THE SAME  
 18 WAY THAT MINE DOES. I AM CONCERNED THAT THIS  
 19 ISSUE IS BEING BRUSHED OFF. THERE IS NO WAY THAT  
 20 MAZDA WOULD PURPOSELY DESIGN A CAR SO THAT IT  
 21 JERKS, LURCHES, AND BUCKS AT SLOW SPEEDS. I HAVE  
 22 READ REVIEWS ON ONLINE MESSAGE BOARDS WHERE  
 23 OTHERS DO COMPLAIN OF SIMILAR EXPERIENCES, WHICH  
 24 IS EVEN MORE CONCERNING. THIS POSES A SAFETY ISSUE  
 25 FOR THE DRIVER, PASSENGERS, AND OTHERS ON THE  
 26 ROAD WHO MAY BE DRIVING NEARBY. I HAVE AN  
 27 APPOINTMENT AND WILL BE TAKING THE CAR BACK THIS  
 28 COMING MONDAY TO TRY AND FURTHER ADDRESS THIS  
 ISSUE, BUT FELT IT NECESSARY TO FILE HERE IN THE  
 CASE THAT FURTHER ACTION NEEDS TO BE TAKEN AT A  
 LARGER SCALE SINCE IT APPEARS AS IF OTHERS, THOUGH  
 NOT ALL, 2019 MAZDA CX-5 OWNERS ARE EXPERIENCING  
 THE SAME. \*TR<sup>48</sup>

120. On June 30, 2020, the owner of a 2020 CX-30 filed the following  
 complaint with NHTSA:

I WAS DRIVING CAR ON.THE HIGHWAY AND AS I  
 PREPARED TO EXIT I BRAKED AND THE  
 CAR HESITATED FOR 2 SECONDS BEFORE BRAKES  
 ENGAGED. CAR HAS ALSO HAD HESITATION  
 UPON ACCELERATION PERIODICALLY .THIS HAS BEEN AN  
 ISSUE UPON JUST A FEW WEEKS OF OWNERSHIP. THE

<sup>48</sup> NHTSA ID 11329175.

1 BREAK ISSUE WAS JUST RECENTLY 7-29-20 I HAVE TAKEN  
2 THE CAR TO THE LOCAL DEALERSHIP ABOUT THE  
3 DRIVING/ACCELARATION ISSUE TWICE WITHOUT  
4 RESOLUTION.<sup>49</sup>

4 121. On September 4, 2020, the owner of a 2016 Mazda CX-5 filed the  
5 following complaint with NHTSA:

6 TL\* THE CONTACT OWNS A 2018 MAZDA CX-5. THE  
7 CONTACT STATED WHILE DRIVING AT LOW SPEEDS, THE  
8 VEHICLE STALLED AND WAS RESTARTED. WHILE THE  
9 PUSH-TO-START WAS ENGAGED, THE VEHICLE REVVED  
10 UP HIGH, STALLED, AND RESTARTED. ADDITIONALLY,  
11 THE AIR CONDITIONER FAILED TO OPERATE AS  
12 DESIGNED. THE RADIO WAS ALSO INOPERABLE. THE  
13 CHECK ENGINE WARNING LIGHT WAS ILLUMINATED. THE  
14 VEHICLE WAS TAKEN TO GUNTHER MAZDA (1800 S STATE  
15 RD 7, FORT LAUDERDALE, FL 33317, (954) 420-6565) WHERE  
16 IT WAS DIAGNOSED THAT THE BATTERY, A/C MOTOR AND  
17 AN UNKNOWN CONTROLLER NEEDED TO BE REPLACED.  
18 THE VEHICLE WAS REPAIRED SEVERAL TIMES HOWEVER,  
19 THE FAILURE RECURRED. THE MANUFACTURER WAS  
20 CONTACTED HOWEVER, NO FURTHER ASSISTANCE WAS  
21 PROVIDED. THE FAILURE MILEAGE WAS 2,000.<sup>50</sup>

17 122. On February 8, 2021, the owner of a 2017 Mazda CX-5 filed the  
18 following complaint with NHTSA:

19 LOSS OF POWER TO A COMPLETE SHUTDOWN WHILE AT  
20 HIGHWAY SPEEDS OF 60-70MPH WITH FUEL TANK  
21 READING 30 MILES TO EMPTY. TOW WAS NECESSARY TO  
22 DEALERSHIP. REPLACED FUEL PUMP. 2ND OCCURRENCE  
23 WITH 60 MILES TO EMPTY. BROKE DOWN AGAIN WHILE  
24 AT HIGHWAY SPEEDS. TOWED A SECOND TIME TO  
25 DEALERSHIP. REPLACE HIGH/LOW FUEL PUMP. WAS  
26 INSTRUCTED NOT TO OPERATE VEHICLE BELOW 1/4 TANK  
27 OF FUEL. MAJOR SAFETY ISSUE WHILE AT HIGHWAY

28 <sup>49</sup> NHTSA ID 11331647.

<sup>50</sup> NHTSA ID 11353214.

1 SPEEDS WITH DIFFICULTY MOVING TO A SAFE AREA.  
2 SEEMS TO BE A DESIGN OR FUEL PUMP ISSUE.<sup>51</sup>

3 123. On February 14, 2021, the owner of a 2017 Mazda6 filed the  
4 following complaint with NHTSA:

5 I BOUGHT MY 2017 MAZDA 6 BRAND NEW. WHILE THE CAR  
6 WAS IN WARRANTY IN JANUARY 2020 WHILE I WAS  
7 DRIVING WITH 50 MILES IN HOUR, THE ENGINE WAS  
8 RUNNING ROUGH, THE ENGINE LIGHT WAS ON AND THE  
9 ENGINE STALL. THE CAR WAS TOWED BY MAZDA AT  
10 DEALER. THEY REPLACED THE FUEL PUMP AT THAT TIME.  
11 FEW DAYS AGO WHILE I WAS DRIVING WITH 35 MILES IN  
12 HOUR THE CAR DID THE SAME THING. MAZDA TOWED  
13 THE CAR TO ANOTHER DEALER. AFTER DIAGNOSIS THEY  
14 TOLD ME THAT IS NOTHING WRONG WITH THE CAR AND  
15 THE CAR IS NOT UNDER THE WARRANTY ANYMOORE . I  
16 TOLD THEM THAT THE ENGINE LIGHT WAS ON AND  
17 SOMETHING MUST BE WRONG. THEY DIDN'T RESPOND.  
18 THE CAR HAS 24,000 MILES AND I AM AFRAID TO DRIVE IT  
19 ANYMORE.<sup>52</sup>

20 124. On April 13, 2021, the owner of a 2017 Mazda CX-5 filed the  
21 following complaint with NHTSA:

22 DRIVING ON EXPRESSWAY 65MPH WITH JUST UNDER A  
23 QUARTER TANK OF GAS AND ENGINE CUT OFF ON ITS  
24 OWN. MY SON WAS ABLE TO PULL OFF TO THE SIDE OF  
25 THE ROAD, BUT WAS VERY DANGEROUS AS IT WAS A  
26 VERY BUSY HIGHWAY. I FEEL THAT THE FUEL PUMP IS  
27 DEFECTIVE AT HIGHWAY SPEEDS. HAD VEHICLE  
28 IMMEDIATELY TOWED TO CLOSEST DEALER. I WAS  
29 CHARGED A DIAGNOSTIC FEE. AGAIN, I FEEL IT IS A WEAK  
30 DESIGN OF THE FUEL PUMP AND DANGEROUS TO DRIVE  
31 AT HIGHWAY SPEEDS.<sup>53</sup>

51 NHTSA ID 11395226.

52 NHTSA ID 11396179.

53 NHTSA ID 11407948.

1 125. On April 23, 2021, the owner of a 2013 Mazda CX-5 filed the  
2 following complaint with NHTSA:

3 WHILE DRIVING MY VEHICLE ON THE INTERSTATE THE  
4 CAR LOST THE ABILITY TO ACCELERATE. ALL OF THE  
5 DASHBOARD LIGHTS CAME ON AND I HAD TO COAST TO  
6 THE SIDE OF THE INTERSTATE. AFTER RESTARTING THE  
7 VEHICLE I WAS ABLE TO DRIVE IT BUT I CANNOT TAKE  
8 THE VEHICLE OVER 30 MPH NOW WITHOUT IT  
9 SHUTTERING AND HAVING ACCELERATION ISSUES. THIS  
10 IS A SERIOUS AND LIFE THREATENING ISSUE THAT NEEDS  
11 TO BE FIXED FREE OF CHARGE. I HAVE FOUND OTHER  
12 REPORTS OF THIS HAPPENING BUT I SEE NO RECALL  
13 INFORMATION. THIS NEEDS TO BE FIXED BEFORE MAZDA  
14 HAS LAWSUITS FILED AGAINST THEM. THIS IS A  
15 MANUFACTURING ERROR AND NOT A USAGE ERROR.  
16 PLEASE LOOK INTO THIS.<sup>54</sup>

13 126. On September 12, 2021, the owner of a 2018 Mazda CX-5 filed the  
14 following complaint with NHTSA:

15 WILL NOT ACCELERATE AT TIMES NO MATTER HOW FAR  
16 YOU PRESS DOWN ON GAS PEDAL AND WILL STALL RIGHT  
17 AFTER. I WILL PULL OVER SHUT OFF VEHICLE AND  
18 RESTART. THIS SOMETIMES CORRECTS THE PROBLEM  
19 RIGHT AWAY. OTHER TIMES IT LASTS LONGER. SYSTEM  
20 MALFUNCTION LIGHT RANDOMLY COMES ON.<sup>55</sup>

21 127. On May 9, 2019, the owners of a 2017 Fiat 124 Spider filed the  
22 following complaint with NHTSA:

23 VEHICLE WILL STALL WHILE DRIVING - TYPICALLY THE  
24 VEHICLE WILL DISPLAY THE ELECTRONIC THROTTLE  
25 CONTROL (ETC) WARNING LIGHT PRIOR TO STALL. STALL  
26 WILL HAPPEN WHILE ACTIVELY DRIVING. ENGINE  
27 INDICATOR LIGHT ALSO ILLUMINATES. DEALER HAS  
28 ATTEMPTED 5 TIMES TO CORRECT. EACH TIME THE  
DEALER DELIVERS VEHICLE. WITHIN 24 HOURS OF

54 NHTSA ID 11413591.

55 NHTSA ID 11432642.

1 DELIVERY, THE ENGINE AGAIN BEGINS TO HESITATE AND  
2 STALL, ETC AND CEL LIGHT COME ON.<sup>56</sup>

3 128. As demonstrated above, Class Vehicles suffer from a uniform defect  
4 that causes the Fuel Pump to malfunction and fail prematurely. Compounding the  
5 issue, drivers often are not protected from these safety risks by a warning prior to  
6 Fuel Pump failure. The above complaints are mere examples of the ones lodged  
7 with NHTSA regarding the Fuel Pump Defect. All the complaints above  
8 experienced symptoms associated with the Fuel Pump Defect.<sup>57</sup>

9 129. Mazda and FCA knew that the Fuel Pump Defect was present in all  
10 Class Vehicles equipped with the defective Denso Fuel Pump, as demonstrated  
11 above, but it failed to include them in the Recall. Mazda’s and FCA’s  
12 unconscionable act deprives those Class Members not included in the Recall a free  
13 and adequate repair, if one is devised and implemented.

14 130. As demonstrated, the Fuel Pump Defect affects all Class Vehicles,  
15 and not just the vehicles that were part of Mazda’s and FCA’s Recalls.  
16 Additionally, the Fuel Pump Defect creates an unreasonable risk of injury or death  
17 to Plaintiffs, Class Members, and others.

18 131. The Fuel Pump Defect causes Class Vehicles to become dangerous  
19 and inoperable while on the road and therefore they are not fit for their ordinary  
20 purpose.

21 **D. Defendants Knew About the Fuel Pump Defect, but Continued to  
22 Manufacture, Market, and Sell Class Vehicles**

23 132. Mazda and FCA knew, should have known, or were reckless in not  
24 knowing about the Fuel Pump Defect, but concealed or failed to disclose the defect  
25 and continued to manufacture, market, and sell its popular Class Vehicles—  
26 including the Recalled Vehicles—equipped with the defective Denso Fuel Pump.

27 \_\_\_\_\_  
28 <sup>56</sup> NHTSA ID 11217536

<sup>57</sup> See, e.g., Exhibits A and C.

1 Specifically, Mazda (and therefore FCA) knew, should have known, or was  
2 reckless in not knowing the defective Fuel Pumps in the Class Vehicles exposed  
3 Class Members to extreme danger and, in order to render them safe, the Class  
4 Vehicles needed new or enhanced Fuel Pumps that functioned safely and as  
5 intended. Nonetheless, Mazda and FCA failed to take corrective action.

6 133. In fact, Mazda (and therefore FCA) knew, should have known, or was  
7 reckless in not knowing about the Fuel Pump Defect since the pre-release process  
8 of designing, manufacturing, engineering, and testing the Class Vehicles.  
9 Specifically, Mazda conducts rigorous pre-production testing and validation.<sup>58</sup>  
10 Mazda and Denso conduct various pre-release testing, such as production part  
11 approval process (“PPAP”) testing and failure mode and effects analysis  
12 (“FMEA”) testing. During these phases, Mazda would have gained comprehensive  
13 and exclusive knowledge about the Fuel Pumps, particularly the basic engineering  
14 principles behind the construction and function of the Fuel Pumps such as their  
15 impellers’ susceptibility to fuel absorption and deformation. However, Mazda  
16 failed to act on that knowledge and instead installed the defective Fuel Pumps in  
17 the Class Vehicles, and Mazda subsequently marketed and sold the vehicles to  
18 unsuspecting consumers without disclosing the safety risk or warning Class  
19 Members.

20 134. Further, as set forth above, the TREAD Act requires automakers like  
21 Mazda and FCA to be in close contact with NHTSA regarding potential defects,  
22 and therefore Mazda and FCA should (and do) monitor NHTSA databases for  
23 consumer complaints regarding their automobiles. From its monitoring of the  
24 NHTSA databases, Mazda (and therefore FCA) knew or should have known of the  
25 many Fuel Pump Defect complaints lodged as early as 2017, such as those quoted  
26

27 <sup>58</sup> [http://suppliers.mazdausa.com/Library/Quality\\_Control\\_Standard\\_For](http://suppliers.mazdausa.com/Library/Quality_Control_Standard_For_Suppliers.pdf?bcs-agent-scanner=a38b7f22-f5b0-3443-829f-9a9ba5195bd0)  
28 [\\_Suppliers.pdf?bcs-agent-scanner=a38b7f22-f5b0-3443-829f-9a9ba5195bd0](http://suppliers.mazdausa.com/Library/Quality_Control_Standard_For_Suppliers.pdf?bcs-agent-scanner=a38b7f22-f5b0-3443-829f-9a9ba5195bd0)  
(last visited November 16, 2021).

1 above. However, Mazda and FCA failed to act on that knowledge by taking action,  
2 including recalling the vehicles with the Fuel Pump Defect.

3 135. Despite Mazda's and FCA's extensive knowledge, Mazda and FCA  
4 failed to act on that knowledge by warning Class Members. Sacrificing consumer  
5 safety for profits, Mazda and FCA instead chose to enrich itself by using false and  
6 misleading marketing to sell the Class Vehicles as safe and durable at inflated  
7 prices.

8 136. Like Mazda and FCA, Denso knew of the Fuel Pump Defect since  
9 long before it recalled its defective Fuel Pumps on April 27, 2020. Denso tells  
10 customers "[b]ecause DENSO's rigorous manufacturing and testing process  
11 produces each fuel pump, you can be sure it meets our high standards for fit and  
12 performance." As part of its rigorous testing of fuel pumps and its ongoing  
13 relationships with manufacturer customers, Denso knew or should have known  
14 about the Fuel Pump Defect months, if not years, before it initiated a recall on  
15 April 27, 2020.

16 137. Evidencing its extensive knowledge, Denso knew as early as 2016  
17 about the Fuel Pump Defect. In 2016, Denso filed a patent application with the  
18 United States Patent and Trademark Office to change the chemical composition of  
19 its impeller for greater resistance to swelling. As Denso stated in the application:

20 The housing includes an inner wall defining a pump chamber into  
21 which a fuel flows. The impeller is made of resin and housed in the  
22 housing. The impeller is positioned such that a clearance having a  
23 specified dimension is secured between the inner wall and the  
24 impeller. ***The impeller may be swelled due to the fuel and water  
25 contained in the fuel, therefore a rotation of the impeller may be  
26 stopped when the impeller is swelled and comes in contact with the  
27 housing.*** Thus, the dimension of the clearance is set to prevent the  
28 impeller from coming in contact with the housing. However, when  
the dimension of the clearance is too large, an abnormality, e.g., an  
increase of an output loss of the fuel pump or an increase of a power  
consumption of the fuel pump, may occur because the fuel leaks  
through the clearance. ***Therefore, it is required to find a resin***

1 *material to suppress a dimensional change of the impeller, which is*  
2 *mounted to the fuel pump, due to the fuel and the water contained*  
3 *in the fuel. The dimensional change will be referred to as a swelling*  
4 *amount hereinafter.*<sup>59</sup>

5 138. Denso’s knowledge of the Fuel Pump Defect reasonably predates the  
6 filing of the patent because Denso must have discovered the need for improved  
7 impeller material well before it filed the patent. Specifically, Denso must have  
8 learned of the Fuel Pump Defect since the original design, engineering, testing,  
9 and validation of the Fuel Pump and impeller, but at the very least from continued  
10 product improvement, testing, and validation of the Fuel Pump and impeller.

11 139. Thus, between 2016, when Denso first learned of the Fuel Pump  
12 Defect, and April 27, 2020, when Denso issued the recall to Mazda, FCA, and  
13 other automobile manufacturers, Denso had *exclusive* knowledge of the Fuel Pump  
14 Defect, and yet Denso failed to disclose the Defect to Plaintiffs and other Class  
15 Members.

16 140. Alternatively, Denso actively concealed, and continues to conceal,  
17 the Fuel Pump Defect. Denso long knew of the Fuel Pump Defect, but in order to  
18 capitalize its economic gains, it intentionally failed to disclose it to Mazda and  
19 FCA or the Class Members. The Fuel Pump Defect is a serious safety defect that  
20 places Plaintiffs and Class Members at an increased risk for injury or death, as  
21 Denso admitted.<sup>60</sup> Mazda, FCA, and Class Members did not know of the Fuel  
22 Pump Defect, and they couldn’t have discovered it through reasonable diligence.  
23 Plaintiff and other Class Members were damaged by Denso’s failure to disclose  
24 the Fuel Pump Defect, and had Denso disclosed it, they would not have purchased

25 \_\_\_\_\_  
26 <sup>59</sup> U.S. Patent Application No. 15767375, *Impeller for Fuel Pump*,  
27 (application date Oct. 26, 2016) (Denso Corporation, et al. applicants), *available*  
28 *at* <https://patentscope.wipo.int/search/en/detail.jsf?docId=US231859533> (last  
visited November 16, 2021).

<sup>60</sup> Exhibits A and B.



1 their Class Vehicles equipped with the Fuel Pump, or certainly would have paid  
2 less to do so.

3 141. Denso could have, but failed to, disclose the Fuel Pump Defect to  
4 Mazda and FCA. Additionally, Denso could have, but failed to, disclose the Fuel  
5 Pump Defect to Plaintiffs and the Class Members by publishing it on its website,  
6 issuing a press release, or issuing an equipment recall, like it ultimately did.

7 142. Defendants, at all material times, regularly met and collaborated, and  
8 continue to meet and collaborate, regarding product quality and trends. Through  
9 these regular discussions, each Defendant knew, should have known, or were  
10 reckless in not knowing what the other knew about the Fuel Pump Defect or the  
11 Fuel Pump in general.

12 143. Despite Defendants’ extensive knowledge, they failed to act on that  
13 knowledge by warning Class Members. Sacrificing consumer safety for profits,  
14 Defendants instead chose to enrich themselves by using false and misleading  
15 marketing to sell the Fuel Pumps and Class Vehicles as safe and durable at inflated  
16 prices.

17 **E. Defendants Continuously Touted Class Vehicles as Safe and**  
18 **Dependable, Concealing the Fuel Pump Defect**

19 144. Mazda’s overarching marketing message for the Class Vehicles was  
20 and is that the vehicles are safe and dependable and that their engines can be relied  
21 on to perform well. This marketing message is false and misleading given the  
22 propensity of the Fuel Pumps in the Class Vehicles to fail, causing the vehicles’  
23 engines to run rough, stall and become inoperable which, as Mazda admits, creates  
24 an unreasonable risk of a crash.


25 145. For example, Mazda dedicates a page on its website entitled “safety,”  
26 where Mazda touts the safety of its vehicles, as the screenshots below indicate:<sup>61</sup>

27 \_\_\_\_\_  
28 <sup>61</sup> <https://www.mazda.com/en/innovation/safety/> (last visited November 16, 2021).



FEELING SAFE GIVES YOU THE FREEDOM TO BE THE BEST DRIVER YOU CAN BE—TO CONCENTRATE ON ENJOYING THE ROAD AHEAD AND FEEL YOUR SPIRITS LIFTED BY THE EXPERIENCE OF DRIVING A MAZDA. THAT'S WHY WE FOCUS NOT JUST ON WHAT SAFETY PREVENTS, BUT ALSO ON WHAT IT MAKES POSSIBLE.

146. In addition to its general marketing message of safety, Mazda made representations specifically about the safety of the Class Vehicles. For example, below is a screen shot from a 2013 Mazda 3 sales brochure:<sup>62</sup>




<sup>62</sup> [https://www.auto-brochures.com/makes/Mazda/3/Mazda\\_US%203\\_2013-2.pdf?bcs-agent-scanner=d776a7d5-916f-ac4e-9b98-1cdb82e50896](https://www.auto-brochures.com/makes/Mazda/3/Mazda_US%203_2013-2.pdf?bcs-agent-scanner=d776a7d5-916f-ac4e-9b98-1cdb82e50896) (last visited November 16, 2021).

147. Below is a screenshot of a 2013 Mazda CX-5 sales brochure.<sup>63</sup>




148. Below is a screenshot of a 2013 Mazda CX-9 sales brochure.<sup>64</sup>



<sup>63</sup> [https://www.auto-brochures.com/makes/Mazda/CX-5/Mazda\\_US%20CX-5\\_2013.pdf?bcs-agent-scanner=5d482460-e068-8a4d-ae2a-7c36321cf6b9](https://www.auto-brochures.com/makes/Mazda/CX-5/Mazda_US%20CX-5_2013.pdf?bcs-agent-scanner=5d482460-e068-8a4d-ae2a-7c36321cf6b9) (last visited November 16, 2021).

<sup>64</sup> [https://www.auto-brochures.com/makes/Mazda/CX-9/Mazda\\_US%20CX-9\\_2013.pdf?bcs-agent-scanner=5d482460-e068-8a4d-ae2a-7c36321cf6b9](https://www.auto-brochures.com/makes/Mazda/CX-9/Mazda_US%20CX-9_2013.pdf?bcs-agent-scanner=5d482460-e068-8a4d-ae2a-7c36321cf6b9)

1 149. Mazda made similar representations throughout the class period. For  
2 example, below is a screenshot from a 2015 Mazda 6:<sup>65</sup>



26 9\_2013.pdf?bcs-agent-scanner=f45dcc28-1f67-5f4d-818f-a9316754d14a (last  
27 visited November 16, 2021).

28 <sup>65</sup> [https://www.auto-brochures.com/makes/Mazda/6/Mazda\\_US%206\\_2015.pdf?bcs-agent-scanner=](https://www.auto-brochures.com/makes/Mazda/6/Mazda_US%206_2015.pdf?bcs-agent-scanner=baf7882e-cd08-f847-8011-a373a291750b) baf7882e-cd08-f847-8011-a373a291750b (last visited November 16, 2021).

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

150. Below is a screenshot from a 2015 Mazda CX-5 sales brochure:<sup>66</sup>



151. Below is a screenshot from a 2016 Mazda CX-9 sales brochure:<sup>67</sup>

**i-ACTIVSENSE**

WITH THREE ROWS OF PRECIOUS CARGO, SAFETY MUST COME FIRST.

Driving is more enjoyable when your vehicle feels like a safe haven in a hectic world. The CX9's comprehensive suite of available i-ACTIVSENSE® safety features uses sophisticated technologies like lasers and radar to help you get a better sense of your surroundings, making you more aware of hazards—before they happen.

**ADVANCED BLIND SPOT MONITORING\***  
This available system uses radar sensors to detect objects in your left and right blind spots. When alert is on with a warning light appearing in the corresponding side mirror. If you signal a lane change while an object is there, the light flashes and a cabin warning chime sounds. On the CX9, the system is even advanced enough to alert you before a fast approaching vehicle enters your blind spot.

**SMART CITY BRAKE SUPPORT\***  
City driving offers its own treacherous obstacle courses. In order to help avoid or reduce the severity of a collision, select models offer Smart City Brake Support. When traveling at speeds between about 2 and 48 mph, this intuitive system detects objects ahead and prepares the vehicle by adjusting brake pads closer to the disc. If no other action is taken, the system automatically applies the brakes.

**SMART BRAKE SUPPORT\***  
Similar to Smart City Brake Support, this system can help avoid or reduce the severity of a collision at higher rates of speed (above 10 mph). Like freeway driving, this Collision Warning feature will alert the driver that braking is immediately necessary if the radar sensor determines that a collision is unavoidable, the automatic brake control will engage.

**REAR CROSS TRAFFIC ALERT\***  
When backing up, this available feature detects a vehicle approaching from the side and promptly alerts the driver with an audible warning, as well as a visual warning in either side mirror and on your center console display screen.

**ADAPTIVE FRONT-LIGHTING SYSTEM**  
Select models offer our Adaptive Front-lighting System. These headlights are specifically designed to help you see around corners at night. As you turn into a corner, the headlights pivot up to 75 degrees in the direction of your turn, improving visibility and allowing you to spot potential hazards and dangers ahead.

**HIGH BEAM CONTROL**  
Available High Beam Control keeps the driver see better at night by maximizing opportunities to use the high beams. The system automatically switches to low beams when it detects oncoming traffic and/or a vehicle ahead.

**LANE DEPARTURE WARNING SYSTEM\***  
This available system gives audible and visual warnings when the vehicle is about to unintentionally depart from its lane at a speed of 37 mph or higher.

**LANE KEEP ASSIST\***  
This available advanced safety system performs all the functions of the Lane Departure Warning System, and adds an extra level of guidance. When it senses a potential unintended lane departure, Lane Keep Assist will aid in steering your Mazda CX9 to guide it back to the center of the lane.

**DISTANCE RECOGNITION SUPPORT SYSTEM\***  
At speeds above 19 mph, this available feature uses radar technology to measure the distance between your Mazda and the vehicle ahead. Indicate by a recommended following distance. If your vehicle encroaches on this recommended distance, a visual warning shows in your Mazda's information display.

**MAZDA RADAR CRUISE CONTROL\***  
Simply press the vehicle speed and distance, and available Mazda Radar Cruise Control will work within a set speed range to help you maintain a safe distance between you and the preceding vehicle, down to 19 mph.

<sup>66</sup> [https://www.auto-brochures.com/makes/Mazda/CX-5/Mazda\\_US%20CX-5\\_2015.pdf?bcs-agent-scanner=f2c54917-1075-3140-8589-65c0f62d7123](https://www.auto-brochures.com/makes/Mazda/CX-5/Mazda_US%20CX-5_2015.pdf?bcs-agent-scanner=f2c54917-1075-3140-8589-65c0f62d7123) (last visited November 16, 2021).

<sup>67</sup> [https://www.auto-brochures.com/makes/Mazda/CX-9/Mazda\\_US%20CX-9\\_2016.pdf?bcs-agent-scanner=4185c797-05a6-134a-a57b-1048b28445f3](https://www.auto-brochures.com/makes/Mazda/CX-9/Mazda_US%20CX-9_2016.pdf?bcs-agent-scanner=4185c797-05a6-134a-a57b-1048b28445f3) (last visited November 16, 2021).



1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

154. Below is a screenshot from a 2019 Mazda CX-3 sales brochure:<sup>70</sup>



RESPONSIVE. AND RESPONSIBLE.  
SENSEMAP TECHNOLOGY enables us to anticipate what we believe to be the ideal driving experience. From the climate to the suspension, to the engine and beyond, we've designed every aspect of our cars to be powerful, yet efficient. SENSEMAP TECHNOLOGY also contributes the joy of driving with outstanding environmental and safety performance.

155. Below is a screenshot from a 2020 Mazda CX-5 sales brochure:<sup>71</sup>

CONFIDENCE WHEN YOU NEED IT MOST

With available i-Activ AWD<sup>SM</sup> the Mazda3 helps you drive confidently in the snow and rain, and improves performance on dry roads too. This innovative technology uses sophisticated real-time vehicle dynamic modeling to help predict traction loss and send torque to the tires that can use it best. Helping to maintain road grip—and your sense of confidence.

No matter what roads you're traveling, G-Vectoring Control Plus is always working in the background. By subtly adjusting the engine torque and braking pressure, this innovative technology makes the steering feel more natural, consistent and intuitive. The end result is an effortless connection between car and driver, so you're always ready for what's ahead.



The production Mazda3 i-Activ AWD shown with Premium Plus Package and accessories. Available July 2020.

<sup>70</sup> [https://www.auto-brochures.com/makes/Mazda/CX-3/Mazda\\_US%20CX-3\\_2019.pdf?bcs-agent-scanner=d8066cd4-2d75-8d4e-836f-c58ff7cda6bb](https://www.auto-brochures.com/makes/Mazda/CX-3/Mazda_US%20CX-3_2019.pdf?bcs-agent-scanner=d8066cd4-2d75-8d4e-836f-c58ff7cda6bb) (last visited November 16, 2021).

<sup>71</sup> [https://www.auto-brochures.com/makes/Mazda/CX-5/Mazda\\_US%20CX-5\\_2020.pdf?bcs-agent-scanner=abf98e0d-70f3-594d-b39b-6959141c6c42](https://www.auto-brochures.com/makes/Mazda/CX-5/Mazda_US%20CX-5_2020.pdf?bcs-agent-scanner=abf98e0d-70f3-594d-b39b-6959141c6c42) (last visited November 16, 2021).

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

156. Below is a screenshot from a 2021 Mazda 3 sales brochure:<sup>72</sup>



CONFIDENCE WHEN YOU NEED IT MOST

With available predictive i-Activ AWD<sup>®</sup> the Mazda CX-5 helps you drive confidently in the snow and rain, and improves performance on dry roads too. This advanced technology helps to detect the potential loss of traction by sensing everything from outside temperature to windshield wiper usage and the driver's steering inputs, then redistributing torque as needed to the tires that can use it best. To help maintain road grip—and your sense of confidence. When the destination takes you off the beaten path, simply press the Off-road Traction Assist control button (when equipped). Engaging this feature will help optimize torque distribution and traction control to help you traverse uneven terrain.

No matter what kind of road you're traveling, G-Vectoring Control Plus is always working in the background, subtly adjusting engine torque and braking pressure to make steering response feel more natural, consistent and intuitive. The end result is more confidence behind the wheel, and a more effortless connection between car and driver.

157. Like Mazda, FCA also brands itself as producing safe and reliable vehicles.

158. For example, in its sales brochure for the 124 Spider, FCA stated it is “literally a gift from above and the “Safety & Security” will “*create peace of mind*”.<sup>73</sup>

**THE TRUE SPORTS CAR IS BACK** With its thrilling airplane parachute-drop introduction at the Turin Auto Show in 1966, the original FIAT® 124 was literally a gift from above. It was an immediate sensation as 1967 European Car of the Year, and its Pininfarina design remains as fresh and relevant today as it was fifty years ago. Unlike most sports cars of the day, the 124 Spider interior was surprisingly roomy, and its advanced coil spring rear suspension, disc brakes and agile manner are why it remains a favorite among collectors. Today's all-new FIAT 124 Spider possesses talents in all those areas, but also the one underlying feature common to every 124 Spider: passion.

<sup>72</sup> [https://www.auto-brochures.com/makes/Mazda/3/Mazda\\_US%203\\_2021.pdf?bcs-agent-scanner=8f01e6c8-b227-094c-b800-8699e4696d19](https://www.auto-brochures.com/makes/Mazda/3/Mazda_US%203_2021.pdf?bcs-agent-scanner=8f01e6c8-b227-094c-b800-8699e4696d19) (last visited November 16, 2021).

<sup>73</sup> [https://www.fiatusa.com/assets/pdf/brochures/flat\\_124\\_spider.pdf](https://www.fiatusa.com/assets/pdf/brochures/flat_124_spider.pdf) (last visited November 22, 2021)



1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28



159. As demonstrated, Mazda and FCA employed and continues to employ a long term and uniform marketing message that its vehicles are of the utmost safety and dependability.

160. Despite Mazda’s and FCA’s knowledge and uniform and pervasive marketing message of safety and dependability, nowhere does Mazda and FCA disclose the Fuel Pump Defect or the unreasonable risk to safety it poses, as admitted in their Recalls.

161. A car with a defective fuel pump that can cause the engine to studder or stall while the vehicle is in motion, as do the Class Vehicles, and thereby exposes occupants to an unreasonable risk of injury or death *is not a safe car*. Thus, Mazda’s and FCA’s marketing of the Class Vehicles as safe and dependable

1 is false and misleading and omits facts that would be material to consumers such  
2 as Class Members who purchased or leased Class Vehicles because they were  
3 consistently marketed as having the utmost safety on the road.

4 162. Mazda and FCA marketed the Class Vehicles as safe and dependable,  
5 but failed to disclose the existence, impact, and danger of the Fuel Pump Defect,  
6 despite its knowledge. Specifically, Mazda and FCA:


- 7 a. Failed to disclose, at and after the time of purchase, lease,  
8 service, or thereafter, any and all known material defects of the  
9 Class Vehicles, including the Fuel Pump Defect, despite its  
10 knowledge;
- 11 b. Failed to disclose, at and after the time of purchase, lease,  
12 service, or thereafter, that the Class Vehicles' Fuel Pumps were  
13 defective and not fit for their ordinary purpose, despite its  
14 knowledge; and
- 15 c. Failed to disclose and actively concealed the existence and  
16 pervasiveness of the Fuel Pump Defect, despite its knowledge.

17 163. Mazda's and FCA's deceptive marketing and willful and knowing  
18 failure to disclose the Fuel Pump Defect damaged, and continues to damage,  
19 Plaintiff and Class Members. If Plaintiff and Class Members had known of the  
20 Fuel Pump Defect and/or that the Class Vehicles were not safe and durable, they  
21 would not have purchased or leased the Class Vehicles or certainly would have  
22 paid less to do so.

23 164. Moreover, Denso has also associated itself with safety and quality.  
24 On its website, Denso represented that it is committed to making high-quality  
25 products that contribute to a higher quality of life for all people.<sup>74</sup>  
26

27 \_\_\_\_\_  
28 <sup>74</sup> <https://www.denso.com/global/en/about-us/our-strengths/> (last visited  
March 1, 2021).

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28



**The pursuit of world firsts**

DENSO is committed to creating technologies that contribute to a better quality of life for all people. Our world-first advances range from common rail systems that dramatically improve diesel engine performance to night view technology that detects pedestrians at night.

165. Denso also stated that it focuses on “Meticulous quality control,” and that “DENSO focuses on safety because cars carry people.”<sup>75</sup>

**Manufacturing**

Innovative products and components can only be realized if they can be manufactured. At DENSO, our technicians and engineers painstakingly refine every detail of our manufacturing systems to enable the creation of the best technologies and products.



**Meticulous quality control**

DENSO focuses on safety because cars carry people. We were one of the first parts manufacturers to build our own test courses to evaluate our products, ensuring that people could confidently drive cars using our components. Our advanced test facilities are comparable with those of major carmakers and include such advances as high-low temperature wind tunnel laboratories and anechoic chambers that simulate the diverse conditions drivers encounter every day.

<sup>75</sup> *Id.*

1 166. In its corporate brochure, Denso stated that it seeks to create a world  
2 that is accident free, a goal that obviously cannot be reached when it produced the  
3 Fuel Pumps with the Fuel Pump Defect.<sup>76</sup>



4  
5  
6  
7  
8  
9  
10  
11  
12  
13 167. Additionally, on its aftermarket website, Denso stated its products are  
14 of high quality, reliable, and valuable.<sup>77</sup>



15  
16  
17  
18  
19 **Quality, Reliability and Value**

20 Quality, Reliability and Value. At DENSO we've taken everything we have learned as an OE manufacturer and applied it to our aftermarket product lines. Every component that  
21 leaves our factories has been designed with precision, manufactured to OE standards and subjected to rigorous safety and performance tests.

22 DENSO factories are QS9000 and ISO9000 certified worldwide, just one of the many reasons why zero defects for parts produced in the millions is a reality for DENSO. A recipient of  
23 the prestigious Deming Award for quality in 1961, we've spent over five decades perfecting our technology and processes, a claim that few automotive manufacturers can make.

24 The OE-standard quality and reliability of DENSO aftermarket components add up to a tremendous value for our customers.

25  
26 <sup>76</sup> [https://www.denso.com/global/en/-/media/global/about-us/corporate-](https://www.denso.com/global/en/-/media/global/about-us/corporate-info/profile/denso_brochure_en.pdf?rev=a5ed1a6eba404a0280d304810569c615)  
27 [info/profile/denso\\_brochure\\_en.pdf?rev=a5ed1a6eba404a0280d304810569c615](https://www.denso.com/global/en/-/media/global/about-us/corporate-info/profile/denso_brochure_en.pdf?rev=a5ed1a6eba404a0280d304810569c615)  
28 (last visited March 1, 2021).

<sup>77</sup> <https://densoautoparts.com/why-denso.aspx> (last visited March 1, 2021).

1 168. Denso made specific remarks about its Fuel Pumps, claiming “not all  
2 fuel pumps are created equal” and that its Fuel Pumps “offer more than triple the  
3 lifetime ....”<sup>78</sup>

4 169. Defendants marketed the Class Vehicles and Fuel Pumps as safe,  
5 dependable, and made of high-quality materials and innovation, but failed to  
6 disclose the existence, impact and danger of the Fuel Pump Defect and/or that the  
7 Class Vehicles were not safe or dependable. Specifically, Defendants:

- 8 a. Failed to disclose, at and after the time of purchase, lease,  
9 and/or service, any and all known material defects of the Class  
10 Vehicles, including the Fuel Pump Defect, despite its  
11 knowledge;
- 12 b. Failed to disclose, at and after the time of purchase, lease,  
13 and/or service, that the Class Vehicles’ Fuel Pumps were  
14 defective and not fit for their ordinary purpose, despite its  
15 knowledge; and
- 16 c. Failed to disclose and actively concealed the existence and  
17 pervasiveness of the Fuel Pump Defect, despite its knowledge.

18 170. Defendants’ deceptive marketing and willful and knowing failure to  
19 disclose the Fuel Pump Defect damaged, and continues to damage, Plaintiffs and  
20 Class Members. If Plaintiffs and Class Members had known of the Fuel Pump  
21 Defect and/or that the Class Vehicles were not safe and durable, they would not  
22 have purchased or leased the Class Vehicles or certainly would have paid less to  
23 do so.

24 ///  
25 ///  
26 ///

27  
28 <sup>78</sup> <https://densoautoparts.com/fuel-pumps.aspx> (last visited March 1, 2021).

1 **F. Defendants Admitted the Fuel Pump Defect Was Dangerously**  
2 **Defective, but Issued Inadequate Recalls**

3 171. Mazda’s Recall, initiated on November 12, 2021, covers 121,038  
4 vehicles with admittedly defective Fuel Pumps.<sup>79</sup> The root cause of Mazda’s  
5 Recall is a Denso Fuel Pump with a plastic impeller made of unsuitable material  
6 which deforms due to fuel absorption.

7 172. FCA’s Recall, initiated on November 12, 2021, covers 1,622 vehicles  
8 with admittedly defective Fuel Pumps.<sup>80</sup> Like Mazda’s Recall, FCA’s Recall is a  
9 Denso Fuel Pump with a plastic impeller made of unsuitable material which  
10 deforms due to fuel absorption.

11 173. However, Mazda’s and FCA’s Recalls are limited in scope and  
12 implements a woefully inadequate repair.

13 174. Specifically, Mazda’s and FCA’s Recalls fail to include older and  
14 newer model year vehicles equipped with the same defective Fuel Pump, as  
15 evidenced by the customer complaints submitted to NHTSA. *See supra.*

16 175. Additionally, Mazda’s and FCA’s Recalls fail to offer a timely and  
17 effective remedy for the Fuel Pump Defect. Although Mazda and FCA say they  
18 will replace the defective Fuel Pumps with improved ones, it fails to provide a  
19 timeline for such repairs, and, as described below, the repairs it will perform are  
20 inadequate and can lead to dangerous conditions.

21 176. Defendants’ supposed “remedy” for the Recalls fail to adequately  
22 remedy the Fuel Pump Defect. The proposed “fix” replaces *only* the fuel pump  
23 motor in the module instead of replacing the entire fuel pump module (the “Recall  
24 Repair”) as is the industry norm. Because of the risk of damage to the entire fuel  
25 pump module if only the fuel pump motor is removed and replaced, it is industry  
26 standard to replace the *entire* fuel pump module. Contrary to industry practice, the

27 \_\_\_\_\_  
28 <sup>79</sup> Exhibit E.  
<sup>80</sup> Exhibit G.

1 Recall Repair replaces only the *motor*, placing Plaintiffs and the Class at an  
2 increased risk of experiencing additional hazardous conditions as a result of  
3 technician error or due to degradation of other components of the fuel pump  
4 module.


5 177. Upon information and belief, the Recall Repair originated from  
6 Denso, the manufacturer of the defective fuel pumps that gave rise to Mazda's and  
7 FCA's Recalls. Denso sells its fuel pumps to automobile manufacturers as part of  
8 a fuel pump module. In a cost-savings effort, Denso provided only the defective  
9 fuel pump *motor*, and not the entire fuel pump *module*, for the Recall Repair  
10 despite knowing that industry norms would require the replacement of the entire  
11 fuel pump module to adequately remedy the Fuel Pump Defect (assuming, of  
12 course, that the new fuel pump assembly functioned properly). Mazda and FCA,  
13 fully aware that this 2020 Recall Repair would be entirely inadequate, and indeed  
14 would risk causing further damage to the fuel pump module and other component  
15 parts, decided to implement this insufficient remedy because it, like Denso, did not  
16 want to incur the costs of providing entire fuel pump modules, which would be  
17 more expensive than swapping out the fuel pump motors in the fuel pump modules  
18 in the Recalled Vehicles. Thus, Denso, Mazda, and FCA are equally responsible  
19 for the inadequate Recall Repair and share equal blame for the potential hazards it  
20 presents.

21 178. The Recall Repair involves both the Fuel Pump and the fuel pump  
22 module, which houses the fuel pump. The Fuel Pump (i.e., the electric motor and  
23 impeller) is an internal component of the fuel pump module. The fuel pump  
24 module is a complete package, hosting the pump, associated plumbing and the fuel  
25 gauge sending unit. Figure 6 below is a photograph of the Denso fuel pump module  
26 used in Class Vehicles.


27

28

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28



179. As Figure 7 below demonstrates, the fuel pump module drops into the fuel tank through an access hole on the topside of the tank. A retainer ring ensures that the flange and O-ring create a tight seal against the tank surface, preventing fuel escape.





1 180. Figure 8 below depicts the component parts of a Denso fuel pump  
2 module.




13  
14 181. The fuel pump module's housing protects the fragile internal  
15 components that fit together like puzzle pieces within the module.

16 182. As Figures 9 and 10 below demonstrate, the Denso fuel pump module  
17 is held together with plastic tabs and clips.



1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28



183. Fuel exposure weakens these plastic tabs and clips depleting durability and elasticity.

184. As Figure 11 below demonstrates, the fuel pump modules contain numerous small and fragile parts, such as O-rings, that require precise installation. Disassembling the fuel pump module exposes these critical components to contamination, dislocation and breakage, thereby affecting vehicle performance.



185. Because of these concerns (and others), it is industry standard to replace the fuel pump module as a complete unit rather than remove and replace

1 discrete failed internal components. Replacing the fuel pump module as a complete  
2 unit greatly reduces technician error frequency.

3 186. However, as Mazda, FCA, and Denso ignored industry norms and  
4 instruct technicians to disassemble the fuel pump module to replace the fuel pump  
5 (i.e., the electric motor and impeller) when performing the “remedy” under the  
6 Recall Repair. Rather than replace the entire fuel pump module, Mazda’s and  
7 FCA’s Recalls direct technicians to replace only the fuel pump motor, an  
8 extremely delicate process requiring the technician to disassemble the fuel pump  
9 module, remove the motor, replace the old motor with a new one, and then  
10 reassemble the fuel pump module. This process involves bending tabs and clips,  
11 which in turn invite hairline cracks, breakage and incomplete catching of the tabs  
12 and clips that hold the fuel pump module together. These common and likely labor  
13 errors create seal failure and resultant fuel leaks and/or fuel pressure loss due to  
14 cavitation<sup>81</sup> or recycling of fuel.

15 187. Mazda’s and FCA’s Recall Repair not only deviates from industry  
16 norms, but it also departs from Mazda’s and FCA’s typical practice. For example,  
17 outside of this Recall, customers who bring their vehicles to a technician for fuel  
18 pump repair typically receive a new fuel pump module. Specifically, recycling of  
19 original fuel pump module parts does not occur outside of this Recall.

20 188. Mazda’s and FCA’s Recall Repair is inadequate because it also places  
21 Plaintiffs and Class Members in harm’s way. Rather than replacing the affected  
22 fuel pump module with a new fuel pump module, Mazda and FCA opted for  
23 maximizing its profits over consumer safety. Plaintiffs and Class Members whose  
24

25 \_\_\_\_\_  
26 <sup>81</sup> Cavitation is a phenomenon in which rapid changes of pressure in a liquid  
27 lead to the formation of small vapor-filled cavities in places where the pressure is  
28 relatively low. When subjected to higher pressure, these cavities, called “bubbles”  
or “voids,” collapse and can generate a shock wave that strong enough to damage  
component parts.

1 vehicles received the Recall Repair drive their Vehicles under the false assumption  
2 that their vehicles were adequately repaired.

3 189. The inadequacy of the Recall Repair is further demonstrated by the  
4 complaints from consumers who own Toyota, Honda, or Subaru vehicles<sup>82</sup> that  
5 continued to experience the Fuel Pump Defect *after* receiving the Recall Repair.

6 190. For example, on September 18, 2020, the owner of a 2019 Honda  
7 Civic submitted a complaint to NHTSA stating that he or she experienced a  
8 concerning stall and loss of motive power *after* the Recall Repair was performed  
9 on the vehicle:

10 TL\* THE CONTACT OWNS A 2019 HONDA CIVIC. THE  
11 CONTACT STATED WHILE DRIVING AT VARIOUS SPEEDS,  
12 THE VEHICLE JERKED, LOSS MOTIVE POWER, SWITCHED  
13 TO LIMP MODE WITH THE CHECK ENGINE WARNING  
14 LIGHT ILLUMINATED. THE CONTACT STATED THAT THE  
15 VEHICLE FAILED TO PROPERLY ACCELERATE WHILE IN  
16 LIMP MODE. AFTER STOPPING THE VEHICLE, THE CHECK  
17 ENGINGE WARNING LIGHT DISAPPEARED AND THE  
18 VEHICLE OPERATED NORMALLY. THE VEHICLE WAS  
19 TAKEN TO THE LOCAL DEALERS AUTONATION MAZDA  
20 LOCATED AT 23551 MAGIC MOUNTAIN PKWY, VALENCIA,  
21 CA 91355, TO BE DIAGNOSED. THE CONTACT WAS  
22 INFORMED THAT THE FAILURE WAS CAUSED BY  
23 CONTAMINATED FUEL. AFTER DRAINING THE FUEL  
24 SYSTEM, THE CONTACT RETRIEVED THE VEHICLE  
25 HOWEVER, THE FAILURE RECURRED. THE  
26 MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE  
27 CONTACT INDICATED THAT THE FAILURE OCCURRED  
28 AFTER THE VEHICLE WAS REPAIRED UNDER NHTSA  
CAMPAIGN NUMBER: 203V314000 (FUEL SYSTEM,  
GASOLINE) IN JULY 2020. THE FAILURE MILEAGE WAS  
29,000.<sup>83</sup>

82 Denso supplied the same or substantially similar defective fuel pumps to  
Toyota, Honda, and Subaru, each of whom implemented the same or substantially  
similar inadequate repair.

83 NHTSA COMPLAINT ID No. 11359797.

1 191. In a particularly terrifying example, on August 30, 2020, the owner  
2 of a 2018 Honda HR-V reported to NHTSA that after initially being told the  
3 necessary part was unavailable, he or she ultimately obtained the 2020 Recall  
4 Repair only to immediately experience the overpowering smell of gasoline from a  
5 gas tank leak that the dealership was unable to remedy, rendering the vehicle  
6 completely unsafe and unfit to drive:

7 RCVD RECALL NOTICE AT END OF JULY FOR FUEL PUMP  
8 MODULE WITHOUT SPECIFICATION IMPELLERS.  
9 OVERTIME THESE IMPELLERS MAY ABSORB AN  
10 EXCESSIVE AMOUNT OF FUEL AND DEFORM. A  
11 DEFORMED IMPELLER MAY CAUSE THE FUEL PUMP TO  
12 STOP WORKING.

13 DID NOT RECEIVE NOTIFICATION UNTIL THE END OF JULY  
14 2020 WHEN THE RECALL WAS SET IN MAY 2020. DEALER  
15 WHERE I PURCHASED VEHICLE WAS UNAWARE OF THE  
16 RECALL AND CHECKED IN THE BEGINNING OF AUGUST  
17 SAYING THE PARTS WERE NOT YET RELEASED BY  
18 MAZDA.

19 FINALLY, ON 8/26/20 I CONTACTED CORPROATE WHO  
20 INDICATED THAT THE PART HAD BEEN RELEASED A FEW  
21 WEEKS PRIOR.

22 DEALER PUT IN A NEW FUEL PUMP WHICH APPARENTLY  
23 FIXES THE PROBLEM BUT UPON PICKING IT UP THE INSIDE  
24 OF THE VEHICLE SMELLED VERY STRONG OF GASOLINE.  
25 THE MAZDA MECHANIC REASSURED IT WAS JUST FUMES  
26 FROM THE REPAIR SINCE THEY ACCESS PUMP TO THE  
27 FUEL TANK FROM INSIDE THE VEHICLE. HOWEVER, ON  
28 THE ROUGHLY 20 MILE RIDE HOME THE SMELL OF  
GASOLINE GOT WORSE SO MUCH THAT WE HAD TO ROLL  
THE WINDOWS DOWN BECAUSE WE WERE GETTING A  
HEADACHE AND OVER TAKEN BY THE GASOLINE SMELL.  
WE STOPPED AT A GAS STATION TO FILL THE VEHICLE  
TANK WHICH WAS DOWN TO ABOUT ¼ TANK.

WHEN THE GAS ATTENDANT FILLED THE TANK ALL THE  
GAS STARTED LEAKING OUT FROM UNDER THE CAR. CAR  
WAS PUSHED AWAY FROM THE PUMP. GAS CONTINUED  
TO POUR FROM UNDERNEATH AS A STEADY STREAM  
THEN AFTER ABOUT A HALF HOUR TO A DRIP. VEHICLE  
WAS TOWED BACK TO DEALER WHO THE NEXT DAY

1 THOUGHT THE WING NUT TO HOLD THE PUMP GASKET  
2 LOOSENED AND ASSURED IT WAS FIXED. THEY FILLED TH  
3 THANK DROVE IT, SAID IT WAS FINE. I LEFT IT  
4 OVERNIGHT, AND THE NEXT DAY THEY CHECKED THE  
5 VEHICLE AND SAW GASOLINE STILL LEAKING OUT FROM  
6 AN UNDETERMINED AREA UNDER THE VEHICLE. WHY  
7 WAS THE PART NOT RELEASED FOR SO LONG? MAZDA  
8 REPAIR GARAGE HAS NOT YET DETERMINED WHERE THE  
9 LEAK IS AND WHAT IS DEFECTIVE AT THE TIME THIS IS  
10 WRITTEN 3 DAYS AFTER THE RECALL REPAIR.<sup>84</sup>

11 192. In another example of the Recall Repair creating more problems than  
12 it solves, on October 6, 2020 the owner of 2018 Honda HR-V reported to NHTSA  
13 that after having the 2020 Recall Repair performed on his or her vehicle parking  
14 light and check warning lights remained illuminated:

15 TL\* THE CONTACT OWNS A 2018 MAZDA HR-V. THE  
16 CONTACT STATED THAT WHILE OPERATING THE  
17 VEHICLE, THE PARKING LIGHT AND CHECK ENGINE  
18 WARNING LIGHTS REMAINED ILLUMINATED. THE  
19 VEHICLE WAS TAKEN TO THE LOCAL DEALER POHANKA  
20 MAZDA LOCATED AT 1772 RITCHIE STATION CT, CAPITOL  
21 HEIGHTS, MD 20743 WHO DIAGNOSED THE VEHICLE AND  
22 INFORMED THE CONTACT THAT THE FAILURES WERE  
23 RELATED TO A PREVIOUS REPAIR PERFORMED UNDER  
24 THE NHTSA CAMPAIGN NUMBER: 20V314000 (FUEL  
25 SYSTEM). NO FURTHER INFORMATION WAS AVAILABLE.  
26 THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER  
27 WAS NOTIFIED OF THE FAILURES. THE FAILURE MILEAGE  
28 WAS 33,000.<sup>85</sup>

193. On January 29, 2021, the owner of a 2019 Honda Insight filed the  
following complaint with NHTSA, reporting subsequent fuel pump issues after  
receiving the Recall repair:

FUEL PUMP REPLACED IN 10/2020 FOR RECALL 20V314000.  
IN 1/2021 I WAS PASSING A VEHICLE ON THE INTERSTATE  
WHEN THE CHECK ENGINE LIGHT STARTED FLASHING,  
THE VEHICLE STARTED BUCKING, AND I LOST

<sup>84</sup> NHTSA Complaint ID No. 11352182.

<sup>85</sup> NHTSA Complaint ID No 11363047.

1 ACCELERATION. AFTER SHUTTING OFF THE CAR FOR A  
 2 FEW MINUTES I WAS ABLE TO CONTINUE DRIVING AT  
 3 INTERSTATE SPEEDS. A LOCAL SHOP READ THE CODE  
 4 AND REPORTED A MISFIRE ON CYLINDERS 3 AND 4.  
 5 MAZDA TECHNICIANS COULDN'T RECREATE THE ISSUE  
 6 OR VIEW ANY CODE HISTORY, BUT DURING A TEST DRIVE  
 7 FOUND THAT THE FUEL GAUGE HAD STOPPED  
 8 FUNCTIONING. UPON INSPECTION OF THE PREVIOUSLY  
 9 REPLACED FUEL PUMP IT WAS DISCOVERED THAT THE  
 10 WIRES WERE CRUMBLING.  
 11 THE FUEL PUMP INSTALLED DURING A RECALL CAUSED  
 12 THE EXACT ISSUE IT WAS SUPPOSED TO AVOID. THE  
 13 SERVICE ADVISOR QUOTED SOMEONE AT MAZDA AS  
 14 SAYING THEY'VE SEEN A FEW OF THESE ISSUES COME  
 15 BACK AFTER THE INITIAL RECALL.<sup>86</sup>

16 194. On July 25, 2020, a consumer with a 2019 Toyota Highlander filed  
 17 the following complaint with NHTSA:

18 The contact owns a 2019 Toyota Highlander. The contact stated that  
 19 while attempting to accelerate from a standing start the vehicle would  
 20 suddenly accelerate and immediately hesitate before accelerating and  
 21 operating as normal. The failure had occurred on 2 separate  
 22 occasions. *The contact indicated that the failure had occurred after*  
 23 *the recall remedy was performed for the NHTSA recall campaign*  
 24 *number 20V012000(fuel system). The cause of the failure was not*  
 25 *yet determined. The dealer ... [a]nd the manufacturer were notified*  
 26 *of the failure. The failure mileage was 30,078<sup>87</sup>*

27 195. On July 2, 2020, a consumer with a 2019 Toyota Highlander filed the  
 28 following complaint with NHTSA:

TI\* the contact owns a 2019 Toyota Highlander. The contact received  
 notification of NHTSA campaign number: 20v012000 (fuel system,  
 gasoline) ... An unknown dealer was contacted and confirmed that  
 parts were available. The manufacturer was made aware of the issue.  
 The contact had experienced a failure. VIN tool confirms parts were  
 available. \*bf

86 NHTSA ID No. 11394766.

87 NHTSA Complaint ID No. 11342099 (emphasis added).

1 **Consumer stated fuel pump was replaced but the jarring of the**  
2 **vehicle happened 2 more times.\*jb<sup>88</sup>**

3 196. On July 20, 2020, a consumer with a 2018 Toyota Camry filed the  
4 following complaint with NHTSA:

5 TI\* the contact owns a 2018 Toyota Camry. **The contact stated that**  
6 **the vehicle was serviced under NHTSA campaign number:**  
7 **20v012000 (fuel system, gasoline) .... After retrieving the vehicle,**  
8 **the contact stated that there was an abnormal fuel odor coming**  
9 **from the rear of the vehicle.** The same dealer was contacted and  
10 informed of the issue. The contact was referred to the manufacturer  
11 to file a complaint. The manufacturer was informed of the failure and  
12 a case was filed. The failure mileage was approximately 8,000.<sup>89</sup>

13 197. On August 24, 2020, a consumer with a 2018 Toyota Corolla filed  
14 the following complaint with NHTSA:

15 TL the contact owns a 2018 Toyota Corolla. The contact received  
16 notification of NHTSA campaign numbers: 20V024000 (air bags)  
17 and 20V012000 (fuel system, gasoline). **The vehicle was taken to the**  
18 **Toyota of Bowie dealer located at 16700 governor bridge rd, bowie,**  
19 **md 20716, where the recalls were repaired. The contact stated after**  
20 **the repairs, she started feeling dizzy and nauseated, having**  
21 **migraine headaches.** The dealer was called back and the technician  
22 was unable to detect the cause of the issue. The contact purchased an  
23 air quality detector and detected a VOC (volatile organic compound)  
24 of.975mg (within 15 minutes of running the vehicle) which was over  
25 EPA recommendation. The manufacturer was made aware of the  
26 failure and was told that someone would call back. The contact was  
27 not called back. The vehicle was not repaired. The failure mileage  
28 was approximately 60,000.<sup>90</sup>

198. On September 8, 2020, a consumer with a 2019 Toyota Highlander  
filed the following complaint with NHTSA:

Gas spilling after fuel pump recall\*\*\*  
Ever since fuel pump recall was done on 08/15/2020, the car is  
leaving me in a dangerous situation when I fill my gas tank in the gas  
station and it's spilling out gas even after the pump nozzle cuts off.

88 NHTSA Complaint ID No. 11337213 (emphasis added).

89 NHTSA Complaint ID No. 11340410 (emphasis added).

90 NHTSA Complaint ID No. 11351018 (emphasis added).



1 This happened twice ( actually 3 times) *and started only after this*  
2 *recall was done.*

3 Last night (9/6/2020) when I was filling gas in a gas station about 50  
4 miles from home, it did sprayout/spilled a large amount of gas ( almost half gallon ) into the ground leaving me in an extremely  
5 dangerous situation. So I drove back to where I live and went into a  
6 Sonoco to confirm the issue. This time the gas got spilled even after  
7 the pump nozzle cut off and stopped pumping. Almost a quarter  
8 gallon gas spilled out.

9 When it happened for the first time on August 24th (08/24/2020)  
10 *when I filled the gas for the first time after this recall I didn't quite*  
11 *realize what was going on and for sure it was my car. After filling*  
12 *the gas tank in the gas station I felt my shoes were sleepy and I*  
13 *could feel gas on the ground. Next day morning I started smelling*  
14 *gas and went to see the back of the car and I could see some drops.*  
15 *Apparently that was liquid gas dropping off being the tank still*  
16 *full.*<sup>91</sup>

17 199. These complaints filed with NHTSA are mere examples of the vast  
18 number of consumers experiencing the Fuel Pump Defect and left without an  
19 adequate recall remedy.

20 200. Therefore, Mazda's and FCA's Recall is inadequate and  
21 unconscionable. Mazda and FCA failed to promptly alert Class Members to the  
22 admittedly dangerous Fuel Pump Defect and provide them with a safe alternative,  
23 which inevitably will lead to more Fuel Pump failures, and possibly injury or  
24 death. Mazda and FCA failed to adequately diagnose and repair the Fuel Pump  
25 Defect, which inevitably will lead to more Fuel Pump failures, and possibly injury  
26 or death. Egregiously, Mazda's and FCA's Recalls are not only an inadequate  
27 remedy for the Fuel Pump Defect, it carries a substantial risk of causing *additional*  
28 damage to the fuel pump module and the Vehicle. Moreover, both Recalls are also  
inadequate in scope, older and newer models equipped with the same defective  
Fuel Pump.

<sup>91</sup> NHTSA Complaint ID No. 11353590 (emphasis added).

1 201. Mazda’s and FCA’s actions are deceitful, unconscionable, and  
2 expose Class Members to injury and death. In addition to these dangers, Mazda’s  
3 and FCA’s actions have deprived purchasers and lessees of the Class Vehicles of  
4 the benefit of their bargain.

5 202. Moreover, even though Denso’s Recall is broader than Mazda’s and  
6 FCA’s, it too fails to include all defective low-pressure Fuel Pumps. Denso states  
7 the affected population of Fuel Pumps was manufactured between September 1,  
8 2017 and October 6, 2018. However, reports of faulty Fuel Pumps and problems  
9 associated with inoperative Fuel Pumps, such as vehicles stalling while driving,  
10 have been made by owners and lessees to NHTSA dating back to 2015, or earlier.  
11 Additionally, at least one other manufacturer that uses Denso’s Fuel Pumps has  
12 recalled vehicles made as early as 2013 for the same Fuel Pump Defect involving  
13 Denso low pressure Fuel Pumps that were made with a lower density. Denso’s  
14 failure to timely, reasonably, and adequately identify the scope of the affected Fuel  
15 Pumps is unfair and unconscionable and exposes Plaintiffs and Class Members to  
16 extreme injury or even death.

17 **G. Applicable Warranties**

18 203. Mazda and FCA sold and leased the Class Vehicles with written  
19 express warranties.

20 204. Mazda offered a written express basic warranty covering Mazda  
21 brand vehicles for 36 months or 36,000 miles covering all components (except  
22 normal wear and tear).<sup>92</sup> Mazda also offered a 60 month or 60,000-mile powertrain  
23 warranty, which covers the Fuel Pump.<sup>93</sup>

24 205. FCA offered a written express four year or 50,000 mile power train  
25 warranty, which covers the Fuel Pump.

27 <sup>92</sup> <https://www.mazdausa.com/owners/warranty> (last visited November 15,  
28 2021).

<sup>93</sup> *Id.*

1           206. Mazda and FCA provide these warranties to buyers and lessees after  
2 the purchase/lease of the Class Vehicles is completed; buyers and lessees have no  
3 pre-sale/lease knowledge or ability to bargain as to the terms of the warranties.

4           207. However, Mazda and FCA admitted a breach of these warranties in  
5 the Recall Report when it reported it did not have a repair or remedy for the  
6 defective Fuel Pump. Class Members complained to dealers about the Fuel Pump  
7 Defect but did not receive an adequate repair, breaching the express and implied  
8 warranties provided by Mazda.

9           **H. Defendants Had Notice of the Defect Throughout the Relevant**  
10           **Period**

11           208. As alleged herein, the Fuel Pump Defect is a serious safety defect that  
12 Mazda has failed to repair, thus rendering the satisfaction of notice requirement  
13 futile. For example, several Plaintiffs have presented their vehicle for repair or  
14 inquired into the Recall repair only to be turned away and left waiting.

15           209. In addition to other forms of notice alleged herein, Mazda and FCA  
16 have notice of the Fuel Pump Defect by way of the numerous complaints filed  
17 against it directly and through its dealers, as well as complaints submitted to  
18 NHTSA and other forums, which, upon information and belief, it monitors. Mazda  
19 and FCA also have notice of the Fuel Pump Defect from the thousands of warranty  
20 claims it admitted to receiving in relation to the Fuel Pump Defect.

21           210. Moreover, as alleged in more detail herein, Mazda and FCA had  
22 notice when Plaintiffs presented their vehicles to Mazda for repair but were  
23 subsequently denied.

24           211. Finally, considering the allegations Plaintiffs set forth herein and  
25 Mazda's and FCA's inability to remedy the Fuel Pump Defect, the remedies  
26 available under any informal settlement procedure would be inadequate, and any  
27 requirement that Plaintiffs and the Class Members resort to an informal dispute  
28 resolution procedure and/or afford Mazda or FCA a reasonable opportunity to cure

1 its breach of warranties (when it is currently unable to do so) is excused and thus  
2 deemed satisfied.

3 **V. FRAUDULENT OMISSION/CONCEALMENT ALLEGATIONS**

4 212. Absent discovery, Plaintiff is unaware of, and unable through  
5 reasonable investigation to obtain, the true names and identities of those  
6 individuals at Mazda, FCA, and Denso responsible for making false and  
7 misleading statements regarding the Class Vehicles. Mazda, FCA, and Denso  
8 necessarily are in possession of all of this information. Plaintiffs' claims arise out  
9 of Defendants' fraudulent omission/concealment of the Fuel Pump Defect, despite  
10 their representations about the quality, safety, and comfort of the Class Vehicles.

11 213. Plaintiffs allege that at all relevant times, including specifically at the  
12 time they and Class Members purchased their Class Vehicle, Defendants knew, or  
13 were reckless in not knowing, of the Fuel Pump Defect; Defendants had a duty to  
14 disclose the Fuel Pump Defect based upon their exclusive knowledge; and  
15 Defendants never disclosed the Fuel Pump Defect to Plaintiffs or the public at any  
16 time or place in any manner other than a halfhearted, inadequate recall of a subset  
17 of the Class Vehicles.

18 214. Plaintiffs make the following specific concealment/omission-based  
19 allegations with as much specificity as possible absent access to the information  
20 necessarily available only to Defendants:

21 a. **Who:** Defendants actively concealed and omitted the Fuel  
22 Pump Defect from Plaintiffs and Class Members while  
23 simultaneously touting the safety and dependability of the  
24 Class Vehicles, as alleged herein. Plaintiffs are unaware of,  
25 and therefore unable to identify, the true names and identities  
26 of those specific individuals at Defendants responsible for  
27 such decisions.

28

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

- b. **What:** Defendants knew, or were reckless or negligent in not knowing, that the Class Vehicles contain the Fuel Pump Defect, as alleged herein. Defendants concealed and omitted the Fuel Pump Defect while making representations about the safety, dependability, and other attributes of the Class Vehicles, as alleged herein.
- c. **When:** Defendants concealed and omitted material information regarding the Fuel Pump Defect at all times while making representations about the safety and dependability of the Class Vehicles on an ongoing basis, and continuing to this day, as alleged herein. Defendants still have not disclosed the truth about the full scope of the Fuel Pump Defect in the Class Vehicles to anyone outside of their respective entities. Defendants have never taken any action to inform consumers about the true nature of the Fuel Pump Defect in Class Vehicles. And when consumers brought their vehicles to Mazda complaining of the Fuel Pump failures, Mazda denied any knowledge of or repair for the Fuel Pump Defect.
- d. **Where:** Defendants concealed and omitted material information regarding the true nature of the Fuel Pump Defect in every communication they had with Plaintiffs and Class Members and made representations about the quality, safety, and comfort of the Class Vehicles. Plaintiffs are aware of no document, communication, or other place or thing, in which Defendants disclosed the truth about the full scope of the Fuel Pump Defect in the Class Vehicles to anyone outside of their respective entities. Such information is not adequately disclosed in any sales documents, displays, advertisements,

1 warranties, owner’s manuals, or on Defendants’ websites.  
2 There are channels through which Defendants could have  
3 disclosed the Fuel Pump Defect, including but not limited to,  
4 (1) point of sale communications; (2) the owner’s manual;  
5 and/or (3) direct communication to Class Members through  
6 means such as state vehicle registry lists.

7 e. **How:** Defendants concealed and omitted the Fuel Pump  
8 Defect from Plaintiffs and Class Members and made  
9 representations about the quality, safety, dependability, and  
10 comfort of the Class Vehicles. Defendants actively concealed  
11 and omitted the truth about the existence, scope, and nature of  
12 the Fuel Pump Defect from Plaintiffs and Class Members at  
13 all times, even though it knew about the Fuel Pump Defect and  
14 knew that information about the Fuel Pump Defect would be  
15 important to a reasonable consumer, and Defendants promised  
16 in its marketing materials that Class Vehicles have qualities  
17 that they do not have.

18 f. **Why:** Defendants actively concealed and omitted material  
19 information about the Fuel Pump Defect in the Class Vehicles  
20 for the purpose of inducing Plaintiffs and Class Members to  
21 purchase and/or lease Class Vehicles, rather than purchasing  
22 or leasing competitors’ vehicles, and made representations  
23 about the quality, safety, durability, and comfort of the Class  
24 Vehicles. Had Defendants disclosed the truth, for example in  
25 its advertisements or other materials or communications,  
26 Plaintiffs and Class Members (all reasonable consumers)  
27 would have been aware of it, and would not have bought or  
28

1 leased the Class Vehicles or would not have paid as much for  
2 them.

3 **VI. TOLLING OF STATUTE OF LIMITATIONS**

4 **A. Continuing Tolling Act**

5 215. Beginning in 2013, Mazda and FCA continuously marketed and sold  
6 Class Vehicles with the defective Fuel Pumps to unsuspecting customers. Mazda  
7 and FCA continuously represented the Class Vehicles as safe and dependable  
8 despite their propensity to lose fuel pressure, hesitate under acceleration and/or  
9 experience engine shutdown. Denso, the manufacturer of the defective Fuel  
10 Pumps, continuously marketed and sold the Fuel Pumps as safe and dependable  
11 despite knowing their impellers could deform due to excessive fuel absorption. By  
12 making these false representations, and failing to disclose the existence of the Fuel  
13 Pump Defect in the Class Vehicles and thereby exposing occupants to risk of injury  
14 and death, Defendants engaged in a continuing wrong sufficient to render  
15 inapplicable any statute of limitations that Mazda and FCA might seek to apply.

16 216. Pursuant to the TREAD Act, 49 U.S.C. § 30118, automobile  
17 manufacturers are required to report information regarding customer complaints  
18 and warranty claims to NHTSA, and federal law imposes criminal penalties  
19 against manufacturers who fail to disclose known safety defects. Mazda and FCA  
20 owed a continuing duty to Plaintiffs and Class Members to disclose to any risks to  
21 life and limb that its products pose. They continually breached that duty.

22 217. Mazda and FCA breached their duties to consumers by knowingly  
23 selling Class Vehicles with the defective Fuel Pumps on an ongoing basis.

24 218. Mazda's and FCA's knowledge of the Fuel Pump Defect is evidenced  
25 by numerous NHTSA complaints by consumers, many of whom reported  
26 contacting Mazda and FCA directly about the defective Fuel Pump. Other NHTSA  
27 complainants reported taking their vehicles to Mazda's and FCA's dealers, who  
28

1 are agents of Mazda and FCA and, on information and belief, report consumer  
2 complaints back to Mazda and FCA.

3 219. Thus, Defendants had continuing knowledge of the Fuel Pump Defect  
4 and the dangers it posed, yet continued to market and sell their products. Plaintiffs'  
5 and other Class Members' claims are not time barred.

6 **B. Fraudulent Concealment Tolling**

7 220. Mazda and FCA had a duty to disclose to Plaintiffs and the Class  
8 Members the true quality and nature of the Class Vehicles, that the Class Vehicles  
9 had a uniform defect; and that the Fuel Pump Defect requires repairs, poses a safety  
10 risk, and reduces the intrinsic and resale value of the affected vehicles.

11 221. This duty arose, *inter alia*, under the TREAD Act, 49 U.S.C. § 30118.

12 222. Denso also had a duty to disclose to Plaintiffs and the Class Members  
13 the true quality and nature of the Fuel Pumps, that the Fuel Pumps in the Class  
14 Vehicles are defective, and that the Fuel Pump Defect poses a safety risk.

15 223. Mazda and FCA knew, or was reckless or negligent in not knowing,  
16 that the Class Vehicles contain the Fuel Pump Defect, as alleged herein. Mazda  
17 and FCA concealed and omitted the Fuel Pump Defect while making  
18 representations about the safety, dependability, and other attributes of the Class  
19 Vehicles, as alleged herein.

20 224. Defendants knew, or were reckless or negligent in not knowing, that  
21 the Class Vehicles contain the Fuel Pump Defect, as alleged herein.

22 225. Defendants together concealed and omitted to disclose the Fuel Pump  
23 Defect while making representations about the safety, dependability, and other  
24 attributes of the Class Vehicles, as alleged herein.

25 226. Despite their knowledge of the Fuel Pump Defect, Defendants failed  
26 to disclose and concealed this material information from Plaintiffs and other Class  
27 Members, and instead continued to market the Class Vehicles as safe and durable.

28



1           227. The purpose of Defendants’ concealment of the Defective Fuel Pump  
2 was to prevent Plaintiffs and other Class Members from seeking redress.

3           228. Plaintiffs and the other Class Members justifiably relied on  
4 Defendants to disclose the existence of dangerous defects, including the Fuel  
5 Pump Defect, in the Class Vehicles that they purchased or leased, because that  
6 defect was not discoverable by Plaintiffs and the other Class Members through  
7 reasonable efforts.

8           229. Any applicable statute of limitations has been tolled by Defendants’  
9 knowledge, active concealment, and denial of the facts alleged herein, which  
10 behavior was ongoing.

11           **C. Discovery Rule Tolling**

12           230. Through the exercise of reasonable diligence, Plaintiffs and other  
13 Class Members could not have discovered prior to Denso’s Recall on April 27,  
14 2020 and Mazda’s/FCA’s November 12, 2021 Recalls that Defendants were  
15 concealing and misrepresenting the existence of the Fuel Pump Defect, which is  
16 installed in the Class Vehicles, and the risks it posed.

17           231. Plaintiffs and the other Class Members could not have reasonably  
18 discovered, and could not have known of facts that would have caused a reasonable  
19 person to suspect, that Defendants failed to disclose material information within  
20 their knowledge about a dangerous defect to consumers worldwide.

21           **VII. CLASS ACTION ALLEGATIONS**

22           232. Plaintiffs bring this action pursuant to Rules 23(a), 23(b)(2), and  
23 23(b)(3) of the Federal Rules of Civil Procedure on behalf of themselves and all  
24 others similarly situated.

25           233. Plaintiffs seek to represent a class (“Nationwide Class”) defined as:

26           All current and former owners or lessees of a Class Vehicle (as  
27 defined herein) that was purchased or leased in the fifty States, the  
28 District of Columbia, Puerto Rico, and all other United States  
territories and/or possessions.

1           234. In addition, and in the alternative to the above, Plaintiffs seek to  
2 represent individual Statewide classes.

3           235. Plaintiff Vance seeks to represent an Alabama statewide class (the  
4 “Alabama Class”) defined as follows:

5           All current and former owners and lessees of a Class Vehicle (as  
6 defined herein) that was purchased or leased in the State of Alabama.

7           236. Plaintiff Haines seeks to represent a California statewide class (the  
8 “California Class”) defined as follows:

9           All current and former owners and lessees of a Class Vehicle (as  
10 defined herein) that was purchased or leased in the State of California.

11           237. Excluded from the Statewide Classes and Nationwide Classes  
12 (together, “Classes”) are Defendants and any of their members, affiliates, parents,  
13 subsidiaries, officers, directors, employees, successors, or assigns; the judicial  
14 officers, and their immediate family members; and Court staff assigned to this  
15 case. Plaintiffs reserve the right to modify or amend definitions of the Classes,  
16 and to add additional classes and sub-classes, as appropriate, during the course of  
17 this litigation.

18           238. This action has been brought and may properly be maintained on  
19 behalf of the Classes proposed herein under the criteria of Rule 23 of the Federal  
20 Rules of Civil Procedure.

21           239. **Numerosity – Federal Rule of Civil Procedure 23(a)(1).** The  
22 members of the Classes are so numerous and geographically dispersed that  
23 individual joinder of all Class Members is impracticable. While Plaintiffs are  
24 informed and believe that there are not less than at least approximately 200,000  
25 members of the Classes, the precise number of Class Vehicles is unknown to  
26 Plaintiffs but may be ascertained from Mazda’s and FCA’s books and records.  
27 Nationwide, Multi-State and Statewide Class Members may be notified of the  
28 pendency of this action by recognized, Court-approved notice dissemination

1 methods, which may include U.S. mail, electronic mail, Internet postings, and/or  
2 published notice.

3 **240. Commonality and Predominance – Federal Rules of Civil**  
4 **Procedure 23(a)(2) and 23(b)(3).** This action involves common questions of law  
5 and fact, which predominate over any questions affecting individual members of  
6 the Classes, including, without limitation:

- 7 a. whether Defendants engaged in the conduct alleged herein;
- 8 b. whether Defendants’ alleged conduct violates applicable law;
- 9 c. whether Defendants designed, manufactured, advertised,  
10 marketed, distributed, leased, sold, or otherwise placed the  
11 Class Vehicles into the stream of commerce in the United  
12 States;
- 13 d. whether Defendants made false or misleading statements  
14 about the quality, safety and characteristics of the Class  
15 Vehicles and/or the Fuel Pumps;
- 16 e. whether the Class Vehicles contain the Fuel Pump Defect;
- 17 f. whether Defendants had actual or implied knowledge about  
18 the Fuel Pump Defect;
- 19 g. whether Defendants failed to disclose the Fuel Pump Defect to  
20 Plaintiffs and the other members of the Classes;
- 21 h. whether Defendants’ omissions and concealment regarding  
22 the quality, safety and characteristics of the Class Vehicles  
23 and/or the Fuel Pumps were likely to deceive members of the  
24 and Statewide Classes in violation of the state consumer  
25 protection statutes alleged herein;
- 26 i. whether Mazda and FCA breached their express warranties  
27 with respect to the Class Vehicles;
- 28

- 1           j.     whether Mazda and FCA breached their implied warranties
- 2                 with respect to the Class Vehicles;
- 3           k.     whether the members of the Classes overpaid for their Class
- 4                 Vehicles as a result of the defect alleged herein;
- 5           l.     whether the members of the Classes are entitled to damages,
- 6                 restitution, disgorgement, statutory damages, exemplary
- 7                 damages, equitable relief, and/or other relief; and
- 8           m.     the amount and nature of relief to be awarded to Plaintiffs and
- 9                 the other members of the Classes.

10           **241. Typicality – Federal Rule of Civil Procedure 23(a)(3).** Plaintiff’s  
11 claims are typical of the claims of the other members of the Classes because  
12 Plaintiffs and the members of the Classes purchased or leased Class Vehicles that  
13 contain defective Fuel Pumps, as described herein. Neither Plaintiffs nor the other  
14 members of the Classes would have purchased the Class Vehicles, or would not  
15 have paid as much as they did for the Class Vehicles, had they known of the Fuel  
16 Pump Defect. Plaintiffs and the other members of the Classes suffered damages as  
17 a direct proximate result of the same wrongful practices in which Defendants  
18 engaged. Plaintiffs’ claims arise from the same practices and course of conduct  
19 that give rise to the claims of the other members of the Classes.

20           **242. Adequacy of Representation – Federal Rule of Civil Procedure**  
21 **23(a)(4).** Plaintiffs are adequate Class representative because their interests do not  
22 conflict with the interests of the other members of the Classes that they seek to  
23 represent. Plaintiffs have retained counsel competent and experienced in complex  
24 class action litigation, including automotive litigation, and Plaintiffs intend to  
25 prosecute this action vigorously. The interests of the members of the Classes will  
26 be fairly and adequately protected by Plaintiffs and their counsel.

27           **243. Declaratory and Injunctive Relief – Federal Rule of Civil**  
28 **Procedure 23(b)(2).** Defendants have acted or refused to act on grounds generally

1 applicable to Plaintiffs and the other members of the Classes, thereby making  
2 appropriate final injunctive relief and declaratory relief, as described below, with  
3 respect to the Nationwide, Multi-State and Statewide Class Members as a whole.

4 244. **Superiority – Federal Rule of Civil Procedure 23(b)(3).** A class  
5 action is superior to any other available means for the fair and efficient  
6 adjudication of this controversy, and no unusual difficulties are likely to be  
7 encountered in the management of this class action. The damages or other financial  
8 detriment suffered by Plaintiffs and the others members of the Classes are  
9 relatively small compared to the burden and expense that would be required to  
10 individually litigate their claims against Defendants, so it would be impracticable  
11 for the other members of the Classes to individually seek redress for Defendants’  
12 wrongful conduct. Even if these Class Members could afford individual litigation,  
13 the court system could not. Individual litigation creates a potential for inconsistent  
14 or contradictory judgments, and increases the delay and expense to all parties and  
15 the court system. By contrast, the class action device, as intended by Congress,  
16 presents far fewer management difficulties, and provides the benefits of single  
17 adjudication, economy of scale, and comprehensive supervision by a single court.

18 **VIII. CLAIMS FOR RELIEF**

19 **A. Claims Brought on Behalf of Alabama Class**

20 **COUNT I**

21 **STRICT PRODUCT LIABILITY**

22 (Individually and on behalf of the Statewide Class)

23 (As to all Defendants)

24 245. Plaintiff Vance (“Plaintiff” for purposes of this Count) incorporates  
25 by reference each allegation as if fully set forth herein.

26 246. Plaintiff brings this claim individually and on behalf of other  
27 members of the Alabama Class (the “Class,” for purposes of this Count).  
28

1           247. Defendants are strictly liable for designing, engineering, testing,  
2 validating, manufacturing, and placing in the stream of commerce an unreasonably  
3 dangerous Fuel Pump.

4           248. Defendants designed, engineered, tested, validated, manufactured,  
5 and placed in the stream of commerce the unreasonable dangerous Fuel Pump.

6           249. The Class Vehicles and Fuel Pumps are being used in an intended  
7 and/or foreseeable manner. Plaintiff and Class Members have not misused or  
8 materially altered the Class Vehicles or Fuel Pumps. The Class Vehicles and Fuel  
9 Pumps are in the same or substantially similar condition as they were at the time  
10 of purchase/lease.

11           250. The Class Vehicles and Fuel Pumps are unreasonably dangerous and  
12 defective because they were designed, engineered, tested, validated,  
13 manufactured, and placed in the stream of commerce with the Fuel Pump Defect  
14 that can cause Class Vehicles to suddenly and unexpectedly stall or lose engine  
15 power.

16           251. The Fuel Pump Defect causes an unreasonably dangerous condition  
17 when Class Vehicles are used for their intended and foreseeable purpose of  
18 providing safe and reliable transportation and places Plaintiff, Class Members, and  
19 others on the road at an unreasonable and substantial risk for injury or death.

20           252. Defendants were aware of feasible alternative designs which would  
21 minimize or eliminate the Fuel Pump Defect and the risk it poses. Such alternative  
22 designs were known and available when the Class Vehicles and Fuel Pumps were  
23 designed, engineered, tested, validated, manufactured, and placed in the stream of  
24 commerce.

25           253. Defendants failed to design, test, validate, manufacture, and place in  
26 the stream of commerce a Class Vehicle and Fuel Pump that is free from the Fuel  
27 Pump Defect and the unreasonable safety risks it poses.

28

1 254. The Fuel Pump Defect causes damage to property other than the  
2 product, as explained in more detail above.

3 255. As a direct and proximate result of Defendants’ actions as described  
4 herein, Plaintiffs and the other Class Members have been damaged in an amount  
5 to be determined at trial.

6 **COUNT II**

7 **BREACH OF EXPRESS WARRANTY**

8 **ALA. CODE §§ 7-2-313 AND 7-2A-210**

9 (Individually and on behalf of the Statewide Class)

10 (As to Mazda)

11 256. Plaintiff Vance (“Plaintiff” for purposes of this Count) incorporates  
12 by reference each allegation as if fully set forth herein.

13 257. Plaintiff brings this claim individually and on behalf of other  
14 members of the Alabama Class (the “Class,” for purposes of this Count).

15 258. Mazda is a merchant with respect to the Class Vehicles.

16 259. In its written express warranties, Mazda expressly warranted that it  
17 would repair or replace defective parts free of charge if the defects became  
18 apparent during the warranty period.

19 260. Mazda’s written express warranties formed the basis of the bargain  
20 that was reached when Plaintiff and the other Class Members purchased or leased  
21 their Class Vehicles.

22 261. Mazda breached its express warranty to repair defective parts in the  
23 Class Vehicles. Mazda admittedly has not repaired the Class Vehicles’ Fuel Pump  
24 Defect.

25 262. Mazda was provided notice of the Fuel Pump Defect as alleged in  
26 detail herein. Mazda has not remedied its breach.

27 263. Further, Mazda has refused to provide an adequate and timely  
28 warranty repair for the Fuel Pump Defect, thus rendering the satisfaction of any

1 notice requirement futile. Customers that have presented their vehicles for  
2 warranty repair due to Fuel Pump failure have been denied adequate repairs.

3 264. The written express warranties fail in their essential purpose because  
4 the contractual remedy is insufficient to make Plaintiff and the other Class  
5 Members whole and because Mazda has failed and/or has refused to adequately  
6 provide the promised remedies within a reasonable time.

7 265. Accordingly, recovery by Plaintiff and the other Class Members is  
8 not limited to the limited remedy of repair, and Plaintiffs, individually and on  
9 behalf of the other Class Members, seeks all remedies as allowed by law.

10 266. Also, as alleged in more detail herein, at the time that Mazda  
11 warranted and sold the Class Vehicles it knew that the Class Vehicles did not  
12 conform to the warranty and were inherently defective, and Mazda improperly  
13 concealed material facts regarding its Class Vehicles. Plaintiff and the other Class  
14 Members were therefore induced to purchase or lease the Mazda Vehicles under  
15 false pretenses.

16 267. As a direct and proximate result of Mazda’s breach of its express  
17 warranty, Plaintiff and the other Class Members have been damaged in an amount  
18 to be determined at trial.

19 **COUNT III**

20 **BREACH OF IMPLIED WARRANTY OF MERCHANTABILITY**

21 **ALA. CODE §§ 7-2-314 AND 7-2A-314**

22 (Individually and on behalf of the Statewide Class)

23 (As to Mazda)

24 268. Plaintiff Vance (“Plaintiff” for purposes of this Count) incorporates  
25 by reference each allegation as if fully set forth herein.

26 269. Plaintiff brings this claim individually and on behalf of other  
27 members of the Alabama Class (the “Class,” for purposes of this Count).

28



1           270. Mazda is a merchant with respect to motor vehicles under Ala. Code  
2 §§ 7-2-104 and 7-2A-103.

3           271. Pursuant to Ala. Code §§ 7-2-314 and 7-2A-212, a warranty that the  
4 Class Vehicles were in merchantable condition was implied by law, and the Class  
5 Vehicles were bought and sold subject to an implied warranty of merchantability.

6           272. The Class Vehicles do not comply with the implied warranty of  
7 merchantability because, at the time of sale and at all times thereafter, they were  
8 defective and not in merchantable condition, would not pass without objection in  
9 the trade, and were not fit for the ordinary purpose for which vehicles were used.  
10 Specifically, the Class Vehicles suffer from the Fuel Pump Defect which causes  
11 the Class Vehicles’ Fuel Pump to prematurely fail.

12           273. Mazda was provided notice of the Fuel Pump Defect as alleged in  
13 detail herein. Mazda has not remedied its breach.

14           274. Further, Mazda has refused to provide an adequate and timely  
15 warranty repair for the Fuel Pump Defect, thus rendering the satisfaction of any  
16 notice requirement futile. As stated above, customers that have presented their  
17 vehicles for warranty repair due to Fuel Pump failure have been denied adequate  
18 repair.

19           275. Plaintiff and the other Class Members suffered injuries due to the  
20 defective nature of the Class Vehicles and Mazda’s breach of the warranty of  
21 merchantability.

22           276. As a direct and proximate result of Mazda’s breach of the warranty  
23 of merchantability, Plaintiffs and the other Class Members have been damaged in  
24 an amount to be proven at trial.

25 ///

26 ///

27 ///

28 ///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**COUNT IV**  
**NEGLIGENT RECALL/UNDERTAKING**  
(Individually and on behalf of the Statewide Class)  
(As to Mazda)

277. Plaintiff Vance (“Plaintiff” for purposes of this Count) incorporates by reference each allegation as if fully set forth herein.

278. Plaintiff brings this claim individually and on behalf of other members of the Alabama Class (the “Class,” for purposes of this Count).

279. Prior to the events that made the basis of this action, Mazda designed, engineered, tested, validated, manufactured, marketed, and placed the Class Vehicles in the stream of commerce.

280. On November 12, 2021, Mazda initiated a voluntary recall of the Recalled Vehicles. Mazda’s recall was voluntary and not initiated by NHTSA.

281. Mazda owed a duty to use reasonable care to Plaintiffs and Class Members based on its undertaking of the Recall.

282. As described above, among other things, Mazda breached its duty by conducting the Recall negligently and/or wantonly by, among other things, failing to adequately diagnose and remedy the Fuel Pump Defect and notify Plaintiffs and the Class to stop driving their Class Vehicles. Mazda’s failure to do so continues to expose Plaintiff and the Class to the risk of injury and death.

283. For the reasons set for the above, Mazda knew, or should have known through the exercise of ordinary care, the Recall was not being performed in a reasonable manner.

284. The Fuel Pump Defect damages property other than the Fuel Pump.

285. As a direct and proximate result, Plaintiff and the other Class Members have been and continue to be damaged in an amount to be determined at trial.

///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**COUNT V**

**FRAUDULENT OMISSION**

(Individually and on behalf of the Statewide Class)

(As to all Defendants)

286. Plaintiff Vance (“Plaintiff” for purposes of this Count) incorporates by reference each allegation as if fully set forth herein.

287. Plaintiff brings this claim individually and on behalf of other members of the Alabama Class (the “Class,” for purposes of this Count).

288. Defendants were aware of the Fuel Pump Defect within the Class Vehicles when they marketed and sold the Class Vehicles to Plaintiff and the other members of the Class.

289. Having been aware of the Fuel Pump Defect within the Class Vehicles, and having known that Plaintiff and the other members of the Class could not have reasonably been expected to know of the Fuel Pump Defect, Defendants had a duty to disclose the defect to Plaintiff and the other members of the Class in connection with the sale or lease of the Class Vehicles.

290. Defendants did not disclose the Fuel Pump Defect to Plaintiffs and the other members of the Class in connection with the sale of the Class Vehicles.

291. For the reasons set forth above, the Fuel Pump Defect within the Class Vehicles comprises material information with respect to the sale or lease of the Class Vehicles.

292. In purchasing the Class Vehicles, Plaintiff and the other members of the Class reasonably relied on Defendants to disclose known material defects with respect to the Class Vehicles.

293. Had Plaintiff and the other members of the Class known of the Fuel Pump Defect within the Class Vehicles, they would have not have purchased the Class Vehicles or would have paid less for the Class Vehicles.

1 294. Through its omissions regarding the Fuel Pump Defect within the  
2 Class Vehicles, Defendants intended to induce, and did induce, Plaintiff and the  
3 other members of the Class to purchase a Class Vehicle that they otherwise would  
4 not have purchased, or pay more for a Class Vehicle than they otherwise would  
5 have paid.

6 295. As a direct and proximate result of Defendants’ omissions, Plaintiffs  
7 and the other members of the Class either overpaid for the Class Vehicles or would  
8 not have purchased the Class Vehicles at all if the Fuel Pump Defect had been  
9 disclosed to them, and, therefore, have incurred damages in an amount to be  
10 determined at trial.

11 **B. Claims on Behalf of the California Class**

12 **COUNT VI**

13 **VIOLATION OF THE CONSUMERS LEGAL REMEDIES ACT,**

14 **CAL. CIV. CODE §§ 1750, et seq.**

15 (Individually and on behalf of the Statewide Class)

16 (As to all Defendants)

17 296. Plaintiff Haines (“Plaintiff” for purposes of this Count) incorporates  
18 by reference the allegations set forth in the preceding paragraphs as though fully  
19 set forth herein.

20 297. Plaintiff brings this cause of action on behalf of himself and on behalf  
21 the California Class (“Class” for purposes of this Count).

22 298. Defendants are “persons” as defined by California Civil Code  
23 § 1761(c).

24 299. Plaintiff and the California Class Members are “consumers” within  
25 the meaning of California Civil Code § 1761(d) because they purchased Class  
26 Vehicles for personal, family, or household use.

27 300. The sale of the Class Vehicles to Plaintiff and the putative Class  
28 Members is a “transaction” as defined by California Civil Code § 1761(e).

1           301. Defendants’ acts and practices, which were intended to result, and  
2 which did result, in the sale of the Class Vehicles, violate § 1770 of the Consumers  
3 Legal Remedies Act (“CLRA”) for at least the following reasons:

- 4           a. Defendants represented that the Class Vehicles have characteristics,  
5 uses or benefits which they do not have;
- 6           b. Defendants advertised their goods with intent to not sell them as  
7 advertised;
- 8           c. Defendants represented that their products are of a particular  
9 standard, quality, or grade when they are not; and
- 10           d. Defendants represented that their goods have been supplied in  
11 accordance with a previous representation when they have not.

12           302. By failing to disclose and concealing the defective nature of the Class  
13 Vehicles from Plaintiff and the prospective Class Members, Defendants violated  
14 California Civil Code § 1761(a), as they represented that the Class Vehicles had  
15 characteristics and benefits that they do not have, and represented that the Class  
16 Vehicles and their engine components were of a particular standard, quality, or  
17 grade when they were of another. *See* Cal. Civ. Code §§ 1770(a)(5), (7), (9), and  
18 (16).

19           303. Defendants’ unfair and deceptive acts or practices occurred  
20 repeatedly in Defendants’ trade or business, were capable of deceiving a  
21 substantial portion of the purchasing public and imposed a serious safety risk on  
22 the public.

23           304. Defendants knew that the Class Vehicles suffered from an inherent  
24 defect, were defectively designed or manufactured, and were not suitable for their  
25 intended use. The Fuel Pump Defect is in each of the Class Vehicles at purchase  
26 or lease but may have not been discovered by putative Class Members until  
27 months, or years, after the purchase. Indeed, Defendants knew, or should have  
28

1 known, well in advance of the Recall that the Class Vehicles contained the Fuel  
2 Pump Defect which presents a substantial danger of bodily injury or death.

3 305. As a result of their reliance on Defendants' omissions and/or  
4 misrepresentations, owners and/or lessees of the Class Vehicles suffered an  
5 ascertainable loss of money, property, and/or value of their Class Vehicles.  
6 Additionally, as a result of the Fuel Pump Defect, Plaintiff and the California Class  
7 Members were harmed and suffered actual damages in that the Class Vehicles are  
8 substantially certain to fail before their expected useful life has run.

9 306. Defendants were under a duty to Plaintiff and the California Class  
10 Members to disclose the defective nature of the Class Vehicles and/or associated  
11 repair costs because Defendants were in a superior position to know the true state  
12 of facts about the Fuel Pump Defect in the Class Vehicles and Plaintiff and  
13 California Class Members could not reasonably have been expected to learn or  
14 discover that their vehicles had a dangerous safety defect until it manifested.

15 307. In failing to disclose the defective nature of the Class Vehicles prior  
16 to January 2019, Defendants knowingly and intentionally concealed material facts  
17 and breached their duty not to do so.

18 308. A reasonable consumer would have considered the facts Defendants  
19 concealed or did not disclose to Plaintiff and the California Class Members to be  
20 material in deciding whether to purchase or lease the Class Vehicles or pay less  
21 for them. Had Plaintiff and the California Class Members known of the defective  
22 nature of the Class Vehicles, they would not have purchased or leased said vehicles  
23 or would have paid less for them.

24 309. Plaintiff and the California Class Members are reasonable consumers  
25 who do not expect their vehicles to suddenly accelerate, decelerate, or stall without  
26 warning and while underway. This is the reasonable and objective consumer  
27 expectation relating to consumer automobiles.

28

1 310. As a result of Defendants’ knowing and intentional concealment of  
2 the Fuel Pump Defect, Plaintiff and the California Class Members were harmed  
3 and suffered actual damages in that the Class Vehicles experienced and will  
4 continue to experience the Fuel Pump Defect and the resultant effects therefrom.

5 311. As a direct and proximate result of Defendants’ unfair or deceptive  
6 acts or practices, Plaintiff and California Class Members suffered and will  
7 continue to suffer actual damages. Had Defendants disclosed the true nature and/or  
8 danger in their vehicles, Plaintiff and members of the California Class would not  
9 have been misled into purchasing the Class Vehicles or would have paid  
10 significantly less for them.

11 312. Plaintiff, on behalf of herself and all other similarly situated  
12 California consumers, and as appropriate, on behalf of the general public of the  
13 State of California, seek injunctive relief prohibiting Defendants from continuing  
14 these unlawful practices pursuant to California Civil Code § 1782(a)(2), and such  
15 other equitable relief, including restitution of either (1) the full purchase or lease  
16 price paid by customers who purchased a Class Vehicle, or (2) a portion of the  
17 purchase or lease price paid by customers who purchased or leased a Class Vehicle  
18 reflecting the difference in value as compared to a vehicle without the defect.

19 313. Plaintiff only seeks injunctive relief for purposes of this Court,  
20 therefore notice is not required.

21 **COUNT VII**

22 **STRICT PRODUCT LIABILITY**

23 (Individually and on Behalf of the Statewide Class)

24 (As to all Defendants)

25 314. Plaintiff Haines (“Plaintiff” for purposes of this Court) incorporates  
26 by reference each allegation as if fully set forth herein.

27 315. Plaintiff brings this claim individually and on behalf of other  
28 members of the California Class (the “Class,” for purposes of this Court).

1           316. Defendants are strictly liable for designing, engineering, testing,  
2 validating, manufacturing, and placing in the stream of commerce an unreasonably  
3 dangerous Fuel Pump.

4           317. Defendants designed, engineered, tested, validated, manufactured,  
5 and placed in the stream of commerce the unreasonable dangerous Fuel Pump.

6           318. The Class Vehicles and Fuel Pumps are being used in an intended  
7 and/or foreseeable manner. Plaintiff and Class Members have not misused or  
8 materially altered the Class Vehicles or Fuel Pumps. The Class Vehicles and Fuel  
9 Pumps are in the same or substantially similar condition as they were at the time  
10 of purchase/lease.

11           319. The Class Vehicles and Fuel Pumps are unreasonably dangerous and  
12 defective because they were designed, engineered, tested, validated,  
13 manufactured, and placed in the stream of commerce with the Fuel Pump Defect  
14 that can cause Class Vehicles to suddenly and unexpectedly stall or lose engine  
15 power.

16           320. The Fuel Pump Defect causes an unreasonably dangerous condition  
17 when Class Vehicles are used for their intended and foreseeable purpose of  
18 providing safe and reliable transportation and places Plaintiff, Class Members, and  
19 others on the road at an unreasonable and substantial risk for injury or death.

20           321. Defendants were aware of feasible alternative designs which would  
21 minimize or eliminate the Fuel Pump Defect and the risk it poses. Such alternative  
22 designs were known and available when the Class Vehicles and Fuel Pumps were  
23 designed, engineered, tested, validated, manufactured, and placed in the stream of  
24 commerce.

25           322. Defendants failed to design, test, validate, manufacture, and place in  
26 the stream of commerce a Class Vehicle and Fuel Pump that is free from the Fuel  
27 Pump Defect and the unreasonable safety risks it poses.

28



1 323. The Fuel Pump Defect causes damage to property other than the  
2 product, as explained in more detail above.

3 324. As a direct and proximate result of Defendants’ actions as described  
4 herein, Plaintiff and the other Class Members have been damaged in an amount to  
5 be determined at trial.

6 **COUNT VIII**  
7 **VIOLATION OF THE SONG-BEVERLY CONSUMER**  
8 **WARRANTY ACT**  
9 **CAL. CIV. CODE §§ 1790, et seq.**

10 (Individually and on Behalf of the Statewide Class)  
11 (As to Mazda)

12 325. Plaintiff Haines (“Plaintiff” for purposes of this Count) incorporate  
13 by reference the allegations set forth in the preceding paragraphs as though fully  
14 set forth herein.

15 326. Plaintiff brings this cause of action on behalf of himself and on behalf  
16 of a California Class (“Class” for purposes of this Count).

17 327. Plaintiff is a buyer as Civil Code section 1791, subdivision (b),  
18 defines the term “buyer.”

19 328. The Class Vehicles are consumer goods, as Civil Code section 1791,  
20 subdivision (a), defines the term “consumer good.” The Class Vehicles include  
21 new motor vehicles, as Civil Code section 1793.22, subdivision (e)(2), defines the  
22 term “new motor vehicle.”

23 329. Mazda was, at all times relevant hereto, the manufacturer, distributor,  
24 warrantor, lessor, and/or seller of the Class Vehicles. Mazda knew or had reason  
25 to know of the specific use for which the Class Vehicles were purchased or leased.

26 330. Plaintiff purchased a Class Vehicle and Mazda provided Plaintiff and  
27 California Class Members with a standard express written warranty covering the  
28 Class Vehicles.

1           331. Mazda is unable to conform Class Vehicles to its express warranty as  
2 it has no fix for the Fuel Pump Defect. Mazda is only prepared to temporarily  
3 replace Plaintiffs' Class Vehicles with ones of inferior quality he cannot safely  
4 operate and that cannot be made to conform to Mazda's express warranty.

5           332. Plaintiff and the California Class Members were harmed because they  
6 purchased or leased the Class Vehicles and paid the full purchase or lease price of  
7 those vehicles but were unable to use such Class Vehicles due to the Fuel Pump  
8 Defect. Temporary loaner vehicles to be provided to Plaintiff and California Class  
9 Members are not of the same quality as the Class Vehicles purchased or leased and  
10 Plaintiff and the Class Members suffered substantial economic injury and other  
11 harm as they were deprived of the benefit of the bargain that they struck with  
12 Mazda.

13           333. Mazda's failure to equip the Class Vehicles with an appropriate and  
14 reliable fuel pump, and failure to repair the Fuel Pump Defect such that the Class  
15 Vehicles conform to the express warranty, is a substantial factor in Plaintiff's and  
16 California Class Members' harm.

17           334. Mazda is unable to conform the Class Vehicles to the express  
18 warranties despite being afforded a reasonable opportunity to do so. Mazda will  
19 not replace the Class Vehicles or refund the purchase price and/or lease payments.  
20 Rather, Mazda insists that California Class Members continue to make payments  
21 on inoperable Class Vehicles.

22           335. Since being informed of the defect in the Class Vehicles, neither  
23 Plaintiff nor Class Members have been able to safely drive their Class Vehicles as  
24 the Fuel Pump Defect is likely to cause death or serious injury if it fails while the  
25 Class Vehicles are being operated.

26           336. Under the Song-Beverly Consumer Warranty Act, all express  
27 warranties are accompanied by the implied warranty of merchantability, which  
28 may not be disclaimed by the manufacturer or retail seller.

1           337. Mazda provided Plaintiff and the California Class Members with an  
2 implied warranty that the Class Vehicles and their components and parts are  
3 merchantable and fit for the ordinary purposes for which they are sold. However,  
4 the Class Vehicles are not fit for their ordinary purpose of providing reasonably  
5 reliable and safe transportation because, among other things, the Class Vehicles  
6 suffered from an inherent defect at the time of sale and thereafter are not fit for  
7 their particular purpose of providing safe and reliable transportation.

8           338. Mazda impliedly warranted that the Class Vehicles were of  
9 merchantable quality and fit for such use. This implied warranty included, among  
10 other things: (1) a warranty that the Class Vehicles that were manufactured,  
11 supplied, distributed, and/or sold by Defendants were safe and reliable for  
12 providing transportation; and (2) a warranty that the Class Vehicles would be fit  
13 for their intended use while they were being operated.

14           339. Contrary to the applicable implied warranties, the Class Vehicles at  
15 the time of sale and thereafter were not fit for their ordinary and intended purpose  
16 of providing Plaintiff and the California Class Members with reliable, durable, and  
17 safe transportation. Instead, the Class Vehicles are defective.

18           340. Mazda's breach of express and implied warranties was willful and  
19 has deprived Plaintiff and the California Class Members of the benefit of their  
20 bargain.

21           341. Mazda has had multiple reasonable opportunities to cure the breach,  
22 but either cannot or will not do so due to conditions reasonably within its control.  
23 Pursuant to the Song-Beverly Consumer Warranty Act, if the manufacturer is  
24 unable to conform a new motor vehicle to the express warranty, then the  
25 manufacturer shall promptly replace the vehicle with one that conforms to the  
26 express warranty or reimburse the buyer. Mazda has done neither despite being  
27 informed that the Class Vehicles are defective and do not conform to applicable  
28 warranties.

1 342. Mazda’s breach of express and implied warranties was willful and  
2 has deprived Plaintiff and the California Class Members of the benefit of their  
3 bargain.

4 343. Mazda had notice of its breach as alleged herein.

5 344. As a direct and proximate cause of Mazda’s breach of express and  
6 implied warranties, Plaintiff and the California Class Members sustained damages  
7 and other losses in an amount to be determined at trial. Defendants’ conduct  
8 damaged Plaintiff and the California Class Members, who are entitled to recover  
9 under section 1794 of the act, including civil penalties, actual damages,  
10 consequential damages, specific performance, diminution in value, costs,  
11 attorneys’ fees, and/or other such relief the Court deems appropriate.

12 **COUNT IX**

13 **VIOLATION OF THE FALSE ADVERTISING LAW**

14 **CALIFORNIA BUS. & PROF. CODE §§ 17500, et seq.**

15 (Individually and on behalf of the Statewide Class)

16 (As to Mazda)

17 345. Plaintiff Haines (“Plaintiff” for purposes of this Count) incorporates  
18 by reference the allegations set forth in the preceding paragraphs as though fully  
19 set forth herein.

20 346. Plaintiff brings this cause of action on behalf of himself and on behalf  
21 California Class (“Class” for purposes of this Count).

22 347. Mazda has benefitted from intentionally selling and leasing at an  
23 unjust profit defective Class Vehicles at artificially inflated prices due to the  
24 concealment of the Fuel Pump Defect, and Plaintiffs and other California Class  
25 Members overpaid for their Class Vehicles.

26 348. Mazda publicly disseminated advertising and promotional material  
27 that was designed and intended to convey to the public that the Class Vehicles  
28

1 were safe, reliable, and operated as consumers would expect the Class Vehicles to  
2 operate.

3 349. Mazda was aware, or should have been aware, of the Fuel Pump  
4 Defect at the time Plaintiff and California Class Members purchased or leased the  
5 Class Vehicles.

6 350. However, Mazda negligently or intentionally made representations in  
7 its advertisements, and, due to issues it was aware of, did not sell the Class  
8 Vehicles that conformed to the representations and promises in the publicly  
9 disseminated advertisements.

10 351. Mazda unjustly received and retained benefits from Plaintiff and the  
11 other California Class Members.

12 352. It is inequitable and unconscionable for Mazda to retain these  
13 benefits.

14 353. Because Mazda wrongfully concealed their misconduct, Plaintiff and  
15 California Class Members were not aware of the facts concerning the Class  
16 Vehicles and did not benefit from Defendants' misconduct.

17 354. Mazda knowingly accepted the unjust benefits of its wrongful  
18 conduct.

19 355. Mazda had notice of conduct as alleged herein.

20 356. As a result of Mazda's misconduct, Plaintiff and California Class  
21 Members suffered an injury-in-fact and lost money and/or property in an amount  
22 to be proven at trial.

23 ///  
24 ///  
25 ///  
26 ///  
27 ///  
28 ///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**COUNT X**  
**VIOLATION OF THE UNFAIR COMPETITION LAW**  
**CAL. CIV. CODE §§ 17200, et seq.**

(Individually and on behalf of the Statewide Class)  
(As to all Defendants)

357. Plaintiff Haines (“Plaintiff” for purposes of this Count) incorporates by reference the allegations set forth in the preceding paragraphs as though fully set forth herein.

358. Plaintiff brings this cause of action on behalf of himself and on behalf the California Class (“Class” for purposes of this Count).

359. As a result of their reliance on Defendants’ omissions and/or misrepresentations, owners and lessees of the Class Vehicles suffered an ascertainable loss of money, property, and/or value in connection with the purchase or lease of their Class Vehicles. Additionally, as a result of the Fuel Pump Defect, Plaintiff and members of the California Class were harmed and suffered actual damages in that the Class Vehicles are substantially certain to fail before their expected useful life has run.

360. California Business & Professions Code § 17200 prohibits acts of “unfair competition,” including any “unlawful, unfair or fraudulent business act or practice” and “unfair, deceptive, untrue or misleading advertising.”

361. Plaintiff and members of the California Class are reasonable consumers who do not expect their vehicles to suffer from sudden acceleration, deceleration, and stalling without warning.

362. Defendants knew the Class Vehicles suffered from inherent defects, were defectively designed or manufactured, would fail prematurely, and were not suitable for their intended use.

363. In failing to disclose the Fuel Pump Defect, Defendants’ knowingly or intentionally concealed material facts and breached their duty not to do so.

1           364. Defendants were under a duty to Plaintiff and members of the  
2 California Class to disclose the Fuel Pump Defect because Defendants were in a  
3 superior position to know the true state of facts about the safety defect and Plaintiff  
4 and members of the California Class could not reasonably have been expected to  
5 learn or discover that the Class Vehicles had a dangerous safety defect until it  
6 manifested.

7           365. A reasonable consumer would have considered the facts Defendants  
8 concealed or did not disclose to Plaintiff and members of the California Class to  
9 be important in deciding whether to purchase or lease the Class Vehicles or pay  
10 less for them. Had Plaintiff and members of the California Class known of the Fuel  
11 Pump Defect in the Class Vehicles, they would not have purchased or leased the  
12 vehicles or would have paid less for them.

13           366. Defendants continued to conceal the defective nature of the Class  
14 Vehicles even after consumers began to report problems. Defendants continue to  
15 cover up and conceal the true nature of the Fuel Pump Defect.

16           367. Defendants’ acts, conduct, and practices were fraudulent, in that they  
17 constituted business practices and acts that were likely to deceive reasonable  
18 members of the public. Defendants’ acts, conduct, and practices were fraudulent  
19 because they are immoral, unethical, oppressive, unscrupulous, and/or are  
20 substantially injurious to consumers.

21           368. Defendants’ acts, conduct, and practices were unfair in that they  
22 constituted business practices and acts the utility of which does not outweigh the  
23 harm to consumers. Defendants’ business acts and practices were further unfair in  
24 that they offend established public policy, are immoral, unethical, oppressive,  
25 unscrupulous, and substantially injurious to consumers.

26           369. A business practice is unlawful if it is forbidden by any law.  
27 Defendants’ acts, conduct, and practices were unlawful, in that they constituted:  
28

- 1 a. Violations of the California Consumers Legal Remedies Act;
- 2 b. Violations of the Song-Beverly Consumer Warranty Act;
- 3 c. Violations of the False Advertising Law;
- 4 d. Violations of Magnuson-Moss Consumer Warranty Act; and
- 5 e. Violations of the express and implied warranty provisions of
- 6 California Commercial Code sections 2313 and 2314.

7 370. By its conduct, Defendants have engaged in unfair competition and  
 8 unlawful, unfair, and fraudulent business practices.

9 371. Defendants’ unfair or deceptive acts or practices occurred repeatedly  
 10 in Defendants’ trade or business and were capable of deceiving a substantial  
 11 portion of the purchasing public.

12 372. As a direct and proximate result of Defendants’ unfair and deceptive  
 13 practices, Plaintiff and members of the California Class have suffered and will  
 14 continue to suffer actual damages.

15 373. Defendants had notice of their conduct as alleged herein.

16 374. Defendants have been unjustly enriched and should be required to  
 17 make restitution to Plaintiffs and members of the California Class pursuant to  
 18 §§ 17203 and 17204 of the California Business & Professions Code. Plaintiff and  
 19 members of the Classes also seek injunctive relief as deemed appropriate by the  
 20 Court.

21 **COUNT XI**

22 **NEGLIGENT RECALL/UNDERTAKING**

23 (Individually and on Behalf of the Statewide Class)

24 (As to Mazda)

25 375. Plaintiff Haines (“Plaintiff” for purposes of this Count) incorporates  
 26 by reference the allegations set forth in the preceding paragraphs as though fully  
 27 set forth herein.



1 376. Plaintiff brings this cause of action on behalf of himself and on behalf  
2 a California Class (“Class” for purposes of this Court).

3 377. Prior to the events made the basis of this action, Mazda designed,  
4 engineered, manufactured, marketed, and placed the Class Vehicles in the stream  
5 of commerce.

6 378. As described above, on November 12, 2021, Mazda initiated a  
7 voluntary recall of the Recalled Vehicles. Mazda’s recall was voluntary and not  
8 initiated by NHTSA.

9 379. Mazda owed a duty to use reasonable care to Plaintiff and Class  
10 Members based on its undertaking of the Recall.

11 380. As described above, Mazda breached its duty by conducting the  
12 Recall negligently and/or wantonly by, among other things, failing to notify  
13 Plaintiff and the Class of the Fuel Pump Defect, failing to direct Class Members  
14 to stop driving their Class Vehicles, and failing to offer Class Members a free  
15 loaner vehicle of comparable make, model, or value as their Class Vehicles until  
16 Mazda is able to devise a remedy that is safe and dependable (if ever) and  
17 implement it in each Class Vehicle. Mazda’s failure to do so continues to expose  
18 Plaintiff and the Class to the risk of injury and death.

19 381. For the reasons set for the above, Mazda knew, or should have known  
20 through the exercise of ordinary care, the Recall was not being performed in a  
21 reasonable manner.

22 382. As a direct and proximate result, Plaintiff and the other Class  
23 Members have been and continue to be damaged in an amount to be determined at  
24 trial.

25 ///  
26 ///  
27 ///  
28 ///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**COUNT XII**

**FRAUDULENT OMISSION**

(Individually and on Behalf of the Statewide Class)

(As to all Defendants)

383. Plaintiff Haines (“Plaintiff” for purposes of this Count) incorporates by reference each allegation as if set forth fully herein.

384. Plaintiff brings this claim individually and on behalf of the California Class (“Class” for purposes of this Count).

385. Defendants were aware of the Fuel Pump Defect within the Class Vehicles when the Class Vehicles were marketed and sold to Plaintiff and the other members of the Class.

386. Having been aware of the Fuel Pump Defect within the Class Vehicles, and having known that Plaintiff and the other members of the Class could not have reasonably been expected to know of the Fuel Pump Defect, Defendants had a duty to disclose the defect to Plaintiff and the other members of the Class in connection with the sale or lease of the Class Vehicles.

387. Defendants did not disclose the Fuel Pump Defect to Plaintiff and the other members of the Class in connection with the sale of the Class Vehicles.

388. For the reasons set forth above, the Fuel Pump Defect within the Class Vehicles comprises material information with respect to the sale or lease of the Class Vehicles.

389. In purchasing the Class Vehicles, Plaintiff and the other members of the Class reasonably relied on Defendants to disclose known material defects with respect to the Class Vehicles.

390. Had Plaintiff and the other members of the Class known of the Fuel Pump Defect within the Class Vehicles, they would have not purchased or leased the Class Vehicles or would have paid less for the Class Vehicles.

1 391. Through their omissions regarding the Fuel Pump Defect within the  
2 Class Vehicles, Defendants intended to induce, and did induce, Plaintiff and the  
3 other members of the Class to either purchase or lease a Class Vehicle that they  
4 otherwise would not have purchased or leased, or pay more for a Class Vehicle  
5 than they otherwise would have paid.

6 392. As a direct and proximate result of Defendants’ omissions, Plaintiff  
7 and the other members of the Class either overpaid for the Class Vehicles or would  
8 not have purchased or leased the Class Vehicles at all if the Fuel Pump Defect had  
9 been disclosed to them, and, therefore, have incurred damages in an amount to be  
10 determined at trial.

11 **C. Claims Brought on Behalf of the Nationwide Class**

12 **COUNT XIII**

13 **BREACH OF EXPRESS WARRANTY ALA. CODE §§ 7-2-313 AND 7-2A-**  
14 **210, AND MATERIALLY IDENTICAL STATE STATUTES**

15 (Individually and on behalf of the Nationwide Class)

16 (As to Mazda)

17 393. Plaintiffs Vance and Haines (“Plaintiffs” for purposes of this Count)  
18 incorporate by reference each allegation as if fully set forth herein.

19 394. Plaintiffs bring this claim individually and on behalf of the other  
20 members of the Nationwide Class (the “Class” for purposes of this Count).

21 395. Mazda is a merchant with respect to the Class Vehicles.

22 396. In its written express warranties, Mazda expressly warranted that it  
23 would repair or replace defective parts free of charge if the defects became  
24 apparent during the warranty period.

25 397. Mazda’s written express warranties formed the basis of the bargain  
26 that was reached when Plaintiffs and the other Class Members purchased or leased  
27 their Class Vehicles.

28

1           398. Mazda breached its express warranty to repair defective parts in the  
2 Class Vehicles. Mazda has not repaired the Class Vehicles' Fuel Pump Defect.

3           399. Mazda was provided notice of the Fuel Pump Defect as alleged in  
4 detail herein. Mazda has not remedied its breach.

5           400. Further, Mazda has refused to provide an adequate and timely  
6 warranty repair for the Fuel Pump Defect, thus rendering the satisfaction of any  
7 notice requirement futile. Customers that have presented their vehicles for  
8 warranty repair due to Fuel Pump failure have been denied adequate repairs.

9           401. The written express warranties fail in their essential purpose because  
10 the contractual remedy is insufficient to make Plaintiffs and the other Class  
11 Members whole and because Mazda has failed and/or has refused to adequately  
12 provide the promised remedies within a reasonable time.

13           402. Accordingly, recovery by Plaintiffs and the other Class Members is  
14 not limited to the limited remedy of repair, and Plaintiffs, individually and on  
15 behalf of the other Class Members, seeks all remedies as allowed by law.

16           403. Also, as alleged in more detail herein, at the time that Mazda  
17 warranted and sold the Class Vehicles it knew that the Class Vehicles did not  
18 conform to the warranty and were inherently defective, and Mazda improperly  
19 concealed material facts regarding its Class Vehicles. Plaintiffs and the other Class  
20 Members were therefore induced to purchase or lease the Mazda Vehicles under  
21 false pretenses.

22           404. As a direct and proximate result of Mazda's breach of its express  
23 warranty, Plaintiffs and the other Class Members have been damaged in an amount  
24 to be determined at trial.

25 ///  
26 ///  
27 ///  
28 ///

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28

**COUNT XIV**  
**BREACH OF IMPLIED WARRANTY OF MERCHANTABILITY**  
**ALA. CODE §§ 7-2-314 AND 7-2A-314, AND MATERIALLY**  
**IDENTICAL STATE STATUES**

(Individually and on behalf of the Statewide Class)  
(As to Mazda)

405. Plaintiffs Vance and Haines (“Plaintiffs” for purposes of this Count) incorporate by reference each allegation as if fully set forth herein.

406. Plaintiffs bring this Count individually and on behalf of the other members of the Nationwide Class (the “Class,” for purposes of this Count).

407. Mazda is a merchant with respect to motor vehicles under Ala. Code §§ 7-2-104 and 7-2A-103.

408. Pursuant to Ala. Code §§ 7-2-314 and 7-2A-212, a warranty that the Class Vehicles were in merchantable condition was implied by law, and the Class Vehicles were bought and sold subject to an implied warranty of merchantability.

409. The Class Vehicles do not comply with the implied warranty of merchantability because, at the time of sale and at all times thereafter, they were defective and not in merchantable condition, would not pass without objection in the trade, and were not fit for the ordinary purpose for which vehicles were used. Specifically, the Class Vehicles suffer from the Fuel Pump Defect which causes the Class Vehicles’ Fuel Pump to prematurely fail.

410. Mazda was provided notice of the Fuel Pump Defect as alleged in detail herein. Mazda has not remedied its breach.

411. Further, Mazda has refused to provide an adequate and timely warranty repair for the Fuel Pump Defect, thus rendering the satisfaction of any notice requirement futile. As stated above, customers that have presented their vehicles for warranty repair due to Fuel Pump failure have been denied adequate repair.

1 412. Plaintiffs and the other Class Members suffered injuries due to the  
2 defective nature of the Class Vehicles and Mazda’s breach of the warranty of  
3 merchantability.

4 413. As a direct and proximate result of Mazda’s breach of the warranty  
5 of merchantability, Plaintiffs and the other Class Members have been damaged in  
6 an amount to be proven at trial.

7 **COUNT XV**

8 **COMMON LAW FRAUDULENT OMISSION/CONCEALMENT**

9 (Individually and on Behalf of the Nationwide Class)

10 (As to Mazda, FCA, and Denso)

11 414. Plaintiffs Vance and Haines (“Plaintiffs” for purposes of this Count)  
12 incorporate by reference each allegation as if fully set forth herein.

13 415. Plaintiffs bring this claim individually and on behalf of the  
14 Nationwide Class (“Class” for purposes of this Count).

15 416. Defendants were aware of the Fuel Pump Defect within the Class  
16 Vehicles when the Class Vehicles were marketed and sold to Plaintiff and the other  
17 members of the Class.

18 417. Having been aware of the Fuel Pump Defect within the Class  
19 Vehicles, and having known that Plaintiffs and the other members of the Class  
20 could not have reasonably been expected to know of the Fuel Pump Defect,  
21 Defendants had a duty to disclose the defect to Plaintiffs and the other members  
22 of the Class in connection with the sale or lease of the Class Vehicles.

23 418. Defendants did not disclose the Fuel Pump Defect to Plaintiffs and  
24 the other members of the Class in connection with the sale of the Class Vehicles.

25 419. For the reasons set forth above, the Fuel Pump Defect within the Class  
26 Vehicles comprises material information with respect to the sale or lease of the  
27 Class Vehicles.

28

1           420. In purchasing the Class Vehicles, Plaintiffs and the other members of  
2 the Class reasonably relied on Defendants to disclose known material defects with  
3 respect to the Class Vehicles.

4           421. Had Plaintiffs and the other members of the Class known of the Fuel  
5 Pump Defect within the Class Vehicles, they would have not purchased or leased  
6 the Class Vehicles or would have paid less for the Class Vehicles.

7           422. Through their omissions regarding the Fuel Pump Defect within the  
8 Class Vehicles, Defendants intended to induce, and did induce, Plaintiffs and the  
9 other members of the Class to either purchase or lease a Class Vehicle that they  
10 otherwise would not have purchased or leased, or pay more for a Class Vehicle  
11 than they otherwise would have paid.

12           423. As a direct and proximate result of Defendants’ omissions, Plaintiffs  
13 and the other members of the Class either overpaid for the Class Vehicles or would  
14 not have purchased or leased the Class Vehicles at all if the Fuel Pump Defect had  
15 been disclosed to them, and, therefore, have incurred damages in an amount to be  
16 determined at trial.

**COUNT XVI**

**VIOLATION OF THE MAGNUSON-MOSS WARRANTY ACT**

**15 U.S.C. §§ 2301, et seq.**

(Individually and on behalf of the Nationwide Class)

(As to Mazda and FCA)

22           424. Plaintiffs Vance and Haines (“Plaintiffs” for purposes of this Count)  
23 incorporate by reference each allegation as if fully set forth herein.

24           425. Plaintiffs bring this Count individually and on behalf of the other  
25 members of the Nationwide Class (the “Class,” for purposes of this Count).

26           426. This Court has jurisdiction to decide claims brought under 15 U.S.C.  
27 § 2301 by virtue of 28 U.S.C. §§ 1332 (a) and (d).  
28

1 427. Plaintiffs and Class Members are “consumers” within the meaning of  
2 the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(3).

3 428. Mazda and FCA are “suppliers” and “warrantors” within the meaning  
4 of the Magnuson-Moss Warranty Act, 15 U.S.C. §§ 2301(4)-(5).

5 429. The Class Vehicles are “consumer products” within the meaning of  
6 the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(1).

7 430. 15 U.S.C. § 2310(d)(1) provides a cause of action for any consumer  
8 who is damaged by the failure of a warrantor to comply with a written warranty.

9 431. In their express written warranties, Mazda and FCA expressly  
10 warranted that it would repair or replace defects in material or workmanship free  
11 of charge if those defects become apparent during the warranty period.

12 432. Mazda’s and FCA’s warranties are written warranties within the  
13 meaning of the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(6). The Class  
14 Vehicles’ implied warranty of merchantability is covered by 15 U.S.C. § 2301(7).

15 433. With respect to Class Members’ purchases or leases of the Class  
16 Vehicles, the terms of Mazda’s and FCA’s written warranties and implied  
17 warranty became part of the basis of the bargain between Mazda/FCA and Plaintiff  
18 and other Class Members.

19 434. Mazda and FCA breached the implied warranty of merchantability.  
20 Without limitation, the Class Vehicles have Fuel Pumps that prematurely fail, as  
21 described above, which renders the Class Vehicles unmerchantable.

22 435. Mazda and FCA breached its express warranties by not offering a  
23 functioning repair for the defective Fuel Pump in the Class Vehicles as evidenced  
24 by Mazda’s own admission in the Recall Report that it has not identified a remedy.

25 436. Further, Mazda and FCA have refused to provide an adequate and  
26 timely warranty repair for the Fuel Pump Defect, thus rendering the satisfaction of  
27 any notice requirement futile. As stated above, Class Members report Fuel Pump  
28 failure to their dealer, but Mazda has failed to repair the defect.



1 437. At the time of sale or lease of each Class Vehicle, Mazda and FCA  
2 knew, should have known, or was reckless in not knowing of the Class Vehicles'  
3 inability to perform as warranted, but nonetheless failed to rectify the situation  
4 and/or disclose the Fuel Pump Defect.

5 438. The amount in controversy of Plaintiffs' individual claims exceed the  
6 sum of \$25. The amount in controversy in this action exceeds the sum of \$50,000,  
7 exclusive of costs and interest, computed on the basis of all claims to be  
8 determined in this lawsuit.

9 439. Plaintiffs, individually and on behalf of the Class Members, seek all  
10 damages permitted by law, including diminution in value of their vehicles, in an  
11 amount to be proven at trial.

12 **PRAYER FOR RELIEF**

13 WHEREFORE, Plaintiffs respectfully request relief against Defendants as  
14 set forth below:

- 15 A. Certifying the proposed Nationwide and Statewide Classes;
- 16 B. Appointing Plaintiffs as the Class representatives and Interim Class  
17 Counsel as Class counsel;
- 18 C. Ordering Defendants to pay actual and statutory damages (including  
19 punitive damages) and restitution to Plaintiffs and the other Class Members, as  
20 allowable by law;
- 21 D. Enjoining Defendants from continuing the unfair business practices  
22 alleged in this Complaint;
- 23 E. Ordering Defendants to pay both pre- and post-judgment interest on  
24 any amounts awarded;
- 25 F. Ordering Defendants to pay attorneys' fees and costs of suit;
- 26 G. Awarding injunctive relief requiring Mazda and FCA to promptly and  
27 fully inform Class Members of the Fuel Pump Defect and its associated dangers  
28 and instructing such Class Members to cease driving their vehicles, and ordering

1 Mazda to provide free loaner vehicles of comparable make, model, or value to the  
2 Class Vehicle each Class member owns or leases until an adequate remedy for the  
3 Fuel Pump Defect is installed in the Class Vehicles; and

4 H. Granting such additional relief as the Court deems just and proper.

5 **DEMAND FOR JURY TRIAL**

6 Plaintiffs demand a jury trial on all issues so triable.

7 Respectfully submitted,

8 Dated: November 23, 2021

BLOOD HURST & O'REARDON, LLP  
TIMOTHY G. BLOOD (149343)  
PAULA R. BROWN (254142)  
JENNIFER L. MACPHERSON (202021)  
CRAIG W. STRAUB (249032)

9 By: s/ Timothy G. Blood

TIMOTHY G. BLOOD

12 501 West Broadway, Suite 1490  
13 San Diego, CA 92101  
14 Tel: 619/338-1100  
15 619/338-1101 (fax)  
16 tblood@bholaw.com  
pbrown@bholaw.com  
cstraub@bholaw.com  
jmacpherson@bholaw.com

17 BEASLEY, ALLEN, CROW,  
18 METHVIN, PORTIS & MILES, P.C.  
19 W. DANIEL "DEE" MILES, III\*  
20 H. CLAY BARNETT, III\*  
21 J. MITCH WILLIAMS\*  
22 272 Commerce Street  
Montgomery, AL 36104  
23 Tel: 334/269-2343  
334/954-7555 (fax)  
24 Dee.Miles@Beasleyallen.com  
25 Clay.Barnett@BeasleyAllen.com  
26 Mitch.Williams@Beasleyallen.com

27 MONTELEONE & McCRORY LLP  
28 JEFFREY S. HURST (138664)  
725 S. Figueroa Street, #3200  
Los Angeles, CA 90017-5446  
Tel: 213/612-9900  
212/612-9930 (fax)  
hurst@mmlawyers.com

*Counsel for Plaintiffs and Proposed  
Classes*

\* *pro hac vice* to be filed

# **EXHIBIT A**

**Part 573 Safety Recall Report****20E-026****Manufacturer Name :** DENSO International America, Inc.**Submission Date :** APR 27, 2020**NHTSA Recall No. :** 20E-026**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : DENSO International America, Inc.

Address : 24777 DENSO Drive

Southfield MI 48033

Company phone : 999

**Population :**

Number of potentially involved : 2,020,000

Estimated percentage with defect : NR

**Equipment Information :**

Brand / Trade 1 : DENSO

Model : Fuel Pump

Part No. : Various Part Numbers

Size : N/A

Function : Fuel Supply

**Descriptive Information :** The low-pressure fuel pump is located in the fuel tank and supplies fuel pressure to the fuel injection system.

Production Dates : SEP 01, 2017 - OCT 06, 2018

**Description of Defect :**

**Description of the Defect :** An impeller in some low pressure fuel pumps may become deformed under certain conditions which could render the fuel pump inoperable.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** If an impeller deforms to a point that creates sufficient interference with the fuel pump body, the fuel pump becomes inoperative. According to vehicle manufacturer's system evaluation, an inoperative fuel pump may result in the illumination of the check engine light and/or master warning indicators, rough engine running, engine no start and/or vehicle stall while driving at low speed and, in rare instances, a vehicle stall could occur while driving at higher speeds, increasing the risk of a crash.

**Description of the Cause :** Under current knowledge, if an impeller is manufactured with a lower density, and contains a lower surface strength or is exposed to production solvent drying for a longer period of time, higher levels of surface cracking may occur which, when excessive fuel absorption occurs, may result in impeller

**Part 573 Safety Recall Report****20E-026**

Page 2

deformation. Geographic location and vehicle applications influence the potential for deformation resulting in fuel pump inoperability.

Identification of Any Warning that can Occur : According to vehicle manufacturer's system evaluation, an inoperative fuel pump results in the illumination of the check engine light and/or master warning indicators, rough running, or no start, all of which are indicators that service is required.

**Involved Components :**

Component Name : NR

Component Description : NR

Component Part Number : NR

**Supplier Identification :****Component Manufacturer**

Name : DENSO International America, Inc.

Address : 24777 Denso Drive  
Southfield MICHIGAN 48086

Country : United States

**Chronology :**

Please see attached DIR report for detail

**Description of Remedy :**

Description of Remedy Program : The remedy program, if any, will be determined by vehicle manufacturers.

How Remedy Component Differs from Recalled Component : The impeller of fuel pumps utilized for a remedy component have higher density.

Identify How/When Recall Condition was Corrected in Production : NR

**Part 573 Safety Recall Report****20E-026**

Page 3

**Recall Schedule :**

Description of Recall Schedule : The recall schedule will be decided by vehicle manufacturers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : Ford Motor Company

Address : 1 American Rd  
Dearborn MI 48126

Country : US

Company Phone : 8003923673

Name : American Honda Motor Co., Inc.

Address : 1919 Torrance Blvd.  
Torrance CA 90501-2746

Country : US

Company Phone : NR

Name : Ford Motor Company

Address : 1 American Rd  
Dearborn MI 48126

Country : US

Company Phone : 3138054301

Name : Mazda North American Operations

Address : 1025 Connecticut Avenue, NW  
Washington DC 20036

Country : US

Company Phone : NR

Name : Magnuson Products, LLC

Address : 1990 Knoll Drive, Building A  
Ventura CA 93003

Country : US

Company Phone : 8056428833

# Part 573 Safety Recall Report

## 20E-026

Page 4

Name : Subaru of America, Inc.

Address : One Subaru Drive  
Camden NJ 08103

Country : US

Company Phone : 8564888500

Name : Toyota Motor North America, Inc.

Address : 6565 Headquarters Drive  
Plano TX 75024

Country : US

Company Phone : 4692924000

Name : Mitsubishi Motors North America, Inc.

Address : 4015 Aspen Grove Dr  
Franklin TN 37067

Country : US

Company Phone : 8654414166

\* NR - Not Reported

# **EXHIBIT B**



**Part 573 Safety Recall Report****20E-026****Manufacturer Name :** DENSO International America, Inc.**Submission Date :** JUN 11, 2020**NHTSA Recall No. :** 20E-026**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : DENSO International America, Inc.

Address : 24777 DENSO Drive

Southfield MI 48033

Company phone : 999

**Population :**

Number of potentially involved : 2,156,057

Estimated percentage with defect : NR

**Equipment Information :**

Brand / Trade 1 : DENSO

Model : Fuel Pump

Part No. : See "Part Numbers"

Size : N/A

Function : Fuel Supply

**Descriptive Information :** The low-pressure fuel pump is located in the fuel tank and supplies fuel pressure to the fuel injection system.

Production Dates : SEP 01, 2017 - OCT 06, 2018

**Description of Defect :**

**Description of the Defect :** An impeller in some low pressure fuel pumps may become deformed under certain conditions which could render the fuel pump inoperable.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** If an impeller deforms to a point that creates sufficient interference with the fuel pump body, the fuel pump becomes inoperative. According to vehicle manufacturer's system evaluation, an inoperative fuel pump may result in the illumination of the check engine light and/or master warning indicators, rough engine running, engine no start and/or vehicle stall while driving at low speed and, in rare instances, a vehicle stall could occur while driving at higher speeds, increasing the risk of a crash.

**Description of the Cause :** Under current knowledge, if an impeller is manufactured with a lower density, and contains a lower surface strength or is exposed to production solvent drying for a longer period of time, higher levels of surface cracking may occur which, when excessive fuel absorption occurs, may result in impeller

**Part 573 Safety Recall Report****20E-026**

Page 2

deformation. Geographic location and vehicle applications influence the potential for deformation resulting in fuel pump inoperability.

**Identification of Any Warning that can Occur :** According to vehicle manufacturer's system evaluation, an inoperative fuel pump results in the illumination of the check engine light and/or master warning indicators, rough running, or no start, all of which are indicators that service is required.

**Involved Components :**

Component Name : NR

Component Description : NR

Component Part Number : NR

**Supplier Identification :****Component Manufacturer**

Name : DENSO International America, Inc.

Address : 24777 Denso Drive  
Southfield MICHIGAN 48086

Country : United States

**Chronology :**

Please see attached DIR report and DIR\_Amendment\_20E-026 for details

**Description of Remedy :**

**Description of Remedy Program :** The remedy program, if any, will be determined by vehicle manufacturers.

**How Remedy Component Differs from Recalled Component :** The impeller of fuel pumps utilized for a remedy component have higher density.

**Identify How/When Recall Condition was Corrected in Production :** NR

**Part 573 Safety Recall Report****20E-026**

Page 3

**Recall Schedule :**

Description of Recall Schedule : The recall schedule will be decided by vehicle manufacturers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : Ford Motor Company

Address : 1 American Rd  
Dearborn MI 48126

Country : US

Company Phone : 8003923673

Name : Ford Motor Company

Address : 1 American Rd  
Dearborn MI 48126

Country : US

Company Phone : 3138054301

Name : Mazda North American Operations

Address : 1025 Connecticut Avenue, NW  
Washington DC 20036

Country : US

Company Phone : NR

Name : Magnuson Products, LLC

Address : 1990 Knoll Drive, Building A  
Ventura CA 93003

Country : US

Company Phone : 8056428833

Name : Toyota Motor North America, Inc.

Address : 6565 Headquarters Drive  
Plano TX 75024

Country : US

Company Phone : 4692924000

# Part 573 Safety Recall Report

## 20E-026

Name : Mitsubishi Motors North America, Inc.

Address : 4015 Aspen Grove Dr  
Franklin TN 37067

Country : US

Company Phone : 8654414166

Name : American Honda Motor Co., Inc.

Address : 1919 Torrance Blvd.  
Torrance CA 90501-2746

Country : US

Company Phone : NR

Name : Subaru of America, Inc.

Address : One Subaru Drive  
Camden NJ 08103

Country : US

Company Phone : 8564888500

\* NR - Not Reported

# **EXHIBIT C**

**Part 573 Safety Recall Report****20E-085****Manufacturer Name :** DENSO International America, Inc.**Submission Date :** NOV 17, 2020**NHTSA Recall No. :** 20E-085**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : DENSO International America, Inc.

Address : 24777 DENSO Drive

Southfield MI 48033

Company phone : 999

**Population :**

Number of potentially involved : 1,517,721

Estimated percentage with defect : NR

**Equipment Information :**

Brand / Trade 1 : DENSO

Model : Fuel Pump

Part No. : Various Part Numbers

Size : N/A

Function : Fuel Supply

**Descriptive Information :** The low-pressure fuel pump is located in the fuel tank and supplies fuel pressure to the fuel injection system.

Production Dates : JUN 26, 2017 - JUN 28, 2019

**Description of Defect :**

**Description of the Defect :** For Description of Defect, please see DIR filed April 24, 2020 attached to recall 20E-026.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** For Description of Safety Risk please see DIR filed April 24, 2020 attached to recall 20E-026.

**Description of the Cause :** For Description of Cause, please see DIR filed April 24, 2020 attached to recall 20E-026.

**Identification of Any Warning that can Occur :** For Identification of Any Warning that can Occur, please see DIR filed April 24, 2020 attached to recall 20E-026.

**Involved Components :**

# Part 573 Safety Recall Report

## 20E-085

Page 2

Component Name : NR

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : DENSO International America, Inc.

Address : 24777 Denso Drive

Southfield MICHIGAN 48086

Country : United States

### Chronology :

For earlier events, see Separate DENSO DIR filed April 24, 2020 attached to recall 20E-026.

#### June 2020 – October 2020

Additional analysis was conducted regarding the density of impellers manufactured during various periods. Because the impeller material contains three elements (resin, glass fiber, and calcium carbonate), but only one element (resin) is susceptible to swelling, only resin density was examined for this analysis. Resin density was found to more closely correlate with the occurrence of field cases than overall impeller density. The resin density findings indicated additional material lots which could contribute to the occurrence of the condition in combination with other factors.

In addition, the surface strength of impellers manufactured during various periods was examined with additional variables considered. This analysis demonstrated that a lower minimum surface strength than previously estimated could be possible.

The new resin density and surface strength information can be correlated by vehicle manufacturers with warranty data, production timing data, vehicle specific variables, and other information to determine which vehicles, if any, may be susceptible to the condition.

#### November 2020

Toyota filed a safety recall notice (20V-682) to cover additional Toyota vehicles that were not included in its earlier recall notices.

DENSO sells low pressure fuel pumps of similar but not identical design and construction to other vehicle manufacturers. The vehicles of the other vehicle manufacturers possess different fuel delivery systems, engine configurations, and other variables to those Toyota included in its recall. Denso is cooperating with other

**Part 573 Safety Recall Report****20E-085**

Page 3

vehicle manufacturers' analysis.

**Description of Remedy :**

Description of Remedy Program : The remedy program, if any, will be determined by vehicle manufacturers.

How Remedy Component Differs from Recalled Component : The impeller of fuel pumps utilized for a remedy component have higher density.

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : The recall schedule will be decided by vehicle manufacturers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : American Honda Motor Co., Inc.

Address : 1919 Torrance Blvd.

Torrance CA 90501-2746

Country : US

Company Phone : NR

Name : Ford Motor Company

Address : 1 American Rd

Dearborn MI 48126

Country : US

Company Phone : 8003923673



# Part 573 Safety Recall Report

## 20E-085

Name : Subaru of America, Inc.  
Address : One Subaru Drive  
Camden NJ 08103  
Country : US  
Company Phone : 8564888500

Name : Toyota Motor North America, Inc.  
Address : 6565 Headquarters Drive  
Plano TX 75024  
Country : US  
Company Phone : 4692924000

Name : Magnuson Products, LLC  
Address : 1990 Knoll Drive, Building A  
Ventura CA 93003  
Country : US  
Company Phone : 8056428833

Name : Mazda North American Operations  
Address : 1025 Connecticut Avenue NW  
Washington DC 20036  
Country : US  
Company Phone : NR

Name : Mitsubishi Motors North America, Inc.  
Address : 4015 Aspen Grove Dr  
Franklin TN 37067  
Country : US  
Company Phone : 8654414166

\* NR - Not Reported

# **EXHIBIT D**



July 17, 2020

Mr. Jeffrey Giuseppe  
Associate Administrator, Enforcement  
National Highway Traffic Safety Administration (NEF-010)  
1200 New Jersey Ave, SE  
Washington, D.C. 20590

Re.: Submission of Foreign Recall Campaign Report

Dear Mr. Giuseppe,

This is to inform you that Mazda Motor Corporation decided to conduct a recall campaign in a foreign country on July 10th, 2020. Mazda North American Operations (MNAO), on behalf of Mazda Motor Corporation of Hiroshima, Japan (Mazda), submits the following information concerning a foreign recall report as required in 49 CFR, Part 579.12.

If you have further questions, please let me know.

Yours sincerely,

A handwritten signature in blue ink, appearing to be "JV".

Joshua Vella  
Director, Vehicle Quality & Safety  
Mazda North American Operations

Page 2

Foreign Safety Recall / Other Safety Campaign Report

## Subject:

Engine stall, no-start or hard start due to fuel pump failure

## Manufacturer Name:

Mazda Motor Corporation

## Type of Action:

Safety Recall

## Potentially Affected Vehicles /Assembly plant / Production Period:

Make/Model	MY	Assembly Plant	Production Period
Mazda/CX-3	18-20MY	Thailand	October 18, 2017 to August 23, 2019
	19MY	JAPAN	September 4, 2018 to October 3, 2018
Mazda/CX-5	18-19MY	Malaysia	October 18, 2017 to July 16, 2019
	18-19MY	Vietnam	October 21, 2017 to July 14, 2018
	18-20MY	Vietnam	November 26, 2017 to September 30, 2019
	20MY	Vietnam	July 22, 2019 to December 30, 2019
	19MY	JAPAN	August 10, 2018 to September 14, 2018
Mazda/CX-8	18-20MY	China	April 28, 2018 to May 15, 2020
	19-20MY	Vietnam	May 29, 2019 to December 19, 2019
Mazda/CX-9	19MY	JAPAN	August 3, 2018 to September 19, 2018
Mazda/Mazda2	19-20MY	Mexico	October 8, 2018 to August 8, 2019
	18-20MY	Thailand	October 18, 2017 to September 2, 2019
	18-20MY	Vietnam	November 2, 2017 to November 20, 2018
	19MY	JAPAN	August 7, 2018 to September 15, 2018
Mazda/Mazda3	18-20MY	China	September 14, 2018 to September 4, 2019
	18-20MY	Malaysia	October 18, 2017 to January 29, 2019
	18-20MY	Thailand	October 18, 2017 to April 30, 2019
	18-20MY	Vietnam	October 22, 2017 to December 30, 2019
	19MY	JAPAN	August 9, 2018 to February 11, 2019

Page 3

Make/Model	MY	Assembly Plant	Production Period
Mazda/Mazda6	18-19MY	China	September 20, 2018 to August 8, 2019
	18-20MY	Vietnam	October 27, 2017 to October 30, 2019
	19MY	JAPAN	August 10, 2018 to September 12, 2018
Mazda/MX-5	19MY	JAPAN	August 21, 2018 to September 13, 2018

Number of affected vehicles:

251,622 vehicles

Markets:

China, Saudi Arabia, Singapore, Thailand, and Others

Estimated percentage of the affected vehicles that contain the subject condition:

Approximately 3.5%

Description of the Defect:

Certain fuel pump impellers located inside the fuel delivery module (FDM) may experience surface cracks due to low part density during the manufacturing process and/or length of time between pump production and vehicle installation. As a result, the impeller may deform, causing interference with surrounding pump components. In this condition, over time the fuel pump operation can become restricted, causing reduced fuel supply to the engine, leading to engine hard start/no start, or possible stall while driving.

The number of reports of the condition:

Alleged field reports: 1,458

Alleged accidents: None, Alleged injuries: None, Alleged fatalities: None

Program for Remediating the Defect:

Owners will be notified of the defect and Mazda dealers will replace affected FDMs with properly manufactured parts as a preventive action. The remedy will be completed free of charge to customers.

Date Field Service Action will commence: End of July 2020.

Determination to recall was made by Mazda Motor Corporation.

Page 4

**Substantially Similar Vehicles in the U.S. and/or U.S. Territories:**

Model Year/Make/Model:

2018-20MY Mazda CX-3/CX-5/CX-9/Mazda2/Mazda3/Mazda6/MX-5/Toyota Yaris

**Reason the Substantially Similar Vehicles in the U.S. are not affected by the recall campaign:**

Due to differences in U.S. logistic conditions, typical customer usage and other factors, Mazda has determined this defect is not likely to occur in U.S. market vehicles. Current U.S. market field data supports this assessment. Mazda will continue to monitor the U.S. and U.S. Territories for future occurrences.

As an additional note, on May 15, 2020, Mazda held a technical review with NHTSA's Office of Defects Investigations to discuss this defect with regard to U.S. market vehicles and ODI concurred that no field action is needed.

**The foreign recall number assigned by foreign authority:**

Not available because a recall number is not assigned in the affected markets.

# **EXHIBIT E**

**Part 573 Safety Recall Report****21V-875****Manufacturer Name :** Mazda North American Operations**Submission Date :** NOV 12, 2021**NHTSA Recall No. :** 21V-875**Manufacturer Recall No. :** 5321K**Manufacturer Information :**

Manufacturer Name : Mazda North American Operations

Address : 1025 Connecticut Avenue, NW

Suite 910 Washington DC 20036

Company phone : 800-222-5500

**Population :**

Number of potentially involved : 121,038

Estimated percentage with defect : 1 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Mazda Mazda6

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : - Recall population determined by the production record of vehicles which have the subject fuel pump installed.

- Vehicles not equipped with the subject fuel pump are not involved in this recall. The following is the affected number of vehicles by MY/Make/Model:  
 MY2018 Mazda Mazda6 built at Mazda Motor Corporation: 13,515 units.

Production Dates : APR 06, 2018 - OCT 24, 2018

VIN Range 1 : Begin : JM1GL1VM4J1313085 End : JM1GL1VM0J1329168  Not sequential

Vehicle 2 : 2019-2019 Mazda CX-3

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : - Recall population determined by the production record of vehicles which have the subject fuel pump installed.

- Vehicles not equipped with the subject fuel pump are not involved in this recall. The following is the affected number of vehicles by MY/Make/Model:  
 MY2019 Mazda CX-3 built at Mazda Motor Corporation: 8,987 units.

Production Dates : APR 10, 2018 - NOV 06, 2018

VIN Range 1 : Begin : JM1DKDC72K0403654 End : JM1DKDB76K0428073  Not sequential



**Part 573 Safety Recall Report****21V-875**

Page 2

Vehicle 3 : 2018-2019 Mazda MX-5

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : - Recall population determined by the production record of vehicles which have the subject fuel pump installed.

- Vehicles not equipped with the subject fuel pump are not involved in this recall. The following is the affected number of vehicles by MY/Make/Model:  
 MY2018 Mazda MX-5 built at Mazda Motor Corporation: 391 units.  
 MY2019 Mazda MX-5 built at Mazda Motor Corporation: 2,517 units.

Production Dates : APR 05, 2018 - OCT 29, 2018

VIN Range 1 : Begin : JM1NDAM75J0205791 End : JM1NDAM79J0206202  Not sequentialVIN Range 2 : Begin : JM1NDAB76K0300011 End : JM1NDAM75K0303267  Not sequential

Vehicle 4 : 2018-2019 Mazda CX-5

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : - Recall population determined by the production record of vehicles which have the subject fuel pump installed.

- Vehicles not equipped with the subject fuel pump are not involved in this recall. The following is the affected number of vehicles by MY/Make/Model:  
 MY2018 Mazda CX-5 built at Mazda Motor Corporation: 72,554 units.  
 MY2019 Mazda CX-5 built at Mazda Motor Corporation: 9,276 units.

Production Dates : APR 03, 2018 - OCT 27, 2018

VIN Range 1 : Begin : JM3KFBCM6J1387268 End : JM3KFBCM5J0476254  Not sequentialVIN Range 2 : Begin : JM3KFBBM7K0500024 End : JM3KFACM3K0514334  Not sequential

Vehicle 5 : 2018-2019 Mazda CX-9

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : - Recall population determined by the production record of vehicles which have the subject fuel pump installed.

- Vehicles not equipped with the subject fuel pump are not involved in this recall. The following is the affected number of vehicles by MY/Make/Model:  
 MY2018 Mazda CX-9 built at Mazda Motor Corporation: 6,734 units.  
 MY2019 Mazda CX-9 built at Mazda Motor Corporation: 6,625 units.

Production Dates : APR 16, 2018 - OCT 17, 2018

VIN Range 1 : Begin : JM3TCACY2J0229736 End : JM3TCACY1J0237357  Not sequentialVIN Range 2 : Begin : JM3TCBCY8K0300008 End : JM3TCBCY5K0308082  Not sequential

**Part 573 Safety Recall Report****21V-875**

Page 3

Vehicle 6 : 2018-2018 Mazda Mazda3

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : - Recall population determined by the production record of vehicles which have the subject fuel pump installed.

- Vehicles not equipped with the subject fuel pump are not involved in this recall. The following is the affected number of vehicles by MY/Make/Model:  
MY2018 Mazda Mazda3 built at Mazda Motor Corporation: 210 units.

Production Dates : MAY 07, 2018 - OCT 01, 2018

VIN Range 1 : Begin : JM1BN1U79J1191050 End : JM1BN1K78J1198901  Not sequential

Vehicle 7 : 2019-2020 Mazda Mazda2

Vehicle Type : LIGHT VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : - Recall population determined by the production record of vehicles which have the subject fuel pump installed.

- Vehicles not equipped with the subject fuel pump are not involved in this recall. The following is the affected number of vehicles by MY/Make/Model:  
MY2019 Mazda Mazda3 built at Mazda de Mexico Vehicle Operation: 186 units.  
MY2020 Mazda Mazda2 built at Mazda de Mexico Vehicle Operation: 43 units.

Production Dates : NOV 01, 2018 - JAN 13, 2020

VIN Range 1 : Begin : 3MDDJBBV0KM309487 End : 3MDDJBBV1KM316139  Not sequentialVIN Range 2 : Begin : 3MDDJBBV7LM400466 End : 3MDDJBBV7LM401990  Not sequential**Description of Defect :**

Description of the Defect : The impeller in some low pressure fuel pumps may become deformed under certain conditions, which could cause fuel pump failure.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Fuel pump failure may result in engine no start and/or vehicle stall while driving at low speed and, in rare instances, a vehicle stall could occur while driving at higher speeds, increasing the risk of a crash.

Description of the Cause : Subject impellers were manufactured with inadequate material which may lead to surface cracking under certain conditions, resulting in impeller deformation. The impeller may deform to the point where it interferes with the fuel pump body, causing fuel pump failure.

Identification of Any Warning that can Occur : Drivers may notice this defect by a check engine light, and/or rough engine operation.

**Part 573 Safety Recall Report****21V-875**

Page 4

**Involved Components :**

Component Name 1 : Pump, Fuel

Component Description : Pump, Fuel

Component Part Number : PE03-13350, PYFL-13350, P54P-13350

**Supplier Identification :****Component Manufacturer**

Name : Denso Corporation

Address : 1-1, Showa-cho, Kariya, Aichi

Foreign States 448-8661

Country : Japan

**Chronology :**

Please refer to "Chronology.pdf" as an attachment.

**Description of Remedy :**

Description of Remedy Program : Owners will be notified by mail and instructed to take their vehicles to Mazda dealers.

Dealers will replace affected fuel pumps with improved parts. The remedy will be completed free of charge to owners. This defect is applicable to the reimbursement plan Mazda submitted on March 10, 2020. Through this general reimbursement plan, Mazda will reimburse vehicle owners for repair cost incurred due to the subject defect prior to submission of this safety recall.

How Remedy Component Differs from Recalled Component : Remedy fuel pumps were manufactured with improved density fuel pump impeller resin material.

Identify How/When Recall Condition was Corrected in Production : Improved density of fuel pump impeller resin material was implemented since July 1, 2019.

**Recall Schedule :**

Description of Recall Schedule : Notification to dealers is expected to occur on or before November 15,

# Part 573 Safety Recall Report

# 21V-875

2021. Mailing of owner notification letters is expected to be completed on or before January 11, 2022.

Planned Dealer Notification Date : NOV 15, 2021 - NOV 15, 2021

Planned Owner Notification Date : JAN 11, 2022 - JAN 11, 2022

\* NR - Not Reported

# **EXHIBIT F**

## Chronology of Defect

### **Fuel pump may fail on MY2019 and MY2020 Mazda2, MY2018 Mazda3, MY2018 Mazda6, MY2019 CX-3, MY2018 and MY2019 CX-5, MY2018 and 2019 CX-9, MY2018 and MY2019 MX-5**

March 26, 2019: Mazda received the first field information from outside the U.S, which reported the engine could not start due to an inoperative fuel pump. Mazda planned to collect the fuel pump from the subject vehicle and investigate it.

April 2019 through August 2019: As a result of parts investigation, it was confirmed that the fuel pump did not function because the deformed impeller in the fuel pump interfered with the fuel pump body. As part of the analysis, additional observations of cracking on the impeller surface were made. To understand the relationship between surface cracks and impeller deformation, Mazda began an investigation to attempt to determine which factors potentially contribute to cracking.

September 17, 2019: Mazda decided to conduct a recall for the purpose of confirming the root cause of the defect on CX-5 in China.

September 2019 through February 2020:As part of the investigation, Mazda hypothesized that testing solvent used during the manufacturing process and low density impellers may be factors causing impeller cracking and began duplication testing. During the test, the surface of the impeller cracked as the solvent dried over time. It was confirmed that fuel pumps produced with impellers of lower density exposed to production drying solvent for longer periods of time could experience the impeller cracking at a level that could lead to excessive fuel absorption, and could cause impeller deformation.

May, 2020: Mazda received no field information regarding this defect from the U.S or U.S territories. As a result of examination about the details of field information received from outside the U.S, Mazda found that there was a difference in occurrence rate among each region and hypothesized the high ambient temperature condition of usage environment may contribute to the occurrence of this defect.

July 10, 2020: Mazda decided to conduct a recall campaign on certain vehicles in China, South-eastern Asia, Central America, and the Middle East, where ambient temperature are relatively high. Since this defect did not seem to occur as often in other countries, Mazda determined to monitor future occurrence in other countries including the U.S and U.S territories. Concurrently, Mazda submitted a foreign recall report regarding this issue to NHTSA. In the report, Mazda explained that due to differences in U.S. logistic conditions, typical customer usage and other factors, this defect was not likely to occur in U.S. market vehicles. The U.S. market field data at that time supported this assessment. Mazda would continue to monitor the U.S. and U.S. Territories for future occurrences.

August 20, 2020: Mazda received the first field information on MY2019 CX-9 from the U.S market, reporting the vehicle experienced a lack of power due to this defect.

September, 2020 through January, 2021: Mazda recognized this failure was beginning to increase in some countries other than the U.S.

July 30, 2021: Mazda decided to conduct a recall campaign on a certain vehicle model in Mexico due to increasing field occurrences in that market.

August 6, 2021: Mazda submitted a foreign recall report regarding this issue to NHTSA. In the report, Mazda explained that due to differences in U.S. logistic conditions, typical customer usage and other factors, this defect was not likely to occur in U.S. market vehicles. The U.S. market field data at that time supported this assessment. Mazda would continue to monitor the U.S. and U.S. Territories for future occurrences.

### Chronology of Defect

**Fuel pump may fail on MY2019 and MY2020 Mazda2, MY2018 Mazda3, MY2018 Mazda6, MY2019 CX-3, MY2018 and MY2019 CX-5, MY2018 and 2019 CX-9, MY2018 and MY2019 MX-5**

August, 2021: Mazda recognized this failure was beginning to increase on a certain vehicle in Europe.

September 1, 2021: Mazda received the fourth field information on MY2018 CX-5 from the U.S market, reporting that fuel pressure was reduced.

Late August, 2021 through September, 2021: This defect frequency continued to increase in Australian markets. Although this defect continues to have a low rate of occurrence in the U.S at present, Mazda began to make arrangements for remedy parts correcting this defect as a precaution in case of global field action. Mazda had received four related field reports from the U.S and U.S territories up to this date.


November 5, 2021: Mazda held a Quality Audit Committee meeting to review all available information to date, and out of an abundance of caution, determined to conduct a proactive field action on certain MY2019 and MY2020 Mazda2, MY2018 Mazda3, MY2018 Mazda6, MY2019 CX-3, MY2018 and MY2019 CX-5, MY2018 and 2019 CX-9, MY2018 and MY2019 MX-5 in the U.S and the U.S territories. No accidents, injuries or deaths have been reported as a result of this defect.

# **EXHIBIT G**



# Part 573 Safety Recall Report

# 21V-879

<b>Manufacturer Name :</b> Chrysler (FCA US, LLC)	
<b>Submission Date :</b> NOV 12, 2021	
<b>NHTSA Recall No. :</b> 21V-879	
<b>Manufacturer Recall No. :</b> Y92	

<b>Manufacturer Information :</b>	<b>Population :</b>
Manufacturer Name : Chrysler (FCA US, LLC) Address : 800 Chrysler Drive CIMS 482-00-91 Auburn Hills MI 48326-2757 Company phone : 1-800-853-1403	Number of potentially involved : 1,622 Estimated percentage with defect : 1 %

**Vehicle Information :**

Vehicle 1 : 2019-2019 Fiat 124 Spider  
 Vehicle Type :  
 Body Style : 2-DOOR  
 Power Train : NR

**Descriptive Information :** Some 2019 MY Fiat 124 Spider vehicles may have been built with a fuel delivery module ("FDM") with impellers that could deform and inhibit the operation.

The suspect period began on April 6, 2018, when the suspect FDMs were introduced into vehicle production, and ended on October 18, 2018, when FDMs with improved molding operations of the impellers were implemented in vehicle production. The suspect period was determined using supplier and vehicle production records.

Similar vehicles not included in the recall population are not equipped with the suspect FDMs or were produced before or after the suspect period.

Production Dates : APR 06, 2018 - OCT 18, 2018  
 VIN Range 1 : Begin : NR End : NR  Not sequential

**Description of Defect :**

Description of the Defect : A FDM with a deformed impeller may interfere with other fuel pump components which can inhibit the operation of the fuel pump potentially causing fuel starvation.

FMVSS 1 : NR  
 FMVSS 2 : NR

Description of the Safety Risk : Fuel starvation may result in an unexpected loss of motive power, which can cause vehicle crash without prior warning.

Description of the Cause : NR

# Part 573 Safety Recall Report

# 21V-879

Page 2

Identification of Any Warning None  
that can Occur :

## Involved Components :

Component Name 1 : Fuel Delivery Module

Component Description : Fuel Pump

Component Part Number : 68313125AA

## Supplier Identification :

### Component Manufacturer

Name : Denso Corporation

Address : 1-1, Showa-cho, Kariya, Aichi  
Foreign States 448-8661

Country : Japan

## Chronology :

- On November 4, 2021, FCA US LLC ("FCA US") became aware of Mazda's intention to voluntarily determine a safety defect exists regarding the FDM on a substantially similar vehicle.
- On November 5, 2021, Mazda held a Quality Audit Committee to review all available information to date and determined to conduct a field action on certain substantially similar vehicles.
- As of November 10, 2021, FCA US is aware of zero customer assistance records, one warranty claim, and zero field reports potentially related to this issue for all markets with a date of receipt for the warranty claim received on August 26, 2019.
- As of November 10, 2021, FCA US is aware of zero accidents and zero injuries potentially related to this issue for all markets.
- On November 9, 2021, FCA Italy, S.p.A. determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected vehicles.

# Part 573 Safety Recall Report

# 21V-879

### Description of Remedy :

Description of Remedy Program : FCA US will conduct a voluntary safety recall of all affected vehicles to replace the FDM.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : The remedy component is a FDM with improved impeller.

Identify How/When Recall Condition was Corrected in Production : NR

### Recall Schedule :

Description of Recall Schedule : \*\*11/12/2021: FCA US will notify dealers and begin notifying owners on or about 01/01/2022.

Planned Dealer Notification Date : JAN 01, 2022 - JAN 01, 2022

Planned Owner Notification Date : JAN 01, 2022 - JAN 01, 2022

\* NR - Not Reported